

1 Products affected

| Product hierarchy no. * | | | | Part no. | SBU | Type / Description | Customer part no. |
|-------------------------|-----|-----|------------|----------------|------------|-------------------------------|-------------------|
| SBU | PG | PUG | Type | | | | |
| 02 | 007 | 012 | 0000001400 | See list below | Connectors | 6610 Appliance Outlet 10A 70° | - |

*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

| List of part numbers affected | | | | |
|-------------------------------|--------------|--------------|---------------|-----------|
| 3-110-812 | 6610.1011 | 6610.1012 | 6610.1013 | 6610.1014 |
| 6610.1014.03 | 6610.1015 | 6610.1015.03 | 6610.1016 | 6610.1017 |
| 6610.1112 | 6610.1152 | 6610.1154 | 6610.1212 | 6610.1253 |
| 6610.1254 | 6610.1254.03 | 6610.1254.04 | 6610.1255.03 | 6610.1312 |
| 6610.1354 | 6610.1354.03 | 6610.1354.04 | 6610.1354.04A | 6610.2011 |
| 6610.2012 | 6610.2013 | 6610.2014 | 6610.2014.03 | 6610.2015 |
| 6610.2015.03 | 6610.2016 | 6610.2016.03 | 6610.2017 | 6610.2112 |
| 6610.2154 | 6610.2212 | 6610.2234 | 6610.2253 | 6610.2254 |
| 6610.2254.03 | 6610.2256.03 | 6610.2312 | 6610.2354 | 6610.3011 |
| 6610.3012 | 6610.3013 | 6610.3014 | 6610.3015 | 6610.3016 |
| 6610.3016.03 | 6610.3017 | 6610.4011 | 6610.4012 | 6610.4013 |
| 6610.4014 | 6610.4015 | 6610.4016 | 6610.4017 | 6610.5014 |
| 6610.5014.03 | 6610.5015 | 6610.5254 | 6610.6012 | 6610.6014 |
| 6610.6254 | 3-111-442 | | | |

2 Type of change

- Change of material
- Change of packaging label

3 Detailed description of change

| Old material | New material |
|---|-----------------------------------|
| Polyamid PA6 (GWIT standard / V0) Polyamid PA66 (GWIT standard / V2) | Polyamid PA6 (GWIT enhanced / V0) |
| Old packaging label | New packaging label |
| <p>(6610-0XXX-XXX-XX1-0XXX)</p> | <p>(6610-0XXX-XXX-XX1-1XXX)</p> |

| Product Change Notification | | | | | PCN 6610 - Change of Material | | |
|-----------------------------|---------------|--------------|-------------|-----------------|-------------------------------|--------|-------------|
| owner | creation date | release date | released by | change order no | rev | page | D10-033-108 |
| vetersa | 19.05.2020 | 19.05.2020 | wullscdo | 2015290 | B | 1 of 2 | |

| | |
|--|--|
| <p>(6610-0XXX-XXX-XX1-2X01)</p> | <p>(6610-0XXX-XXX-XX1-1X01)</p> |
|--|--|

4 Reason of change

- Enhanced glow wire requirements
- Material consolidation
- Appearance consolidation (colour of the front surface according to 4710-5)
- Configuration code changed because of enhanced glow wire requirements.

5 Release date

Orders placed after WW20/20 are manufactured with the new material. The change is traceable on the label by the printed configuration code.

6 Impact of change and recommended action

| | | |
|---------------|-----|----------------------------|
| Form | Yes | Appearance of colour |
| Fit | No | - |
| Function | No | - |
| Manufacturing | No | - |
| Label | Yes | Configuration Code changed |
| Packaging | No | - |

7 Reference Documents / Attachments

| Kind of document | Remarks |
|----------------------------|---------|
| Data Sheet | |

| | | | | | | | |
|-----------------------------|---------------|--------------|-------------|-----------------|-------------------------------|--------|-------------|
| Product Change Notification | | | | | PCN 6610 - Change of Material | | |
| owner | creation date | release date | released by | change order no | rev | page | D10-033-108 |
| vetersa | 19.05.2020 | 19.05.2020 | wullscdo | 2015290 | B | 2 of 2 | |