

Light is OSRAM


Not For New Designs OS-NFND-2021-004

15 March 2021

Expected discontinuation date: 6/1/2021

Reason: The following products have reached their end of life.

OSRAM OS Expectations: Please do not design the products into your new projects. For existing projects, kindly check your demand and plan for last time buy accordingly.



Please direct your feedback to your local Sales office.

| Not for new design products | | Recommended Replacement | | | |
|-----------------------------|---------------------|-------------------------|-------|-------------------------|--------------------|
| Device | Brand | Device | Brand | Datasheet Ordering Code | Expected PDN start |
| GW PULTA.CM | OSCONIQ P 3737 (2W) | | | | 1.Jun.2021 |

| Q-Number | Q-Description | Device Family | Brand |
|-----------------|-----------------------------------|----------------------|--------------|
| Q65112A7127 | GW PULTA1.CM-MCME-XX52-1-1050-R18 | GW PULTA1_Cx | OSCONIQ |
| Q65112A7128 | GW PULTA1.CM-MCME-XX53-1-1050-R18 | GW PULTA1_Cx | OSCONIQ |
| Q65112A9873 | GW PULTA1.CM-MDND-XX52-1-1050-R18 | GW PULTA1_Cx | OSCONIQ |
| Q65112A9874 | GW PULTA1.CM-MDND-XX53-1-1050-R18 | GW PULTA1_Cx | OSCONIQ |