

# PRODUCT CHANGE NOTIFICATION

Product Category STRONGHOLD 20230223-1

Product Group STRONGHOLD

ISSUE DATE: 23-Feb-23

IMPACTED REGIONS:  NA  EMEA  LATAM  AP

REASON FOR CHANGE:  DISCONTINUATION  
 OTHER

**DESCRIPTION OF CHANGE: (Required)**

Discontinuation of some StrongHold parts. Thanks for your ongoing support.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

**DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:**

| SCHEDULE FOR CHANGE                  | Year (YYYY) | Month (MM) | Day (DD) |
|--------------------------------------|-------------|------------|----------|
| New product sample availability date |             |            |          |
| Old product discontinuation date*    | 2023        | 5          | 24       |

**\*Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

| IMPACTED PART NUMBER(s) | Compatibility Type |
|-------------------------|--------------------|
| JP4ZP-X20               | No Replacement     |
| JP4WG-X2                | No Replacement     |
| JP4WG-X6                | No Replacement     |
| P6Z34                   | No Replacement     |