




Product Change Notification (PCN)

PCN Number	509589	Date Issued	January 05, 2021
Reason for Change	Obsolete		
Change Type Description	This is to inform you that the part(s) referenced in this notice will be made obsolete. Please contact your Molex Sales Engineer for additional questions concerning possible replacement part(s).		
Reason for Short Notice	Corrective Actions		
Planned Implementation Date	February 28, 2021		
Recommended Replacement Parts	Please see the attached replacement parts list .xls file.		
Last Time Buy Date for Obsolete Parts	January 31, 2021		
Last Time Ship Date for Obsolete Parts	February 28, 2021		

Before Change



After Change

Overview

- Molex is obsoleting part number 34905-2443 due to an improved sealing and crimping design. The replacement material number is 34905-2447
- Product Impact
 - 34905-2447 has a full chamfer at back of the terminal box while 34905-2443 only has a partial chamfer
 - 34905-2447 has been designed to pass all servicing requirements per USCAR-2 Rev.6
- Please refer to above for LTB and LTS date
 - If these dates are cause for concern, please contact your Molex representative to discuss alternatives
- PPAP and samples available upon request



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:509589**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com

Molex Part Number	Replacement part number:
349052443	349052447