



Expertise Applied | Answers Delivered

8755 W. Higgins Road
Suite 500
Chicago, IL 60631
www.littelfuse.com

June 18, 2020

LF PCN A0183: Notification of MCASE+ Unslotted Black Dash marking

Dear Valued Customer,


As part of our continuous improvement process to support our customers, Littelfuse is taking the following actions for the MCASE+ Unslotted fuses:

Littelfuse will add a black dash between the rating mark in the fuse cover for the MCASE+ Unslotted products. This action is being taken to clarify the difference between the series Slotted (.PXPS) and Unslotted (.PXP). It will support as a visual “Pokayoke” for customers usage. This adjustment will have no impact on the Form, Fit, or Function of the product.


Current

New

MCASE+™ Unslotted



MCASE+™ Unslotted



This will be a running change and we will start producing parts with the adjusted rating marking by September 28, 2020.

Impacted Materials:

<i>Product Series</i>	<i>Style / Description</i>
0695015.PXP	FUSE - MCASE+ 32VDC UNSLOTTED 15A
0695020.PXP	FUSE - MCASE+ 32VDC UNSLOTTED 20A
0695025.PXP	FUSE - MCASE+ 32VDC UNSLOTTED 25A
0695030.PXP	FUSE - MCASE+ 32VDC UNSLOTTED 30A
0695040.PXP	FUSE - MCASE+ 32VDC UNSLOTTED 40A
0695900.PXP	SHUNT - MCASE+ 32VDC UNSLOTTED

Please contact your local Littelfuse representative if you have any additional questions. We will be pleased to answer any questions you may have. Thank you for your continued support.