



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000829

DATE: 21-Apr-2016

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DS1500WE+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1500WEN+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1500YE+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1500YEN+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1501WE+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1501WE+T&R	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1501WEN+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1501WEN+T&R	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1501YE+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1501YEN+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1501YEN+T&R	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1553-100+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1553-85+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1553P-100+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1553P-85+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1642-100+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1642-85+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1643-100+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1643-85+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1643P-100+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS17285E-3+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS17285EN-3+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1742-100+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1742-100IND+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1742-85+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1742W-120+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 22-May-2016

Discontinuance	DS1742W-150+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1743-100+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1743-100IND+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1743-85+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1743-85IND+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1743P-100+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1743P-100IND+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1743P-85+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1743P-C01+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1743W-120+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1743W-120IND+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1743W-150+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1743WP-120+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1743WP-120IND+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS1743WP-150+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS17485E-3+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS17485E-5+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS17885E-3+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured
Discontinuance	DS17885E-5+	N/A	21-Oct-2016	21-Apr-2018	Part can no longer be manufactured