



Product Discontinuation Notice: Various ABV Series Switches

PCN.PGE10.11.29.2017

11.29.2017

| | |
|---------------------------------|---|
| Effective Date: | June 1, 2017 |
| Last Time Buy Date: | September 30, 2017 |
| Last Time Ship Date: | September 30, 2017 |
| Discontinuation Details: | Change of agency certification (UL/CSA/VDE/SEMKO) |
| Suggested Replacement: | Replacement part has UL/C-UL, ENEC/VDE certifications (See below) |
| Affected Part Numbers: | See attachment for detailed list. ABV*****8 → Replaced by ABV*****3 ABV*****9 → Replaced by ABV*****3 |
| Datasheets: | See attached. |
| Notes: | Please see above for possible replacements. |

| Affected Part Numbers | Replacement Part Numbers | Comments |
|-----------------------|--------------------------|---|
| ABV1612619 | ABV1612613 | Replacement part has UL/C-UL, ENEC/VDE certifications |
| ABV1612618 | ABV1612613 | Replacement part has UL/C-UL, ENEC/VDE certifications |
| ABV1216619 | ABV1216613 | Replacement part has UL/C-UL, ENEC/VDE certifications |
| ABV1616619 | ABV1616613 | Replacement part has UL/C-UL, ENEC/VDE certifications |
| ABV1214619 | ABV1214613 | Replacement part has UL/C-UL, ENEC/VDE certifications |
| ABV1212619 | ABV1212613 | Replacement part has UL/C-UL, ENEC/VDE certifications |
| ABV1234509 | ABV1234503 | Replacement part has UL/C-UL, ENEC/VDE certifications |
| ABV1614619 | ABV1614613 | Replacement part has UL/C-UL, ENEC/VDE certifications |
| ABV1210619 | ABV1210613 | Replacement part has UL/C-UL, ENEC/VDE certifications |
| ABV1232419 | ABV1232413 | Replacement part has UL/C-UL, ENEC/VDE certifications |
| ABV1610619 | ABV1610613 | Replacement part has UL/C-UL, ENEC/VDE certifications |
| ABV1230619 | ABV1230613 | Replacement part has UL/C-UL, ENEC/VDE certifications |