

INFORMATION NOTE





N° 014/16

Laser marking change affecting several products of SCT595 package family

Subject of Change: Laser marking change affecting several products of SCT595 package family

Products affected:	Type	SP N°	OPN	Package
	TLE4250-2G	SP000255450	TLE42502GHTSA1	PG-SCT595-5
	TLE4296G V50	SP000950240	TLE4296GV50HTSA1	PG-SCT595-5
	TLE4296G V33	SP000950236	TLE4296GV33HTSA1	PG-SCT595-5
	TLE4296G V30	SP000950200	TLE4296GV30HTSA1	PG-SCT595-5
	TLE4296-2G V50	SP000014333	TLE42962GV50HTSA1	PG-SCT595-5
	TLE4296-2G V33	SP000014332	TLE42962GV33HTSA1	PG-SCT595-5
	TLE4295G V33	SP000950292	TLE4295GV33HTSA1	PG-SCT595-5
	TLE4295G V30	SP000950306	TLE4295GV30HTSA1	PG-SCT595-5
	TLE4295G V26	SP000950324	TLE4295GV26HTSA1	PG-SCT595-5
	TLE4294G V50	SP000361641	TLE4294GV50HTSA1	PG-SCT595-5
	TLE4286G	SP000950138	TLE4286GHTSA1	PG-SCT595-5
	TLE4285G	SP000011850	TLE4285GHTSA1	PG-SCT595-5
	IFX20002MB V50	SP001041644	IFX20002MBV50HTSA1	PG-SCT595-5
	IFX20002MB V33	SP001041636	IFX20002MBV33HTSA1	PG-SCT595-5
	IFX20001MB V50	SP000623428	IFX20001MBV50HTSA1	PG-SCT595-5
	IFX20001MB V33	SP000623344	IFX20001MBV33HTSA1	PG-SCT595-5

Reason of Change: New laser marking tool.

Description of Change:	Old	New (additional)
Laser marking	<p>Old laser marking</p> 	<p>Additional laser marking</p> 

INFORMATION NOTE



N° 014/16

Assessment:

No change in fit, form, function or material. Comparable visual appearance between the old and new (additional) laser marking.

Time Schedule:

July 2016 onwards

Documentation:

n.a.

If you have any questions, please do not hesitate to contact your local Sales office.