



3540 Bassett Street
Santa Clara, CA 95054, USA
Phone: +1-408-982-0700
Fax: +1-408-727-7087

IXDN0014

July 28, 2004.

End of life some non-switchable AC and DC current regulators

Description of change:

End of Life for below part types in the current regulator family.

IXCP30M35A	IXCY30M35A
IXCY02M35	IXCY40M35A
IXCY20M35A	IXCY50M35A
IXCY20M35	IXCP20M45A
IXCY10M35A	IXCY50M45A
IXCP60M35	IXCP10M45A
IXCY60M35	IXCP100M45
IXCP50M35A	IXCP02M45A
IXCP50M35	IXCY100M35S
IXCY02M35A	IXCY100M45
IXCP40M35	IXCP10M35S
IXCY10M35	IXCY30M45
IXCP30M35	IXCP30M45
IXCP20M35A	IXCY20M45A
IXCP20M35	IXCY10M45A
IXCP10M35A	IXCP50M45A
IXCP10M35	IXCY30M45A
IXCP100M35	IXCY40M45
IXCP02M35A	IXCY02M45A
IXCP02M35	IXCP40M45A
IXCY100M35	IXCP40M45
IXCP40M35A	IXCY40M45A
IXCY40M35	IXCP30M45A
IXCY50M35	IXCY01N90E
IXCY30M35	IXCP01N90E

Reasons for change:

Minimal demand for the current regulators.

Identification: Not Applicable

Schedule of change: July 2004.

Influence on quality: None.

Influence on Reliability: None.

Questions to be addressed to: Sudhir Kommineni, Manager of Product Development;
s.kommineni@ixys.net , Phone: +1-408-982-0700; Fax: +1-408-727-7087

Customer response:

Company: _____

IXDN0014

Name and Position: _____

Phone/Fax/e-mail: _____

CHANGES ARE:

___ ACCEPTED

___ NOT ACCEPTED (please comment)

___ TO BE EVALUATED / MORE INFORMATION IS NEEDED (please comment)

COMMENTS: _____

WRITTEN RESPONSE MUST BE RECEIVED WITHIN 30 DAYS OF THE DATE OF THIS PCN.
OTHERWISE IXYS CORPORATION WILL CONSIDER CHANGE IS APPROVED.
PLEASE CONTACT FACTORY REGARDING AVAILABILITY OF OLD TYPE PRODUCTS.