

PRODUCT CHANGE NOTIFICATION

TO: ALL AFFECTED CUSTOMERS

FROM: QUALTEK ELECTRONICS

DATE: October 5, 2015

CLASSIFICATION OF CHANGE: FAD1-04010 AND FAD1-05010 SERIES REMOVAL OF SLEEVE BEARING

THE FOLLOWING PART NUMBERS ARE OBSOLETE:

PART NUMBER	RECOMMENDED PART NUMBER REPLACEMENT
FAD1-04010BSLW11	FAD1-04010BHLW11
FAD1-04010BSMW11	FAD1-04010BHMW11
FAD1-04010BSHW11	FAD1-04010BHHW11
FAD1-04010CSAW11	FAD1-04010CHAW11
FAD1-04010CSLW11	FAD1-04010CHLW11
FAD1-04010CSMW11	FAD1-04010CHMW11
FAD1-04010CSHW11	FAD1-04010CHHW11
FAD1-04010CSJW11	FAD1-04010CHJW11
FAD1-04010DSLW11	FAD1-04010DHLW11
FAD1-04010DSMW11	FAD1-04010DHMW11
FAD1-04010DSHW11	FAD1-04010DHHW11
FAD1-05010BSLW11	FAD1-05010BHLW11
FAD1-05010BSMW11	FAD1-05010BHMW11
FAD1-05010BSHW11	FAD1-05010BHHW11
FAD1-05010CSLW11	FAD1-05010CHLW11
FAD1-05010CSMW11	FAD1-05010CHMW11
FAD1-05010CSHW11	FAD1-05010CHHW11
FAD1-05010DSLW11	FAD1-05010DHLW11
FAD1-05010DSMW11	FAD1-05010DHMW11
FAD1-05010DSHW11	FAD1-05010DHHW11

THE RECOMMENDED REPLACEMENT IS TO SWITCH TO THE HYDRO DYNAMIC BEARING. THIS BEARING STRUCTURE PROVIDES A LONGER LIFE 50K HOURS VS 30K HOURS WHILE ALSO PROVIDING SIMILAR LEVELS OF NOISE AND PERFORMANCE.

LAST TIME BUY: NONE.

CONTACT INFORMATION: PLEASE CONTACT QUALTEK ELECTRONICS CUSTOMER SERVICE FOR AVAILABILITY.

PHONE: 440-951-3300

FAX: 440-951-7252