



## Overview

The purpose of this notification is to communicate that Xilinx is discontinuing certain XC3000, XC4000XL, XC5206, Virtex®, Spartan®-3 products, and Aerospace & Defense “XQ” products.

## Description

As part of Xilinx regular product pruning activities, the following XC3000, XC4000XL, XC5206, Virtex, Spartan-3, and Aerospace & Defense “XQ” products have been identified for obsolescence.

A list of special products under SCDs that are affected by this notice are also listed in this notice (see Appendix A – SCD Parts Affected).

This notice should be used in conjunction with previous discontinuance notices which can be found at: [http://www.xilinx.com/support/documentation/customer\\_notices.htm](http://www.xilinx.com/support/documentation/customer_notices.htm).

## Key Dates and Ordering Information

Final orders are accepted until October 13, 2009.

Final deliveries must occur on or before April 13, 2010.

RMAs will be accepted until October 13, 2010.

## Products Affected

Standard products affected include all SCDs associated with the part numbers listed in this notice.

1. [Spartan-3 Products Affected](#)
2. [Virtex-II Pro X Products Affected](#)
3. [XC3000 Products Affected](#)
4. [XC4000XL Products Affected](#)
5. [XC5206 Products Affected](#)
6. [Aerospace & Defense Products Affected](#)
7. [Aerospace & Defense “XQ” Products Affected](#)
8. [Virtex-E Products Affected](#)
9. [Virtex-4 Products Affected](#)
10. [Appendix A - SCD Parts Affected](#)

Notes: SCD part numbers based on these base part numbers will also be affected (see Appendix A – SCD Parts Affected at the end of this PDN). Please contact your local Xilinx sales representative if you have additional questions regarding the part discontinuances.

Table 1: Spartan-3 Products Affected

Part Number	Replacement Part
XC3S50-4CP132C	XC3S100E-4CP132C
XC3S50-4CP132I	XC3S100E-4CP132I
XC3S50-4CPG132C	XC3S100E-4CPG132C

Part Number	Replacement Part
XC3S50-4CPG132I	XC3S100E-4CPG132I
XC3S50-5CP132C	XC3S100E-5CP132C
XC3S50-5CPG132C	XC3S100E-5CPG132C

\*Notes:

- 1) The recommended replacement part is not a drop in replacement. A board redesign may be necessary.

Table 2: Virtex-II Pro X Products Affected

Part Number	Replacement Part
XC2VPX20-5FF896C	* No direct replacement
XC2VPX20-5FF896I	* No direct replacement
XC2VPX20-5FFG896C	* No direct replacement
XC2VPX20-5FFG896I	* No direct replacement

Part Number	Replacement Part
XC2VPX20-6FF896C	* No direct replacement
XC2VPX20-6FF896I	* No direct replacement
XC2VPX20-6FFG896C	* No direct replacement
XC2VPX20-6FFG896I	* No direct replacement

\*Notes:

- 1) There is no drop in replacement; devices in the Virtex-4 FX, Virtex-5 LXT, and Virtex-5 FXT are suitable replacements, but are not pin-out compatible.
- 2) All SCDs associated with these part numbers will also be affected.

Table 3: XC3000 Products Affected (All Devices in this product line are affected.)

Part Number	Replacement Part
XC3020A-6PC68C	* No direct replacement
XC3020A-6PC84C	* No direct replacement
XC3020A-7PC68C	* No direct replacement
XC3020A-7PC68I	* No direct replacement
XC3020A-7PC84C	* No direct replacement
XC3020A-7PC84I	* No direct replacement
XC3030A-6PC68C	* No direct replacement
XC3030A-6PC84C	* No direct replacement
XC3030A-6PQ100C	* No direct replacement
XC3030A-6VQ100C	* No direct replacement
XC3030A-7PC68C	* No direct replacement
XC3030A-7PC68I	* No direct replacement
XC3030A-7PC84C	* No direct replacement
XC3030A-7PC84I	* No direct replacement
XC3030A-7PQ100C	* No direct replacement
XC3030A-7PQ100I	* No direct replacement
XC3030A-7VQ100C	* No direct replacement
XC3030A-7VQ100I	* No direct replacement
XC3030A-7VQG100C	* No direct replacement
XC3042A-6PC84C	* No direct replacement
XC3042A-6PQ100C	* No direct replacement
XC3042A-6VQ100C	* No direct replacement

Part Number	Replacement Part
XC3042A-7PC84C	* No direct replacement
XC3042A-7PC84I	* No direct replacement
XC3042A-7PQ100C	* No direct replacement
XC3042A-7PQ100I	* No direct replacement
XC3042A-7VQ100C	* No direct replacement
XC3042A-7VQ100I	* No direct replacement
XC3064A-6PC84C	* No direct replacement
XC3064A-6PQ160C	* No direct replacement
XC3064A-6TQ144C	* No direct replacement
XC3064A-7PC84C	* No direct replacement
XC3064A-7PC84I	* No direct replacement
XC3064A-7PQ160C	* No direct replacement
XC3064A-7PQ160I	* No direct replacement
XC3064A-7TQ144C	* No direct replacement
XC3064A-7TQ144I	* No direct replacement
XC3090A-6PC84C	* No direct replacement
XC3090A-6PQ160C	* No direct replacement
XC3090A-7PC84C	* No direct replacement
XC3090A-7PC84I	* No direct replacement
XC3090A-7PQ160C	* No direct replacement
XC3090A-7PQ160I	* No direct replacement

\*Notes:

- 1) The XC3000 family has no direct replacement. For longer term support, it is recommended that designs be converted to one of the Spartan families.
- 2) All SCDs associated with these part numbers will also be affected.

Table 4: XC4000XL Products Affected (All Devices in this product line are affected.)

Part Number	Replacement Part	Part Number	Replacement Part
XC4005XL-09PQ160C	No direct replacement	XC4010XL-2PQ100C	No direct replacement
XC4005XL-09PQ208C	No direct replacement	XC4010XL-2PQ100I	No direct replacement
XC4005XL-09TQ144C	No direct replacement	XC4010XL-2PQ208C	No direct replacement
XC4005XL-09VQ100C	No direct replacement	XC4010XL-2PQ208I	No direct replacement
XC4005XL-1PQ160C	No direct replacement	XC4010XL-2TQ144C	No direct replacement
XC4005XL-1PQ160I	No direct replacement	XC4010XL-2TQ144I	No direct replacement
XC4005XL-1PQ208C	No direct replacement	XC4010XL-3BG256C	No direct replacement
XC4005XL-1PQ208I	No direct replacement	XC4010XL-3BG256I	No direct replacement
XC4005XL-1TQ144C	No direct replacement	XC4010XL-3PQ100C	No direct replacement
XC4005XL-1TQ144I	No direct replacement	XC4010XL-3PQ100I	No direct replacement
XC4005XL-1TQG144C	No direct replacement	XC4010XL-3PQ208C	No direct replacement
XC4005XL-1VQ100C	No direct replacement	XC4010XL-3PQ208I	No direct replacement
XC4005XL-1VQ100I	No direct replacement	XC4010XL-3TQ144C	No direct replacement
XC4005XL-2PQ160C	No direct replacement	XC4010XL-3TQ144I	No direct replacement
XC4005XL-2PQ160I	No direct replacement	XC4013XL-09BG256C	No direct replacement
XC4005XL-2PQ208C	No direct replacement	XC4013XL-09PQ160C	No direct replacement
XC4005XL-2PQ208I	No direct replacement	XC4013XL-09PQ208C	No direct replacement
XC4005XL-2TQ144C	No direct replacement	XC4013XL-09PQ240C	No direct replacement
XC4005XL-2TQ144I	No direct replacement	XC4013XL-1BG256C	No direct replacement
XC4005XL-2VQ100C	No direct replacement	XC4013XL-1BG256I	No direct replacement
XC4005XL-2VQ100I	No direct replacement	XC4013XL-1PQ160C	No direct replacement
XC4005XL-3PQ160C	No direct replacement	XC4013XL-1PQ160I	No direct replacement
XC4005XL-3PQ160I	No direct replacement	XC4013XL-1PQ208C	No direct replacement
XC4005XL-3PQ208C	No direct replacement	XC4013XL-1PQ208I	No direct replacement
XC4005XL-3PQ208I	No direct replacement	XC4013XL-1PQ240C	No direct replacement
XC4005XL-3TQ144C	No direct replacement	XC4013XL-1PQ240I	No direct replacement
XC4005XL-3TQ144I	No direct replacement	XC4013XL-2BG256C	No direct replacement
XC4005XL-3TQG144C	No direct replacement	XC4013XL-2BG256I	No direct replacement
XC4005XL-3VQ100C	No direct replacement	XC4013XL-2PQ160C	No direct replacement
XC4005XL-3VQ100I	No direct replacement	XC4013XL-2PQ160I	No direct replacement
XC4010XL-09BG256C	No direct replacement	XC4013XL-2PQ208C	No direct replacement
XC4010XL-09PQ100C	No direct replacement	XC4013XL-2PQ208I	No direct replacement
XC4010XL-09PQ208C	No direct replacement	XC4013XL-2PQ240C	No direct replacement
XC4010XL-09TQ144C	No direct replacement	XC4013XL-2PQ240I	No direct replacement
XC4010XL-1BG256C	No direct replacement	XC4013XL-3BG256C	No direct replacement
XC4010XL-1BG256I	No direct replacement	XC4013XL-3BG256I	No direct replacement
XC4010XL-1PQ100C	No direct replacement	XC4013XL-3PQ160C	No direct replacement
XC4010XL-1PQ100I	No direct replacement	XC4013XL-3PQ160I	No direct replacement
XC4010XL-1PQ208C	No direct replacement	XC4013XL-3PQ208C	No direct replacement
XC4010XL-1PQ208I	No direct replacement	XC4013XL-3PQ208I	No direct replacement
XC4010XL-1TQ144C	No direct replacement	XC4013XL-3PQ240C	No direct replacement
XC4010XL-1TQ144I	No direct replacement	XC4013XL-3PQ240I	No direct replacement
XC4010XL-2BG256C	No direct replacement	XC4028XL-09BG352C	No direct replacement
XC4010XL-2BG256I	No direct replacement	XC4028XL-09HQ240C	No direct replacement

**Table 4 (Continue): XC4000XL Products Affected (All Devices in this product line are affected.)**

Part Number	Replacement Part	Part Number	Replacement Part
XC4028XL-1BG352C	No direct replacement	XC4062XL-1BG432C	No direct replacement
XC4028XL-1BG352I	No direct replacement	XC4062XL-1BG432I	No direct replacement
XC4028XL-1HQ240C	No direct replacement	XC4062XL-1BG560C	No direct replacement
XC4028XL-1HQ240I	No direct replacement	XC4062XL-1BG560I	No direct replacement
XC4028XL-2BG352C	No direct replacement	XC4062XL-2BG432C	No direct replacement
XC4028XL-2BG352I	No direct replacement	XC4062XL-2BG432I	No direct replacement
XC4028XL-2HQ240C	No direct replacement	XC4062XL-2BG560C	No direct replacement
XC4028XL-2HQ240I	No direct replacement	XC4062XL-2BG560I	No direct replacement
XC4028XL-3BG352C	No direct replacement	XC4062XL-3BG432C	No direct replacement
XC4028XL-3BG352I	No direct replacement	XC4062XL-3BG432I	No direct replacement
XC4028XL-3HQ240C	No direct replacement	XC4062XL-3BG560C	No direct replacement
XC4028XL-3HQ240I	No direct replacement	XC4062XL-3BG560I	No direct replacement
XC4062XL-09BG432C	No direct replacement	XC4062XL-3BGG432C	No direct replacement
XC4062XL-09BG560C	No direct replacement		

Notes:

- 1) For longer term support, it is recommended that designs be converted to one of the Spartan families.
- 2) All SCDs associated with these part numbers will also be affected.

**Table 5: XC5206 Products Affected**

Part Number	Replacement Part	Part Number	Replacement Part
XC5206-3PQ100C	No direct replacement	XC5206-5PQ100I	No direct replacement
XC5206-4PQ100C	No direct replacement	XC5206-6PQ100C	No direct replacement
XC5206-5PQ100C	No direct replacement	XC5206-6PQ100I	No direct replacement

**Table 6: Aerospace & Defense Products Affected**

Standard products affected include all SCDs associated with the part numbers listed below.

Part Number	Replacement Part	Part Number	Replacement Part
XC3042-100CB100B	No direct replacement	XC3042-100PG84M	No direct replacement
XC3042-100CB100M	No direct replacement	XC3090-100CB164M	No direct replacement
XC3042-100PG132M	No direct replacement	XC3090-100PG175M	No direct replacement

**Table 7: Aerospace & Defense "XQ" Products Affected**

Part Number	Replacement Part
XQ4085XL-1CB228M	No direct replacement

### Virtex-E Products Affected

Selected low running Virtex-E part numbers ordered with SCD0773 are affected by this XCN. Please refer to the SCD part list (see [Appendix A – SCD Parts Affected](#) at the end of this PDN).

### Virtex-4 Products Affected

Selected low running and unused Virtex-4 part numbers ordered with SCD4007, SCD4012, SCD0968 and SCD0998 are affected by this notice. Please refer to the SCD part list (see [Appendix A – SCD Parts Affected](#) at the end of this PDN).

## Response

No response is required. For additional information or questions, please contact [Xilinx Technical Support](#). For help with your last time buy requirements or possible replacement options, please contact your local sales representative.

**Important Notice:** Xilinx Customer Notifications (XCNs, XDNs, and Quality Alerts) can be delivered via e-mail alerts sent by the Support website (<http://www.xilinx.com/support>). Register today and personalize your “Documentation and Design Advisory Alerts” area to include Customer Notifications. Xilinx Support provides many benefits, including the ability to receive alerts for new and updated information about specific products, as well as alerts for other publications such as data sheets, errata, application notes, etc. For information on how to sign up, refer to [Xilinx Answer Record 18683](#).

## Appendix A – SCD Parts Affected

Table 8: Virtex-II Pro X SCD Part Numbers Affected

Part Number	Replacement Part
XC2VPX20-5FF896C0950	No direct replacement
XC2VPX20-6FF896C4000	No direct replacement
XC2VPX20-6FF896I4000	No direct replacement
XC2VPX20-6FF896C4004	No direct replacement

Part Number	Replacement Part
XC2VPX20-6FF896C4005	No direct replacement
XC2VPX20-6FFG896C4004	No direct replacement
XC2VPX20-6FFG896C4005	No direct replacement

Table 9: Virtex-E SCD Part Numbers Affected

Part Number	Replacement Part
XC1V1000E-6BG560I0773	XC1V1000E-6BG560I
XC1V1000E-6FG1156C0773	XC1V1000E-6FG1156C
XC1V1000E-6FG900C0773	XC1V1000E-6FG900C
XC1V1000E-8FG1156C0773	XC1V1000E-8FG1156C
XC1V100E-6BG352I0773	XC1V100E-6BG352I
XC1V100E-6PQ240C0773	XC1V100E-6PQ240C
XC1V100E-7PQ240C0773	XC1V100E-7PQ240C
XC1V100E-8PQ240C0773	XC1V100E-8PQ240C
XC1V2000E-6BG560C0773	XC1V2000E-6BG560C
XC1V2000E-6BG560I0773	XC1V2000E-6BG560I
XC1V2000E-8BG560C0773	XC1V2000E-8BG560C
XC1V2000E-8FG1156C0773	XC1V2000E-8FG1156C
XC1V2000E-8FG680C0773	XC1V2000E-8FG680C
XC1V200E-6BG352C0773	XC1V200E-6BG352C
XC1V200E-6FG456C0773	XC1V200E-6FG456C
XC1V200E-6FG456I0773	XC1V200E-6FG456I
XC1V200E-6PQ240C0773	XC1V200E-6PQ240C
XC1V200E-7BG352C0773	XC1V200E-7BG352C
XC1V200E-7PQ240C0773	XC1V200E-7PQ240C
XC1V200E-8FG256C0773	XC1V200E-8FG256C
XC1V200E-8PQ240C0773	XC1V200E-8PQ240C
XC1V300E-6BG432C0773	XC1V300E-6BG432C
XC1V300E-6FG256C0773	XC1V300E-6FG256C

Part Number	Replacement Part
XC1V300E-6FG456C0773	XC1V300E-6FG456C
XC1V300E-6PQ240C0773	XC1V300E-6PQ240C
XC1V300E-7FG456C0773	XC1V300E-7FG456C
XC1V300E-7PQ240C0773	XC1V300E-7PQ240C
XC1V300E-8BG432C0773	XC1V300E-8BG432C
XC1V300E-8FG456C0773	XC1V300E-8FG456C
XC1V400E-6BG560C0773	XC1V400E-6BG560C
XC1V400E-6PQ240C0773	XC1V400E-6PQ240C
XC1V400E-7BG432C0773	XC1V400E-7BG432C
XC1V400E-7PQ240C0773	XC1V400E-7PQ240C
XC1V400E-8FG676C0773	XC1V400E-8FG676C
XC1V50E-6FG256C0773	XC1V50E-6FG256C
XC1V50E-6PQ240C0773	XC1V50E-6PQ240C
XC1V50E-7FG256C0773	XC1V50E-7FG256C
XC1V600E-6FG676I0773	XC1V600E-6FG676I
XC1V600E-6FG680I0773	XC1V600E-6FG680I
XC1V600E-6HQ240C0773	XC1V600E-6HQ240C*
XC1V600E-6HQ240I0773	XC1V600E-6HQ240I*
XC1V600E-7BG432C0773	XC1V600E-7BG432C
XC1V600E-7BG432I0773	XC1V600E-7BG432I
XC1V600E-7FG676C0773	XC1V600E-7FG676C
XC1V600E-8HQ240C0773	XC1V600E-8HQ240C*

**Note:**

Select low running parts with SCD0773 are being obsoleted. The replacement is standard product, which is now exactly the same as parts ordered under SCD0773.

\* HQ240 package is a temporary replacement. This package will be subject to an EOL announcement in 1st half 2009.

**Table 10: Virtex-4 SCD Part Numbers Affected**

Part Number	Replacement Part
XC4VFX60-10FF1152C4007	XC4VFX60-10FF1152C
XC4VFX60-10FFG1152C4012	XC4VFX60-10FFG1152C
XC4VFX60-10FFG672C4007	XC4VFX60-10FFG672C
XC4VFX60-11FF1152C4007	XC4VFX60-11FF1152C
XC4VFX60-11FF1152C4012	XC4VFX60-11FF1152C
XC4VFX60-11FF672C4012	XC4VFX60-11FF672C
XC4VFX60-11FFG1152C4012	XC4VFX60-11FFG1152C
XC4VFX60-11FFG672C4012	XC4VFX60-11FFG672C
XC4VLX100-10FF1148C0968	XC4VLX100-10FF1148C
XC4VLX100-10FF1148I0968	XC4VLX100-10FF1148I
XC4VLX100-10FF1513C0968	XC4VLX100-10FF1513C
XC4VLX100-10FF1513I0968	XC4VLX100-10FF1513I
XC4VLX100-11FF1148C0968	XC4VLX100-11FF1148C
XC4VLX100-11FF1148I0968	XC4VLX100-11FF1148I
XC4VLX100-11FF1513C0968	XC4VLX100-11FF1513C
XC4VLX100-11FF1513I0968	XC4VLX100-11FF1513I
XC4VLX100-12FF1148C0968	XC4VLX100-12FF1148C
XC4VLX100-12FF1513C0968	XC4VLX100-12FF1513C
XC4VLX15-10FF668C0968	XC4VLX15-10FF668C
XC4VLX15-10FF668I0968	XC4VLX15-10FF668I
XC4VLX15-10FF676C0968	XC4VLX15-10FF676C
XC4VLX15-10FF676I0968	XC4VLX15-10FF676I
XC4VLX15-10SF363C0968	XC4VLX15-10SF363C
XC4VLX15-10SF363I0968	XC4VLX15-10SF363I
XC4VLX15-11FF668C0968	XC4VLX15-11FF668C
XC4VLX15-11FF668I0968	XC4VLX15-11FF668I
XC4VLX15-11FF676C0968	XC4VLX15-11FF676C
XC4VLX15-11FF676I0968	XC4VLX15-11FF676I
XC4VLX15-11SF363C0968	XC4VLX15-11SF363C
XC4VLX15-11SF363I0968	XC4VLX15-11SF363I
XC4VLX15-12FF668C0968	XC4VLX15-12FF668C
XC4VLX15-12FF676C0968	XC4VLX15-12FF676C
XC4VLX15-12SF363C0968	XC4VLX15-12SF363C
XC4VLX160-10FF1148C0968	XC4VLX160-10FF1148C
XC4VLX160-10FF1148I0968	XC4VLX160-10FF1148I
XC4VLX160-10FF1513C0968	XC4VLX160-10FF1513C
XC4VLX160-10FF1513I0968	XC4VLX160-10FF1513I
XC4VLX160-11FF1148C0968	XC4VLX160-11FF1148C
XC4VLX160-11FF1148I0968	XC4VLX160-11FF1148I
XC4VLX160-11FF1513C0968	XC4VLX160-11FF1513C
XC4VLX160-11FF1513I0968	XC4VLX160-11FF1513I
XC4VLX160-12FF1148C0968	XC4VLX160-12FF1148C
XC4VLX160-12FF1513C0968	XC4VLX160-12FF1513C
XC4VLX200-10FF1513C0968	XC4VLX200-10FF1513C

Part Number	Replacement Part
XC4VLX200-10FF1513I0968	XC4VLX200-10FF1513I
XC4VLX200-11FF1513C0968	XC4VLX200-11FF1513C
XC4VLX25-10FF668C0968	XC4VLX25-10FF668C
XC4VLX25-10FF668I0968	XC4VLX25-10FF668I
XC4VLX25-10FF676C0968	XC4VLX25-10FF676C
XC4VLX25-10FF676I0968	XC4VLX25-10FF676I
XC4VLX25-10SF363C0968	XC4VLX25-10SF363C
XC4VLX25-10SF363I0968	XC4VLX25-10SF363I
XC4VLX25-11FF668C0968	XC4VLX25-11FF668C
XC4VLX25-11FF668I0968	XC4VLX25-11FF668I
XC4VLX25-11FF676C0968	XC4VLX25-11FF676C
XC4VLX25-11FF676I0968	XC4VLX25-11FF676I
XC4VLX25-11SF363C0968	XC4VLX25-11SF363C
XC4VLX25-11SF363I0968	XC4VLX25-11SF363I
XC4VLX25-12FF668C0968	XC4VLX25-12FF668C
XC4VLX25-12FF676C0968	XC4VLX25-12FF676C
XC4VLX25-12SF363C0968	XC4VLX25-12SF363C
XC4VLX40-10FF1148C0968	XC4VLX40-10FF1148C
XC4VLX40-10FF1148I0968	XC4VLX40-10FF1148I
XC4VLX40-10FF668C0968	XC4VLX40-10FF668C
XC4VLX40-10FF668I0968	XC4VLX40-10FF668I
XC4VLX40-11FF1148C0968	XC4VLX40-11FF1148C
XC4VLX40-11FF1148I0968	XC4VLX40-11FF1148I
XC4VLX40-11FF668C0968	XC4VLX40-11FF668C
XC4VLX40-11FF668I0968	XC4VLX40-11FF668I
XC4VLX40-12FF1148C0968	XC4VLX40-12FF1148C
XC4VLX40-12FF668C0968	XC4VLX40-12FF668C
XC4VLX60-10FF1148C0968	XC4VLX60-10FF1148C
XC4VLX60-10FF1148I0968	XC4VLX60-10FF1148I
XC4VLX60-10FF668C0968	XC4VLX60-10FF668C
XC4VLX60-10FF668I0968	XC4VLX60-10FF668I
XC4VLX60-11FF1148C0968	XC4VLX60-11FF1148C
XC4VLX60-11FF1148I0968	XC4VLX60-11FF1148I
XC4VLX60-11FF668C0968	XC4VLX60-11FF668C
XC4VLX60-11FF668I0968	XC4VLX60-11FF668I
XC4VLX60-12FF1148C0968	XC4VLX60-12FF1148C
XC4VLX60-12FF668C0968	XC4VLX60-12FF668C
XC4VLX80-10FF1148C0968	XC4VLX80-10FF1148C
XC4VLX80-10FF1148I0968	XC4VLX80-10FF1148I
XC4VLX80-11FF1148C0968	XC4VLX80-11FF1148C
XC4VLX80-11FF1148I0968	XC4VLX80-11FF1148I
XC4VXS35-10FF668C0998	XC4VXS35-10FF668C
XC4VXS35-11FF668C0998	XC4VXS35-11FF668C
XC4VXS35-12FF668C0998	XC4VXS35-12FF668C

**Table 11: Spartan-3 SCD Part Numbers Affected**

Part Number	Replacement Part
XC3S50-4CP132C0974	XC3S100E-4CP132C
XC3S50-4CP132I0974	XC3S100E-4CP132I
XC3S50-4CPG132C0974	XC3S100E-4CPG132C

Part Number	Replacement Part
XC3S50-4CPG132I0974	XC3S100E-4CPG132I
XC3S50-5CP132C0974	XC3S100E-5CP132C
XC3S50-5CPG132C0974	XC3S100E-5CPG132C

**\*Notes:**

- 1) The recommended replacement part is not a drop in replacement. A board redesign may be necessary.
- 2) Design must be re-implemented using Xilinx software design tools when targeting the replacement part



Table 12: XC3000 SCD Part Numbers Affected

Part Number	Replacement Part
XC3020A-7PC84C0090	No direct replacement
XC3020A-7PC84C0100	No direct replacement
XC3030A-6PC68C0280	No direct replacement
XC3030A-7PC68C0100	No direct replacement
XC3030A-7PC68C0168	No direct replacement
XC3030A-7PC68I0280	No direct replacement
XC3030A-7PC84C0090	No direct replacement
XC3030A-7PC84C0100	No direct replacement
XC3042A-6PC84C0383	No direct replacement
XC3042A-7PC84C0090	No direct replacement
XC3042A-7PC84C0100	No direct replacement
XC3042A-7PC84C0280	No direct replacement
XC3042A-7PC84I0090	No direct replacement
XC3042A-7PC84I0100	No direct replacement

Part Number	Replacement Part
XC3042A-7PQ100C0167	No direct replacement
XC3042A-7PQ100C0262	No direct replacement
XC3042A-7PQ100C0341	No direct replacement
XC3042A-7PQ100C0546	No direct replacement
XC3064A-6PC84C0090	No direct replacement
XC3064A-6PC84C0100	No direct replacement
XC3064A-7PC84C0090	No direct replacement
XC3064A-7PC84C0100	No direct replacement
XC3064A-7PC84C0280	No direct replacement
XC3064A-7PC84I0090	No direct replacement
XC3064A-7PQ160C0280	No direct replacement
XC3090A-7PC84C0090	No direct replacement
XC3090A-7PC84I0100	No direct replacement

Table 13: XC4000XL SCD Part Numbers Affected

Part Number	Replacement Part
XC4005XL-1VQ100C0280	No direct replacement
XC4005XL-2TQ144C0262	No direct replacement
XC4005XL-3PQ208C0907	No direct replacement
XC4010XL-2BG256C0262	No direct replacement
XC4013XL-09PQ240C0314	No direct replacement
XC4013XL-1PQ208C0624	No direct replacement
XC4013XL-1PQ208C0630	No direct replacement
XC4013XL-1PQ208C0907	No direct replacement
XC4013XL-3PQ160C0630	No direct replacement
XC4013XL-3PQ160I0630	No direct replacement

Part Number	Replacement Part
XC4013XL-3PQ208C0624	No direct replacement
XC4013XL-3PQ208I0624	No direct replacement
XC4013XL-3PQ240C0280	No direct replacement
XC4028XL-1HQ240C0624	No direct replacement
XC4028XL-3BG352C0624	No direct replacement
XC4028XL-3BG352C0630	No direct replacement
XC4028XL-3HQ240C0624	No direct replacement
XC4062XL-09BG432C0630	No direct replacement
XC4062XL-1BG432C0634	No direct replacement

Notes:

- 1) For longer term support, it is recommended that designs be converted to one of the Spartan families.

Table 14: Aerospace &amp; Defense SCD Part Numbers Affected

Part Number	Replacement Part
XQR2V3000-4CG717V0977	No direct replacement
XQR2V3000-4CG717V0978	No direct replacement

Part Number	Replacement Part
XQVR300-4CB228M0520	No direct replacement
XQVR600-4CB228M0520	No direct replacement



## Revision History

The following table shows the revision history for this document.

Date	Version	Revision
10/13/08	1.0	Initial release.
10/20/08	1.1	Removed notes for HQ package from <a href="#">Table 4</a> and <a href="#">Table 13</a> for XC4000XL and XC4000XL SCD parts. Add note to <a href="#">Table 1</a> and <a href="#">Table 11</a> for Spartan-3 and Spartan-3 SCD parts.
06/01/09	1.1.1	Minor changed to add note 2 to <a href="#">Table 11</a> of Appendix A.
04/27/10	1.2	Removed XC4005XL-2PQ100C, XC4010XL-2PQ160C and XC4028XL-2HQ160C from <a href="#">Table 4</a> . These parts have already been PDN'd on <a href="#">PDN2004-21</a> . Removed XC3090A-7PG175M from <a href="#">Table 6</a> . This part has already been PDN'd on <a href="#">PDN2003-01</a> . Removed XQVR1000-4CG560M from <a href="#">Table 7</a> . This part has already been PDN'd on <a href="#">XCN07010</a> .

## Notice of Disclaimer

THE XILINX HARDWARE FPGA AND CPLD DEVICES REFERRED TO HEREIN ("PRODUCTS") ARE SUBJECT TO THE TERMS AND CONDITIONS OF THE XILINX LIMITED WARRANTY WHICH CAN BE VIEWED AT <http://www.xilinx.com/warranty.htm>. THIS LIMITED WARRANTY DOES NOT EXTEND TO ANY USE OF PRODUCTS IN AN APPLICATION OR ENVIRONMENT THAT IS NOT WITHIN THE SPECIFICATIONS STATED ON THE XILINX DATA SHEET. ALL SPECIFICATIONS ARE SUBJECT TO CHANGE WITHOUT NOTICE. PRODUCTS ARE NOT DESIGNED OR INTENDED TO BE FAIL-SAFE, OR FOR USE IN ANY APPLICATION REQUIRING FAIL-SAFE PERFORMANCE, SUCH AS LIFESUPPORT OR SAFETY DEVICES OR SYSTEMS, OR ANY OTHER APPLICATION THAT INVOKES THE POTENTIAL RISKS OF DEATH, PERSONAL INJURY OR PROPERTY OR ENVIRONMENTAL DAMAGE ("CRITICAL APPLICATIONS"). USE OF PRODUCTS IN CRITICAL APPLICATIONS IS AT THE SOLE RISK OF CUSTOMER, SUBJECT TO APPLICABLE LAWS AND REGULATIONS. ALL SPECIFICATIONS ARE SUBJECT TO CHANGE WITHOUT NOTICE.