



Not Recommended for New Design: RE C90 Series Relays

NRFND.PG0002.A.10.9.2020

10.9.2020

About This Notice:	The RE C90 Series Relays with C90 suffix are Not Recommended For New Design due to future plans for discontinuation.
Features:	
Effective Date:	Immediate
Affected Parts and/or Replacements:	See Attached. There are no direct replacements.
Datasheet(s):	See Attached.
Notes:	ARE***** Series Relays (without C90 suffix) were previously announced as NRND.

Part Number

ARE1003C90
ARE1006C90
ARE1009C90
ARE1012C90
ARE1024C90
ARE104HC90
ARE10A03C90
ARE10A03ZC90
ARE10A06C90
ARE10A06ZC90
ARE10A09C90
ARE10A09ZC90
ARE10A12C90
ARE10A12ZC90
ARE10A24C90
ARE10A24ZC90
ARE10A4HC90
ARE10A4HZC90
ARE1303C90
ARE1306C90
ARE1309C90
ARE1312C90
ARE1324C90
ARE134HC90
ARE13A03C90
ARE13A03ZC90
ARE13A06C90
ARE13A06ZC90
ARE13A09C90
ARE13A09ZC90
ARE13A12C90
ARE13A12ZC90
ARE13A24C90
ARE13A24ZC90
ARE13A4HC90
ARE13A4HZC90