



Product Discontinuance Notice - PDN 17_0055 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

PDN Title:

Discontinuance of ADSP-BF504F and ADSP-BF506F Products

Publication Date: 30-Oct-2017

Last Time Buy Date: 15-Mar-2018

Last Time Ship Date: 30-Oct-2019

Revision Description:

Initial Release

Reason For Discontinuance

Micron has obsoleted the flash memory used with these products and no suitable replacement flash memory is available.

Supporting Documents None

For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representative

Americas: PDN_Americas@analog.com

Europe: PDN_Europe@analog.com

Japan: PDN_Japan@analog.com

Rest of Asia: PDN_ROA@analog.com

PDN 17_0055 Discontinued Parts Material List

Model	Product Family	Replacement Part	Pin To Pin Compatible	Comments
AD91194Z	ADSP-BF504F	ADSP-BF504BCPZ-4	No	
ADSP-BF504BCPZ-3F	ADSP-BF504F	ADSP-BF504BCPZ-4	No	External flash memory is required
ADSP-BF504BCPZ-4F	ADSP-BF504F	ADSP-BF504BCPZ-4	No	External flash memory is required
ADSP-BF504KCPZ-3F	ADSP-BF504F	ADSP-BF504BCPZ-4	No	External flash memory is required
ADSP-BF504KCPZ-4F	ADSP-BF504F	ADSP-BF504BCPZ-4	No	External flash memory is required
ADSP-BF506BSWZ-3F	ADSP-BF506F	ADSP-BF504BCPZ-4	No	External flash memory and external ADC are required
ADSP-BF506BSWZ-4F	ADSP-BF506F	ADSP-BF504BCPZ-4	No	External flash memory and external ADC are required

Appendix A - PDN 17_0055 Revision History

Rev	Publish Date	Rev Description
Rev. -	30-Oct-2017	Initial Release

Analog Devices, Inc. Proprietary Information

DocId:1183 Layout Rev:2 Parent DocId:None