



TE Connectivity

Product Change Notification: E-19-003026

PCN Date: 17-APR-19

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
 Changing the current splice method to paper splice for ease of operation and efficiency improvement for customers.

Description of Changes
 Following part numbers are changed the current splice methods to paper splice for ease the operation and efficiency improvement for customers

Splice Method

1) Paper Splice (115-25007-2)- Interleave paper type 2) Paper Splice (115-25007-3)- No Interleave paper type

NEW CONTACT STRIP (DO NOT WELD, WELD OR OTHERWISE SPLICE TOGETHER) MUST BE 3 - 4 INCHES BETWEEN END OF ONE CONTACT STRIP AND BEGINNING OF NEXT

Reason for Changes:
 Product Improvement. Dear Customer, because of our continuous strive for improving our product quality and customer process efficiency, we hereby inform you about the changing the current splice method to paper splice method. The new splice method is changed by following a strict procedure, which guarantees quality, ability to supply and form-fit-function of the concerned products. The new splice method is under a certified quality management system according the standard industry requirements. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	19-AUG-2019
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	21-AUG-2019

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-928771-4	NO						
1-964108-1	NO						
1-964114-1	NO						
1534234-1	NO						
160810-2	NO			"CB3194-000", "AMPS-0-0160810-2"			
160897-2	NO			"CB3193-000", "AMPS-0-0160897-2"			
2238060-1	NO						
2238061-1	NO						
2238062-1	NO						
2238087-1	NO						
2238088-1	NO						
2238089-1	NO						
281622-2	NO						
281623-2	NO						
284633-1	NO						
62430-1	NO						
62898-1	NO						
62938-1	NO						
62958-1	NO						
63661-1	NO						
926851-1	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
926851-2	NO						
964110-1	NO						
964252-1	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-964114-1	NO						
2238060-1	NO						
2238061-1	NO						
2238062-1	NO						
2238087-1	NO						
2238088-1	NO						
2238089-1	NO						
281623-2	NO						
62898-1	NO						
62958-1	NO						
63661-1	NO						
926851-1	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-928771-4	NO						
1-964114-1	NO						
1534234-1	NO						
160810-2	NO			"CB3194-000", "AMPS-0-0160810-2"			
160897-2	NO			"CB3193-000", "AMPS-0-0160897-2"			
2238060-1	NO						
2238061-1	NO						
2238062-1	NO						
2238087-1	NO						
2238088-1	NO						
2238089-1	NO						
281623-2	NO						
62430-1	NO						
62898-1	NO						
62938-1	NO						
62958-1	NO						
63661-1	NO						
926851-1	NO						
926851-2	NO						
964252-1	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-928771-4	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-964108-1	NO						
1534234-1	NO						
160810-2	NO			"CB3194-000", "AMPS-0-0160810-2"			
160897-2	NO			"CB3193-000", "AMPS-0-0160897-2"			
2238087-1	NO						
2238088-1	NO						
2238089-1	NO						
281622-2	NO						
281623-2	NO						
284633-1	NO						
62430-1	NO						
62898-1	NO						
62938-1	NO						
63661-1	NO						
926851-2	NO						
964110-1	NO						
964252-1	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-928771-4	NO						
1534234-1	NO						
160810-2	NO			"CB3194-000", "AMPS-0-0160810-2"			
160897-2	NO			"CB3193-000", "AMPS-0-0160897-2"			
62430-1	NO						
62898-1	NO						
62938-1	NO						
63661-1	NO						
926851-2	NO						
964252-1	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-928771-4	NO						
1-964108-1	NO						
1-964114-1	NO						
1534234-1	NO						
160810-2	NO			"CB3194-000", "AMPS-0-0160810-2"			
160897-2	NO			"CB3193-000", "AMPS-0-0160897-2"			
2238060-1	NO						
2238061-1	NO						
2238062-1	NO						
2238087-1	NO						
2238088-1	NO						
2238089-1	NO						
281622-2	NO						
281623-2	NO						
284633-1	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
62430-1	NO						
62898-1	NO						
62938-1	NO						
63661-1	NO						
926851-2	NO						
964110-1	NO						
964252-1	NO						