



<b>PCN Number:</b>	20181214003	<b>PCN Date:</b>	Jan. 7 2019
<b>Title:</b>	Pin One Dot Size/Location Component Marking improvement for select WCSP Devices		
<b>Customer Contact:</b>	<a href="#">PCN Manager</a>	<b>Dept:</b>	Quality Services
<b>Change Type:</b>			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Assembly Process
<input type="checkbox"/>	Design	<input type="checkbox"/>	Datasheet
<input type="checkbox"/>	Test Site	<input checked="" type="checkbox"/>	Packing/Shipping/Labeling
<input type="checkbox"/>	Wafer Bump Site	<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>	Wafer Fab Site	<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Part number change
<input type="checkbox"/>		<input type="checkbox"/>	Assembly Materials
<input type="checkbox"/>		<input type="checkbox"/>	Mechanical Specification
<input type="checkbox"/>		<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process

### PCN Details

#### Description of Change:

This letter is to inform customers of a Pin 1 dot size/location component marking improvement as shown below, where the Pin 1 dot is reduced in size and more clearly marked in a specific quadrant to align with the package Pin 1 location.

	Current Pin One Dot	New Pin One Dot
<b>Size</b>	200um	<b>80um</b>
<b>Picture</b>		

#### Reason for Change:

Provided improved visual for Pin 1 dot size/location

#### Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

None

#### Changes to product identification resulting from this PCN:

Device Pin 1 dot symbolization

#### Product Affected:

DSYB3502A0YKGR	LP5907UVX-1.6/NOPB	LP5907UVX2.925-S	P59115A033YKGR
DSYB3502B0YENR	LP5907UVX-1.7/NOPB	LP5908UVX-1.8/NOPB	P5911A033CYKGR
LP5907A28YKMR	LP5907UVX-1.8/NOPB	LP59115A33YKGR	P5911A033ZYKGR
LP5907A29YKMR	LP5907UVX-2.2/NOPB	LP5911A033YKGR	P5911A18YKGR

LP5907A33YKMR	LP5907UVX-2.8/NOPB	LP5911A285YKGR	P5911A285YKGR
LP5907UVE-1.8/NOPB	LP5907UVX-2.85/NOPB	LP5916A33YENR	P5911A30YKGR
LP5907UVE-2.8/NOPB	LP5907UVX-3.0/NOPB	LP5917A18YKER	P5916A33YENR
LP5907UVE-2.85/NOPB	LP5907UVX-3.2/NOPB	LP5917A30YKER	P5917A18YKER
LP5907UVE-3.0/NOPB	LP5907UVX-3.3/NOPB	LP5918A33YENR	P5917A30YKER
LP5907UVE-3.2/NOPB	LP5907UVX1.35-S	P5907A28YKMR	P5917A31YKER
LP5907UVE-3.3/NOPB	LP5907UVX1.825-S	P5907A33YKMR	P5918A33YENR
LP5907UVX-1.3/NOPB	LP5907UVX19/NOPB	P5907UVX3.6-S	TPD1E14A4YFWR

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

<b>Location</b>	<b>E-Mail</b>
USA	<a href="mailto:PCNAmericasContact@list.ti.com">PCNAmericasContact@list.ti.com</a>
Europe	<a href="mailto:PCNEuropeContact@list.ti.com">PCNEuropeContact@list.ti.com</a>
Asia Pacific	<a href="mailto:PCNAsiaContact@list.ti.com">PCNAsiaContact@list.ti.com</a>
Japan	<a href="mailto:PCNJapanContact@list.ti.com">PCNJapanContact@list.ti.com</a>