

Product Discontinuance Notice - PDN 10_0093 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

PDN Title:

AD8005, AD8532, AD8566: Discontinuation of Select Lead(Pb) Bearing Models

Publication Date:29-Jun-2010Last Time Buy Date:29-Jun-2011Last Time Ship Date:29-Jun-2012

Reason For Discontinuance

Elimination is due to decreased activity of the AD8005, AD8532, AD8566 lead(Pb) bearing models.

Supporting Documents None

	For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representitive							
Americas:	PDN_Americas@analog.com	Europe:	PDN_Europe@analog.com	Japan: Rest of Asia:	PDN_Japan@analog.com PDN_ROA@analog.com			

PDN 10_0093 Discontinued Parts Material List							
Model	Product Family	Replacement Part	Pin To Pin Compatible	Comments			
AD8005ART-R2	AD8005	AD8005ARTZ-REEL7	Yes	Lead-free equivalent			
AD8532ARM-R2	AD8532	AD8532ARMZ-REEL	Yes	Lead-free equivalent			
AD8566ARM-R2	AD8566	AD8566ARMZ-REEL	Yes	Lead-free equivalent			

Appendix A - PDN 10_0093 Revision History						
Rev	Publish Date	Rev Description				
Rev	29-Jun-2010	Initial Release				

Analog Devices, Inc. Proprietary Information

Docld:187 Layout Rev.1 Parent Docld:None