

## Product Advisory

Issue Date: January 20, 2023

**Change Type:**

OCP3.0 pull tab bracket update

**Parts Affected:**

<b>BRCM Part Number</b>	<b>New Revision Number</b>
BCM957504-N425G	30

**Description and Extent of Change:**

The LED port markings "L" for Link and "A" for Activity are added for each port on the bracket.

**Reasons for Change:**

Consistency with other brackets

**Effect of Change on Fit, Form, Function, Quality, or Reliability:**

The adapter specification will remain the same. No changes to adapter form, fit, function, quality and reliability.

**Effective Date of Change:**

This will be implemented as running change starting after March 30, 2023.

---

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.