



# Product Termination Notification

Oct 7, 2022

**Product Change Notification #: 2022043T**  
**Subject: Lumileds announces product termination for LUXEON CSP HL1**

## Overview

Lumileds is announcing the discontinuation of its LUXEON CSP HL1 products. At this time, Lumileds is ready to proceed with the end of life for this product. The details and supporting documents are attached below.

|   |   |
|---|---|
| <b>Description of Change(s):</b>                            | End of Life for LUXEON CSP HL1                        |
| <b>Customer Impact and Recommended Actions:</b>             | Use LUXEON HL1Z as replacement options                |
| <b>Products affected:</b>                                   | <b>All LUXEON CSP HL1</b>                             |
| <b>Reference Documents/Attachments:</b>                     | Attachment A: Affected Part Numbers                   |
| <b>Customer part number(s), if applicable:</b>              | - See Attachment A for Affected Lumileds part numbers |
| <b>Last order date, if necessary, of obsolesced product</b> | Not Applicable – immediate discontinuance             |
| <b>Last ship date, if necessary, of obsolesced product</b>  | Not Applicable – immediate discontinuance             |

## Next Steps

As a next step, please provide acknowledgement of receipt of this PTN and provide feedback along with any additional requests to your Lumileds Account Manager or Quality Manager no later than **Oct-30, 2022**

## Contact:

If you have any questions, or need any further assistance, please contact your Lumileds sales representative.

**CONFIDENTIAL**  
Document No. 30574135  
Rev. AA

# Attachments

## Attachment A: Affected part numbers

| Part Number  |                    |
|--------------|--------------------|
| 12NC         | CPN                |
| 927790210801 | L1HL-2780100000000 |
| 927702759701 | L1HL-27801000CACN0 |
| 927703060201 | L1HL-27801000CADCO |
| 927790210201 | L1HL-2790100000000 |
| 927702760201 | L1HL-27901000CACN0 |
| 927703060501 | L1HL-27901000CADCO |
| 927790210901 | L1HL-3080100000000 |
| 927702759801 | L1HL-30801000CACN0 |
| 927703060301 | L1HL-30801000CADCO |
| 927790210301 | L1HL-3090100000000 |
| 927702760301 | L1HL-30901000CACN0 |
| 927703060601 | L1HL-30901000CADCO |
| 927790211001 | L1HL-3580100000000 |
| 927702759901 | L1HL-35801000CACN0 |
| 927790210401 | L1HL-3590100000000 |
| 927702760401 | L1HL-35901000CACN0 |
| 927790210101 | L1HL-4080100000000 |
| 927702760001 | L1HL-40801000CACN0 |
| 927703060401 | L1HL-40801000CADCO |
| 927790210501 | L1HL-4090100000000 |
| 927702760501 | L1HL-40901000CACN0 |

|              |                    |
|--------------|--------------------|
| 927703060701 | L1HL-40901000CADCO |
| 927790211201 | L1HL-5080100000000 |
| 927702760101 | L1HL-50801000CACNO |
| 927790210601 | L1HL-5090100000000 |
| 927702760601 | L1HL-50901000CACNO |
| 927790211301 | L1HL-6580100000000 |
| 927790210701 | L1HL-6590100000000 |
| 927702994301 | L1HL-2790100000000 |
| 927703152401 | L1HL-2790100000000 |
| 927702993201 | L1HL-3080100000000 |
| 927702994601 | L1HL-3090100000000 |
| 927703152501 | L1HL-3090100000000 |
| 927702993501 | L1HL-3580100000000 |
| 927702994901 | L1HL-3590100000000 |
| 927703152601 | L1HL-3590100000000 |
| 927702993801 | L1HL-4080100000000 |
| 927702995201 | L1HL-4090100000000 |
| 927703152701 | L1HL-4090100000000 |
| 927702994101 | L1HL-5080100000000 |
| 927702995501 | L1HL-5090100000000 |
| 927703152801 | L1HL-5090100000000 |
| 927702995601 | L1HL-6590100000000 |
| 927703152901 | L1HL-6590100000000 |
| 927702168201 | L1HL-27801000AWK80 |
| 927702168201 | L1HL-27801000AWK80 |
| 927702169001 | L1HL-27801000AWM90 |
| 927702169001 | L1HL-27801000AWM90 |

|              |                    |
|--------------|--------------------|
| 927702540601 | L1HL-27801000AYW70 |
| 927702544101 | L1HL-27801000AYX30 |
| 927702544701 | L1HL-27801000AYY80 |
| 927702168601 | L1HL-27901000AWK80 |
| 927702168601 | L1HL-27901000AWK80 |
| 927702994501 | L1HL-27901000AWK80 |
| 927702994501 | L1HL-27901000AWK80 |
| 927703153101 | L1HL-27901000AWK80 |
| 927702169401 | L1HL-27901000AWM90 |
| 927702169401 | L1HL-27901000AWM90 |
| 927702994401 | L1HL-27901000AWM90 |
| 927702994401 | L1HL-27901000AWM90 |
| 927703153001 | L1HL-27901000AWM90 |
| 927702540801 | L1HL-27901000AYW70 |
| 927702544301 | L1HL-27901000AYX30 |
| 927702544901 | L1HL-27901000AYY80 |
| 927702168101 | L1HL-30801000AWK80 |
| 927702168101 | L1HL-30801000AWK80 |
| 927702993401 | L1HL-30801000AWK80 |
| 927702168901 | L1HL-30801000AWM90 |
| 927702168901 | L1HL-30801000AWM90 |
| 927702993301 | L1HL-30801000AWM90 |
| 927702455801 | L1HL-30801000AYJ30 |
| 927702456101 | L1HL-30801000AYK80 |
| 927702491301 | L1HL-30801000AYW70 |
| 927702168501 | L1HL-30901000AWK80 |
| 927702168501 | L1HL-30901000AWK80 |
| 927702994801 | L1HL-30901000AWK80 |
| 927702994801 | L1HL-30901000AWK80 |
| 927703153301 | L1HL-30901000AWK80 |
| 927702169301 | L1HL-30901000AWM90 |
| 927702169301 | L1HL-30901000AWM90 |
| 927702994701 | L1HL-30901000AWM90 |
| 927702994701 | L1HL-30901000AWM90 |
| 927703153201 | L1HL-30901000AWM90 |
| 927702540901 | L1HL-30901000AYW70 |
| 927702544401 | L1HL-30901000AYX30 |
| 927702545001 | L1HL-30901000AYY80 |
| 927702168001 | L1HL-35801000AWK80 |
| 927702168001 | L1HL-35801000AWK80 |
| 927702993701 | L1HL-35801000AWK80 |
| 927702168801 | L1HL-35801000AWM90 |
| 927702168801 | L1HL-35801000AWM90 |
| 927702993601 | L1HL-35801000AWM90 |

|              |                    |
|--------------|--------------------|
| 927702540701 | L1HL-35801000AYW70 |
| 927702544201 | L1HL-35801000AYX30 |
| 927702544801 | L1HL-35801000AYY80 |
| 927702168401 | L1HL-35901000AWK80 |
| 927702168401 | L1HL-35901000AWK80 |
| 927702995101 | L1HL-35901000AWK80 |
| 927702995101 | L1HL-35901000AWK80 |
| 927703153501 | L1HL-35901000AWK80 |
| 927702169201 | L1HL-35901000AWM90 |
| 927702169201 | L1HL-35901000AWM90 |
| 927702995001 | L1HL-35901000AWM90 |
| 927702995001 | L1HL-35901000AWM90 |
| 927703153401 | L1HL-35901000AWM90 |
| 927702541001 | L1HL-35901000AYW70 |
| 927702544501 | L1HL-35901000AYX30 |
| 927702545101 | L1HL-35901000AYY80 |
| 927702167901 | L1HL-40801000AWK80 |
| 927702167901 | L1HL-40801000AWK80 |
| 927702994001 | L1HL-40801000AWK80 |
| 927702168701 | L1HL-40801000AWM90 |
| 927702168701 | L1HL-40801000AWM90 |
| 927702993901 | L1HL-40801000AWM90 |
| 927702455901 | L1HL-40801000AYJ30 |
| 927702456201 | L1HL-40801000AYK80 |
| 927702491401 | L1HL-40801000AYW70 |
| 927702168301 | L1HL-40901000AWK80 |
| 927702168301 | L1HL-40901000AWK80 |
| 927702995401 | L1HL-40901000AWK80 |
| 927702995401 | L1HL-40901000AWK80 |
| 927703153701 | L1HL-40901000AWK80 |
| 927702169101 | L1HL-40901000AWM90 |
| 927702169101 | L1HL-40901000AWM90 |
| 927702995301 | L1HL-40901000AWM90 |
| 927702995301 | L1HL-40901000AWM90 |
| 927703153601 | L1HL-40901000AWM90 |
| 927702541101 | L1HL-40901000AYW70 |
| 927702544601 | L1HL-40901000AYX30 |
| 927702545201 | L1HL-40901000AYY80 |
| 927702167801 | L1HL-50801000AWK80 |
| 927702167801 | L1HL-50801000AWK80 |
| 927702994201 | L1HL-50801000AWK80 |
| 927702456001 | L1HL-50801000AYJ30 |
| 927702456301 | L1HL-50801000AYK80 |
| 927702491501 | L1HL-50801000AYW70 |

|              |                    |
|--------------|--------------------|
| 927702082201 | L2H1-2780016MAC001 |
| 927702901901 | L2H1-2780016MAC001 |
| 927702091701 | L2H1-2780009MAC001 |
| 927703034601 | L2H1-2780009MAC001 |
| 927702999901 | L2H1-2780015RAC001 |
| 927702082601 | L2H1-2790016MAC001 |
| 927702902001 | L2H1-2790016MAC001 |
| 927703151701 | L2H1-2790016MAC001 |
| 927703013001 | L2H1-2790016MAC001 |
| 927702092101 | L2H1-2790009MAC001 |
| 927703035001 | L2H1-2790009MAC001 |
| 927703151601 | L2H1-2790009MAC001 |
| 927703076601 | L2H1-2790009MAC001 |
| 927703000401 | L2H1-2790015RAC001 |
| 927702082101 | L2H1-3080016MAC001 |
| 927702902101 | L2H1-3080016MAC001 |
| 927703012601 | L2H1-3080016MAC001 |
| 927702091801 | L2H1-3080009MAC001 |
| 927703034501 | L2H1-3080009MAC001 |
| 927703076201 | L2H1-3080009MAC001 |
| 927703000001 | L2H1-3080015RAC001 |
| 927702082501 | L2H1-3090016MAC001 |
| 927702902301 | L2H1-3090016MAC001 |
| 927703012901 | L2H1-3090016MAC001 |
| 927703151901 | L2H1-3090016MAC001 |
| 927702092201 | L2H1-3090009MAC001 |
| 927703034901 | L2H1-3090009MAC001 |
| 927703076501 | L2H1-3090009MAC001 |
| 927703151801 | L2H1-3090009MAC001 |
| 927703000501 | L2H1-3090015RAC001 |
| 927702082001 | L2H1-3580016MAC001 |
| 927702902501 | L2H1-3580016MAC001 |
| 927703012501 | L2H1-3580016MAC001 |
| 927702091901 | L2H1-3580009MAC001 |
| 927703034401 | L2H1-3580009MAC001 |
| 927703076101 | L2H1-3580009MAC001 |
| 927703000101 | L2H1-3580015RAC001 |
| 927702082401 | L2H1-3590016MAC001 |
| 927702902801 | L2H1-3590016MAC001 |
| 927703152101 | L2H1-3590016MAC001 |
| 927703012801 | L2H1-3590016MAC001 |
| 927702092301 | L2H1-3590009MAC001 |
| 927703034801 | L2H1-3590009MAC001 |
| 927703076401 | L2H1-3590009MAC001 |

|              |                    |
|--------------|--------------------|
| 927703152001 | L2H1-3590009MAC001 |
| 927703000601 | L2H1-3590015RAC001 |
| 927702081901 | L2H1-4080016MAC001 |
| 927702903101 | L2H1-4080016MAC001 |
| 927703012401 | L2H1-4080016MAC001 |
| 927702092001 | L2H1-4080009MAC001 |
| 927703034301 | L2H1-4080009MAC001 |
| 927703076001 | L2H1-4080009MAC001 |
| 927703000201 | L2H1-4080015RAC001 |
| 927702354201 | L2H1-4080042RAC001 |
| 927702082301 | L2H1-4090016MAC001 |
| 927702903301 | L2H1-4090016MAC001 |
| 927703152301 | L2H1-4090016MAC001 |
| 927703012701 | L2H1-4090016MAC001 |
| 927702092401 | L2H1-4090009MAC001 |
| 927703034701 | L2H1-4090009MAC001 |
| 927703152201 | L2H1-4090009MAC001 |
| 927703076301 | L2H1-4090009MAC001 |
| 927703000701 | L2H1-4090015RAC001 |
| 927702125601 | L2H1-5080016MAC001 |
| 927702903401 | L2H1-5080016MAC001 |
| 927703012301 | L2H1-5080016MAC001 |
| 927703000301 | L2H1-5080015RAC001 |