



Product Change Notification - SYST-17PBUF969

Date:

18 Dec 2018

Product Category:

USB to Ethernet Controllers

Affected CPNs:



Notification subject:

Data Sheet - LAN7850 - Hi-Speed USB 2.0 to 10/100/1000 Ethernet Controller with HSIC

Notification text:

SYST-17PBUF969

Microchip has released a new DeviceDoc for the LAN7850 - Hi-Speed USB 2.0 to 10/100/1000 Ethernet Controller with HSIC of devices. If you are using one of these devices please read the document located at [LAN7850 - Hi-Speed USB 2.0 to 10/100/1000 Ethernet Controller with HSIC](#).

Notification Status: Final

Description of Change: Section: Cover, Section 9.0, "Gigabit Ethernet PHY (GPHY)," on page 90, Section 9.1, "Category 5 Twisted Pair Media Interface," on page 90, Section 15.3.2, "Ethernet PHY Extended Page 1 Registers," on page 246. Correction: Removed references to cable diagnostic functions.

Impacts to Data Sheet: None

Reason for Change: To Improve Manufacturability

Change Implementation Status: Complete

Date Document Changes Effective: 18 Dec 2018

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s):

[LAN7850 - Hi-Speed USB 2.0 to 10/100/1000 Ethernet Controller with HSIC](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to [receive Microchip PCNs via email](#) please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to [change your PCN profile, including opt out](#), please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

LAN7850-I/8JX

LAN7850/8JX

LAN7850T-I/8JX

LAN7850T/8JX