

**Date: January 2, 2015**

**To: BCA and BMA Add-A-Pole Fuse Block Customers**

**Subject: End-of-Life Notice and Recommended Replacement Products**

Eaton's Bussmann business has developed a new line of modular ferrule fuse block products for Class CC and supplemental fuse applications. The new fuse blocks are fully modular with a snap-together design for tool-less assembly of multiple-pole blocks at point-of-use while reducing inventory and assembly time. Each block has provisions for DIN-Rail or panel mounting that permit the same block to be used for multiple applications. The new blocks also feature optional covers that enhance electrical safety with IP20 finger-safe ratings for the full wire size range of each block. Safety is further improved with an enhanced lockout/tagout feature, compatible with a broad array of lock designs. Covers are available with open circuit indication to speed troubleshooting and have provisions for an optional snap-in marker label for easy circuit identification.

As a result of the launch of these new fuse blocks, Eaton's Bussmann business is discontinuing the Add-A-Pole Class CC fuse block (BCA) and  $1\frac{3}{32}$ " x  $1\frac{1}{2}$ " (10 x 38mm) supplemental fuse block (BMA) products. The new fuse blocks are drop-in replacements with the same terminal options while incorporating enhanced design features and options that make them a superior solution to the ones they replace. The affected part numbers are listed in the table below, along with their recommended replacements from the new modular fuse block product line.

Existing inventory is saleable product and should not be returned. Last time orders for BCA and BMA products will be accepted up to February 15, 2015, or while inventory lasts, for shipment no later than February 28, 2015.

Description	Discontinued Fuse Blocks		Recommended New Fuse Blocks	
	Part #	UPC	New Part #	UPC
Class CC Fuse Block, 1 Pole	BCA6031PQ	051712725385	BCM603-1PQ	051712486330
Class CC Fuse Block, 1 Pole	BCA6031SQ	051712725392	BCM603-1SQ	051712486361
Class CC Fuse Block, 2 Pole	BCA6032PQ	051712725422	BCM603-2PQ	051712486736
Class CC Fuse Block, 2 Pole	BCA6032SQ	051712725439	BCM603-2SQ	051712486385
Class CC Fuse Block, 3 Pole	BCA6033PQ	051712725460	BCM603-3PQ	051712486743
Class CC Fuse Block, 3 Pole	BCA6033SQ	051712725477	BCM603-3SQ	051712486392
Class CC Fuse Block, Adder	BCA603APQ	051712725347	BCM603-1PQ	051712486330
Class CC Fuse Block, Adder	BCA603ASQ	051712725354	BCM603-1SQ	051712486361
Midget Fuse Block, 1 Pole	BMA6031PQ	051712725408	BMM603-1PQ	051712486408
Midget Fuse Block, 1 Pole	BMA6031SQ	051712725415	BMM603-1SQ	051712486446
Midget Fuse Block, 2 Pole	BMA6032PQ	051712725446	BMM603-2PQ	051712486422
Midget Fuse Block, 2 Pole	BMA6032SQ	051712725453	BMM603-2SQ	051712486460
Midget Fuse Block, 3 Pole	BMA6033PQ	051712725484	BMM603-3PQ	051712486439
Midget Fuse Block, 3 Pole	BMA6033SQ	051712725491	BMM603-3SQ	051712486477
Midget Fuse Block, Adder	BMA603APQ	051712725361	BMM603-1PQ	051712486408
Midget Fuse Block, Adder	BMA603ASQ	051712725378	BMM603-1SQ	051712486446

If you have any questions regarding this product change notice, please contact your local Bussmann representative.

Kind Regards,

Darren McDowell  
Product Manager

[DarrenLMcDowell@Eaton.com](mailto:DarrenLMcDowell@Eaton.com)