

PCN Number:	20190212003.0	PCN Date:	February 19, 2019
Title:	Datasheet for LMK01801		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
		<input type="checkbox"/>	Wafer Bump Site
		<input type="checkbox"/>	Wafer Bump Material
		<input type="checkbox"/>	Wafer Bump Process
		<input type="checkbox"/>	Wafer Fab Site
		<input type="checkbox"/>	Wafer Fab Materials
		<input type="checkbox"/>	Wafer Fab Process

Notification Details

Description of Change:

Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details.



LMK01801

SNAS573B – JANUARY 2012 – REVISED JANUARY 2019

Changes from Revision A (April 2013) to Revision B

Page

• Added <i>Device Information</i> table	1
• Changed Pin Control Mode Table for EN_PIN_CTRL = Low	1
• Added SPI note for Pin Control Mode Tables	1
• Changed polarity for pins 4,5 and 9,10 to be correct.	1
• Changed CLKinX_DIV condition to "2 to 8" from "1 to 8" for f_{CLKinX}	1
• Deleted T_{CR} because readback is not supported	12
• Added <i>Device and Documentation Support</i> section	49
• Added <i>Mechanical, Packaging, and Orderable Information</i> section	50

The datasheet number will be changing.

Device Family	Change From:	Change To:
LMK01801	SNAS573A	SNAS573B

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/LMK01801>

Reason for Change:

To accurately reflect device characteristics.

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.

Changes to product identification resulting from this PCN:

None.

Product Affected:

LMK01801BISQ/NOPB	LMK01801BISQE/NOPB	LMK01801BISQX/NOPB
-------------------	--------------------	--------------------

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
WW PCN Team	PCN_ww_admin_team@list.ti.com