



Product Change Notification / NTDO-20RUKF310

Date:

02-Apr-2023

PCN Type:

End of Life

Notification Subject:

eSign# E000169948: End of Life (EOL) of selected BM77SPP03MC2, BM77SPP05MC2, BM77SPPS3MC2, BM77SPPS5MC2, RN4677 and IS1677SM device families.

Notification Text:

PCN Status:End of Life (EOL) Notification

Microchip Parts Affected:Please open one of the files found in the Affected CPNs section.

The list of affected CPNs with its corresponding replacement parts (if applicable) can be found on the attachments field labeled as PCN_#_Suggested Replacements.

NOTE: For your convenience Microchip includes identical files in two formats (.pdf and .xls).

EOL Description:The selected BM77SPP03MC2, BM77SPP05MC2, BM77SPPS3MC2, BM77SPPS5MC2, RN4677 and IS1677SM device families will be moving to End of Life (EOL) status effective today. These selected device families will no longer be offered after April 2, 2023. Please review the attached parts affected list below for details about replacement parts if applicable.

Note: If replacement parts are not listed in the attached list please contact your **Local Sales Representative**

Reason for EOL:No longer have manufacturing support for the CPN listed in the attachment.

Estimated Effective Dates:April 2, 2023

Revision History:April 2, 2023: Issued EOL notification.

Attachments:

[PCN_NTDO-20RUKF310_Suggested Replacements.xlsx](#)
[PCN_NTDO-20RUKF310_Suggested Replacements.pdf](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

PCN_NTDO-20RUKF310

EOL Catalog Part Number (CPN)	Replacement CPN	Notes about Recommended Replacement parts
IS1677SM-101	IS1678SM-152	Contact Your Local Sales Office
IS1677SM-101-TRAY		Contact Your Local Sales Office
BM77SPP03MC2-0003AA	BM78SPP05MC2-0B06AA	Contact Your Local Sales Office
BM77SPP03MC2-0004AA		Contact Your Local Sales Office
BM77SPP03MC2-0006AA		Contact Your Local Sales Office
BM77SPP03MC2-0007AA		Contact Your Local Sales Office
BM77SPP03MC2-0008AA		Contact Your Local Sales Office
BM77SPP03MC2-0009AA		Contact Your Local Sales Office
BM77SPP03MC2-000AAA		Contact Your Local Sales Office
BM77SPP03MC2-000BAA		Contact Your Local Sales Office
BM77SPP05MC2-0006AA		Contact Your Local Sales Office
BM77SPP05MC2-0006AA		BM78SPPS5MC2-0B06AA
BM77SPPS3MC2-0007AA	Contact Your Local Sales Office	
BM77SPPS3MC2-0008AA	Contact Your Local Sales Office	
BM77SPPS3MC2-000AAA	Contact Your Local Sales Office	
BM77SPPS5MC2-0004AA	Contact Your Local Sales Office	
RN4677-V/RM100	RN4678-VB/RM122 or RN4678APL-VB/RM122	Contact Your Local Sales Office
RN4677-V/RM112		Contact Your Local Sales Office
IS1677SM-102	Contact Your Local Sales Office	
IS1677SM-102-TRAY	Contact Your Local Sales Office	
BM77SPPS3MC2-S00AAA	Contact Your Local Sales Office	
BM77SPPS3MC2-PH07AA	Contact Your Local Sales Office	