



Test Procedure for the NUD4001DGEVB Evaluation Board



Table 1: Required Equipment

AC or DC Power Supply	Digital Multimeter	Red Test Leads
Black Test Leads		

Test Procedure:

- 1. Apply 12 V ac or dc to the input pins.**
- 2. The LEDs will light up.**
- 3. Measure the current through the LEDs.**