



August 25, 2021

**Subject: Incorrect MSL printed on labels**

Dear customer,

Skyworks has identified a labeling issue that has affected some of the Skyworks products that you may receive. The MSL rating was printed as MSL 2 on the labels, but this is not accurate for the affected products. A root cause and corrective action investigation has been initiated to determine why this happened and prevent its recurrence.

In the current global capacity-constrained environment, Skyworks wants to ensure that your orders will continue to be fulfilled without delay or interruption, which requires that the existing labels be left in place. The part numbers with remaining inventory that you may receive with inaccurate labels are listed in Appendix A.

There is no change to the manufacturing recipe or materials used for these lots, and they continue to be rated the same as all prior shipments you have received. This error is only a clerical error in the MSL printed on the labels.

If you have technical questions regarding this advisory, please contact your sales representative.

Sincerely,

A handwritten signature in black ink that reads "Harold Melton".

Harold Melton  
Quality Engineering Director  
Tel. 512.297.3604

## Appendix A

**Affected products for future shipments:**

Part Number (T&R)	Part Number (non-T&R)	MSL Printed	Actual MSL
SI2404-D-FSR	SI2404-D-FS	2	3
SI3010-F-FSR	SI3010-F-FS	2	3
SI3056-D-FSR	SI3056-D-FS	2	3
SI8232BB-D-IS1R	SI8232BB-D-IS1	2	2a
SI82395BD-ISR	SI82395BD-IS	2	2a
SI82397BD-ISR	SI82397BD-IS	2	2a
SI8273BBD-IS1R	SI8273BBD-IS1	2	2a
SI8273BB-IS1R	SI8273BB-IS1	2	2a
SI8273DB-IS1R	SI8273DB-IS1	2	2a
SI8273GB-IS1R	SI8273GB-IS1	2	2a
SI8286CC-ISR	SI8286CC-IS	2	3
SI8410AB-D-ISR	SI8410AB-D-IS	2	2a
SI8420BD-D-ISR	SI8420BD-D-IS	2	2a
SI8422AD-D-ISR	SI8422AD-D-IS	2	2a
SI8422BD-D-ISR	SI8422BD-D-IS	2	2a
SI8423AB-D-ISR	SI8423AB-D-IS	2	2a
SI8431AB-D-ISR	SI8431AB-D-IS	2	2a
SI8440BB-D-ISR	SI8440BB-D-IS	2	2a
SI8442AB-C-ISR	SI8442AB-C-IS	2	2a
SI8442AB-D-ISR	SI8442AB-D-IS	2	2a
SI8442BB-D-ISR	SI8442BB-D-IS	2	2a
SI8600AC-B-ISR	SI8600AC-B-IS	2	2a
SI8602AC-B-ISR	SI8602AC-B-IS	2	2a
SI8610BD-B-ISR	SI8610BD-B-IS	2	2a
SI8622BD-B-ISR	SI8622BD-B-IS	2	2a
SI8622BT-ISR	SI8622BT-IS	2	2a
SI8622ET-ISR	SI8622ET-IS	2	2a
SI8631AB-B-ISR	SI8631AB-B-IS	2	2a
SI8631BT-ISR	SI8631BT-IS	2	2a
SI8640BT-ISR	SI8640BT-IS	2	2a
SI8641BD-B-IS2R	SI8641BD-B-IS2	2	3

Part Number (T&R)	Part Number (non-T&R)	MSL Printed	Actual MSL
SI8641BT-ISR	SI8641BT-IS	2	2a
SI8642BD-B-IS2R	SI8642BD-B-IS2	2	3
SI8642ET-ISR	SI8642ET-IS	2	2a
SI8662BD-B-ISR	SI8662BD-B-IS	2	2a
SI8662ED-B-ISR	SI8662ED-B-IS	2	2a
SI8752AB-ISR	SI8752AB-IS	2	2a