

Product Discontinuation



PD_074_19

| | |
|-----------------------|------------|
| ■ Last Order Date: | 2019-10-15 |
| ■ Last Delivery Date: | 2020-04-15 |

Reason: Sales Product Name (SPN) nomenclature change. Both products are halogen free and have the same form, fit and function.
Please order "non-G" version going forward.

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | | |
|-----------------|---------------|-----------------|---------|-------------------|---------------|----------------|---------|------------------------|
| Device | Ordering Code | OPN | Package | Device | Ordering Code | OPN | Package | Pin-to-pin replacement |
| IRLML2402GTRPBF | SP001572972 | IRLML2402GTRPBF | SOT23 | IRLML2402TRPBF | SP001552710 | IRLML2402TRPBF | SOT23 | YES |
| IRLML2502GTRPBF | SP001558826 | IRLML2502GTRPBF | SOT23 | IRLML2502TRPBF | SP001558336 | IRLML2502TRPBF | SOT23 | YES |
| IRLML2803GTRPBF | SP001550482 | IRLML2803GTRPBF | SOT23 | IRLML2803TRPBF | SP001572964 | IRLML2803TRPBF | SOT23 | YES |
| IRLML5103GTRPBF | SP001568594 | IRLML5103GTRPBF | SOT23 | IRLML5103TRPBF | SP001572946 | IRLML5103TRPBF | SOT23 | YES |
| IRLML5203GTRPBF | SP001567222 | IRLML5203GTRPBF | SOT23 | IRLML5203TRPBF | SP001558846 | IRLML5203TRPBF | SOT23 | YES |
| IRLML6302GTRPBF | SP001550492 | IRLML6302GTRPBF | SOT23 | IRLML6302TRPBF | SP001574060 | IRLML6302TRPBF | SOT23 | YES |
| IRLML6401GTRPBF | SP001568584 | IRLML6401GTRPBF | SOT23 | IRLML6401TRPBF | SP001577044 | IRLML6401TRPBF | SOT23 | YES |
| IRLML6402GTRPBF | SP001578888 | IRLML6402GTRPBF | SOT23 | IRLML6402TRPBF | SP001552740 | IRLML6402TRPBF | SOT23 | YES |

If you have any questions, please do not hesitate to contact your local sales office or Miriam Wolheim, Business Manager, miriam.wolheim@infineon.com

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability.
Early ordering is strongly recommended!