



Customer Information Notification

2022050311 : Release of Errata Document Revision "11" and Reference Manual Addendum for T4240 Family of Devices

Note: This notice is NXP Company Proprietary.

Issue Date: Jul 01, 2022 **Effective date:** Jul 02, 2022

Here is your personalized notification about a NXP general announcement.
For detailed information we invite you to view this notification online

Management summary

Release of Errata Document Revision "11" and Reference Manual Addendum for T4240 Family of Devices.

Change Category

<input type="checkbox"/> Wafer Fab Process	<input type="checkbox"/> Assembly Process	<input type="checkbox"/> Product Marking	<input type="checkbox"/> Test Process	<input type="checkbox"/> Design
<input type="checkbox"/> Wafer Fab Materials	<input type="checkbox"/> Assembly Materials	<input type="checkbox"/> Mechanical Specification	<input type="checkbox"/> Test Equipment	<input checked="" type="checkbox"/> Errata
<input type="checkbox"/> Wafer Fab Location	<input type="checkbox"/> Assembly Location	<input type="checkbox"/> Packing/Shipping/Labeling	<input type="checkbox"/> Test Location	<input type="checkbox"/> Electrical spec./Test coverage
<input type="checkbox"/> Firmware	<input type="checkbox"/> Other			

PCN Overview

Description

The following changes have been made to the T4240, T4160 and T4080 Errata document:

Added the following PCI-e errata:

- A050275
- A050279
- A050280
- A050281
- A050282
- A050283
- A-050284
- A-050290
- A-050293
- A-050301
- A-050303
- A-050306

Removed the following USB erratum:

• A-0996261

Updated the wording for eDMA erratum A-011218 "eDMA may not work with SPI"

Reason

Notify customers of T4240 device errata and Reference Manual updates.

Anticipated Impact on Form, Fit, Function, Reliability or Quality

No Impact on form, fit, function, reliability or quality

Additional information

Additional documents: [view online](#)

Contact and Support

For all inquiries regarding the ePCN tool application or access issues, please contact NXP "Global Quality Support Team".

For all Quality Notification content inquiries, please contact your local NXP Sales Support team.

For specific questions on this notice or the products affected please contact our specialist directly:

Name	Safwan Raad
Position	Apps Manager
e-mail address	safwan.raad@nxp.com

At NXP Semiconductors we are constantly striving to improve our product and processes to ensure they reach the highest possible Quality Standards. Customer Focus, Passion to Win.

NXP Quality Management Team.

About NXP Semiconductors

NXP Semiconductors N.V. (NASDAQ: NXPI) provides High Performance Mixed Signal and Standard Product solutions that leverage its leading RF, Analog, Power Management, Interface, Security and Digital Processing expertise. These innovations are used in a wide range of automotive, identification, wireless infrastructure, lighting, industrial, mobile, consumer and computing applications.

You have received this email because you are a designated contact or subscribed to NXP Quality Notifications. NXP shall not be held liable if this Notification is not correctly distributed within your organization.

This message has been automatically distributed. Please do not reply .

NXP Semiconductors
High Tech Campus, 5656 AG Eindhoven, The Netherlands

© 2006- 2022 NXP Semiconductors. All rights reserved.

Changed Orderable Part#	12NC	Product Type	Product Description	Package Outline	Package Description	Product Status	Customer Specific Indicator	Product Line
T4160NXE7PQB	935311662557	T4160NXE7PQB	T4160 R2 XT WE 1500	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4080NXN7PQB	935311976557	T4080NXN7PQB	T4080 R2 XT 1500	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4081NSN7TTB	935313235557	T4081NSN7TTB	T4081 R2 ST 1800/1800	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4241NSE7PQB	935313253557	T4241NSE7PQB	T4241 R2 ST WE 1500/1600	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4241NSE7QTB	935313303557	T4241NSE7QTB	T4241 R2 ST WE 1667/1800	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4081NXE7PQB	935313315557	T4081NXE7PQB	T4081 R2 XT WE 1500/1600	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4161NSE7TTB	935313374557	T4161NSE7TTB	T4161 R2 ST WE 1800/1800	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4241NSN7TTB	935313375557	T4241NSN7TTB	T4241 R2 ST 1800/1800	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4081NXN7TTB	935316366557	T4081NXN7TTB	T4081 R2 XT 1800/1800	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4161NXN7TTB	935316386557	T4161NXN7TTB	T4161 R2 XT 1800/1800	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4161NSE7QTB	935316412557	T4161NSE7QTB	T4161 R2 ST WE 1667/1800	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4161NSE7PQB	935316444557	T4161NSE7PQB	T4161 R2 ST WE 1500/1600	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4160NSN7QTB	935318121557	T4160NSN7QTB	T4160 R2 ST 1667	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4161NXN7PQB	935318848557	T4161NXN7PQB	T4161 R2 XT 1500/1600	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4081NXE7QTB	935318852557	T4081NXE7QTB	T4081 R2 XT WE 1600/1800	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4081NSE7PQB	935318853557	T4081NSE7PQB	T4081 R2 ST WE 1500/1600	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4241NSN7PQB	935318887557	T4241NSN7PQB	T4241 R2 ST 1500/1600	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4241NXE7TTB	935318925557	T4241NXE7TTB	T4241 R2 XT WE 1800/1800	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4081NSE7QTB	935318933557	T4081NSE7QTB	T4081 R2 ST WE 1667/1800	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4161NSN7TTB	935318934557	T4161NSN7TTB	T4161 R2 ST 1800/1800	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4081NXE7TTB	935318935557	T4081NXE7TTB	T4081 R2 XT WE 1800/1800	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4240NSE7QTB	935320222557	T4240NSE7QTB	T4240 R2 ST WE 1667	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4080NSE7PQB	935320255557	T4080NSE7PQB	T4080 R2 ST WE 1500	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4080NSE7QTB	935320304557	T4080NSE7QTB	T4080 R2 ST WE 1667	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4240NXE7PQB	935320402557	T4240NXE7PQB	T4240 R2 XT WE 1500	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4160NXN7PQB	935321959557	T4160NXN7PQB	T4160 R2 XT 1500	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4080NXE7PQB	935322005557	T4080NXE7PQB	T4080 R2 XT WE 1500	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4160NSE7QTB	935322104557	T4160NSE7QTB	T4160 R2 ST WE 1667	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4080NSN7QTB	935322105557	T4080NSN7QTB	T4080 R2 ST 1667	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4240NXN7PQB	935322113557	T4240NXN7PQB	T4240 R2 XT 1500	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4161NXN7QTB	935322481557	T4161NXN7QTB	T4161 R2 XT 1600/1800	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4161NXE7PQB	935322498557	T4161NXE7PQB	T4161 R2 XT WE 1500/1600	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4081NXN7QTB	935322511557	T4081NXN7QTB	T4161 R2 XT 1600/1800	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4081NXN7PQB	935322522557	T4081NXN7PQB	T4081 R2 XT 1500/1600	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4081NSN7QTB	935322544557	T4081NSN7QTB	T4081 R2 ST 1667/1800	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4240NSN7PQB	935323503557	T4240NSN7PQB	T4240 R2 ST 1500	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4160NSE7TTB	935323661557	T4160NSE7TTB	T4160 R2 ST WE 1800/1800	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4241NSE7TTB	935323853557	T4241NSE7TTB	T4241 R2 ST WE 1800/1800	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4241NXN7TTB	935323854557	T4241NXN7TTB	T4241 R2 XT 1800/1800	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4241NXE7QTB	935323862557	T4241NXE7QTB	T4241 R2 XT WE 1600/1800	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4161NXE7QTB	935323863557	T4161NXE7QTB	T4161 R2 XT WE 1600/1800	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4081NSN7PQB	935323884557	T4081NSN7PQB	T4081 R2 ST 1500/1600	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4241NXN7QTB	935323888557	T4241NXN7QTB	T4241 R2 XT 1600/1800	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4240NSN7QTB	935324764557	T4240NSN7QTB	T4240 R2 ST 1667	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4240NSE7PQB	935324809557	T4240NSE7PQB	T4240 R2 ST WE 1500	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4240NSE7TTB	935324898557	T4240NSE7TTB	T4240 R2 ST WE 1800/1800	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4241NXE7PQB	935325098557	T4241NXE7PQB	T4241 R2 XT WE 1500/1600	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4241NXN7PQB	935325106557	T4241NXN7PQB	T4241 R2 XT 1500/1600	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4161NXE7TTB	9353251124557	T4161NXE7TTB	T4161 R2 XT WE 1800/1800	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4241NSN7QTB	935325126557	T4241NSN7QTB	T4241 R2 ST 1667/1800	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4080NSN7PQB	935325835557	T4080NSN7PQB	T4080 R2 ST 1500	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4160NSE7PQB	935325859557	T4160NSE7PQB	T4160 R2 ST WE 1500	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4160NSN7PQB	935325888557	T4160NSN7PQB	T4160 R2 ST 1500	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4240NSN7TTB	935325938557	T4240NSN7TTB	T4240 R2 ST 1800/1800	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4160NSN7TTB	935325946557	T4160NSN7TTB	T4160 R2 ST 1800/1800	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4161NSN7PQB	935326061557	T4161NSN7PQB	T4161 R2 ST 1500/1600	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4161NSN7QTB	935326096557	T4161NSN7QTB	T4161 R2 ST 1667/1800	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4081NSE7TTB	935326097557	T4081NSE7TTB	T4081 R2 ST WE 1800/1800	FCPBGA1932L	SOT1645-1	RFS	No	BLDN
T4081NSE7NQB	935364733557	T4081NSE7NQB	T4081 R2 ST WE 1333/1600	FCPBGA1932L	SOT1645-1	WIT	No	BLDN
T4081NSN7NQB	935364734557	T4081NSN7NQB	T4081 R2 ST 1333/1600	FCPBGA1932L	SOT1645-1	WIT	No	BLDN
T4161NSE7NQB	935364735557	T4161NSE7NQB	T4161 R2 ST WE 1333/1600	FCPBGA1932L	SOT1645-1	WIT	No	BLDN
T4161NSN7NQB	935364736557	T4161NSN7NQB	T4161 R2 ST 1333/1600	FCPBGA1932L	SOT1645-1	WIT	No	BLDN
T4241NSE7NQB	935364737557	T4241NSE7NQB	T4241 R2 ST WE 1333/1600	FCPBGA1932L	SOT1645-1	WIT	No	BLDN
T4241NSN7NQB	935364738557	T4241NSN7NQB	T4241 R2 ST 1333/1600	FCPBGA1932L	SOT1645-1	WIT	No	BLDN