

PRODUCT CHANGE NOTIFICATION

Product Category STRONGHOLD 20211216-1

Product Group STRONGHOLD

ISSUE DATE: 16-Dec-21

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Some Stronghold products will be discontinued with no replacement parts.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2022	3	16

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s) Compatibility Type

- MP85W4T5-C6/A9 No Replacement
- MP85W4T5-C6/A9L No Replacement
- MP89W1T2-C6/A9E No Replacement
- MP89W1T2-C6/A9L No Replacement
- MP89W1T5-C6/A9 No Replacement
- MP89W1T5-C6/A9L No Replacement
- MP89W2T2-C6/A9E No Replacement
- MP89W2T2-C6/A9L No Replacement
- MP89W2T5-C6/A9 No Replacement
- MP89W2T5-C6/A9L No Replacement