

To : Dear Valued Customers

Product Discontinuance Notice

Subject : Products discontinue.													
Parts Affected :													
<table border="1"> <thead> <tr> <th>Part No.</th> <th>Package Type</th> </tr> </thead> <tbody> <tr> <td>1N4148-G</td> <td>DO-35</td> </tr> <tr> <td>CDSL4148-G</td> <td>MiniMELF (SOD-80)</td> </tr> <tr> <td>CZRL5225B-G Thru CZRL5267B-G</td> <td>MiniMELF (SOD-80)</td> </tr> <tr> <td>CZRL55C2V4-G Thru CZRL55C75-G</td> <td>MiniMELF (SOD-80)</td> </tr> <tr> <td>CZRL55C2V4-USG Thru CZRL55C75-USG</td> <td>MiniMELF (SOD-80)</td> </tr> </tbody> </table>		Part No.	Package Type	1N4148-G	DO-35	CDSL4148-G	MiniMELF (SOD-80)	CZRL5225B-G Thru CZRL5267B-G	MiniMELF (SOD-80)	CZRL55C2V4-G Thru CZRL55C75-G	MiniMELF (SOD-80)	CZRL55C2V4-USG Thru CZRL55C75-USG	MiniMELF (SOD-80)
Part No.	Package Type												
1N4148-G	DO-35												
CDSL4148-G	MiniMELF (SOD-80)												
CZRL5225B-G Thru CZRL5267B-G	MiniMELF (SOD-80)												
CZRL55C2V4-G Thru CZRL55C75-G	MiniMELF (SOD-80)												
CZRL55C2V4-USG Thru CZRL55C75-USG	MiniMELF (SOD-80)												
Reason for Discontinuance :													
Due to low demand, the part listed below will be discontinued.													
Alternative Products :													
Please contact sales person or manufacturer's representative.													
Last time buy / order entry : Dec 30, 2021													
Effective Date : Sep 30, 2022													
R&D Dept. Signature :	QA Dept. Signature :												
													