



520 Park East Blvd., New Albany, IN 47150 U.S.A
(812)-944-6733 / 1-800-SAMTEC9

Product Change Notification

1. ECN #: 285091

2. Date of Announcement: October 24, 2016

3. Series:

- IPBS - .165 DOUBLE ROW SOCKET ASSEMBLY

4. Part #'s Affected


- IPBS-106-XX-XX-D-XX
- IPBS-107-XX-XX-D-XX
- IPBS-108-XX-XX-D-XX
- IPBS-109-XX-XX-D-XX
- IPBS-110-XX-XX-D-XX
- IPBS-111-XX-XX-D-XX
- IPBS-112-XX-XX-D-XX
- IPBS-113-XX-XX-D-XX
- IPBS-114-XX-XX-D-XX
- IPBS-115-XX-XX-D-XX

5. Description of Change:


Add void corings on 06 through 15 positions body.

6. Method of Identifying Change

Visual inspection; voids will be noticed on ends of body where prior revisions had no voids; this is a rolling change.




Existing product with -GP option



Existing product with -GP option

Changed product with -GP option



Changed product with -GP option

7. Reason for Change:

Changes made to improve dimensional consistency.

8. Impact of Change on Form, Fit, or Function:

- Form - this is a Form change.

9. Projected Implementation Date: November 17, 2016