



Not Recommended For New Design: All EYP Series Thermal Cutoffs

NRFND.PG47.10.17.2017

10.17.2017

About This Notice:	EYP Series Thermal Cutoffs are effective immediately Not Recommended for New Design due to declining market and aging production equipment.
Features:	Please see datasheet.
Effective Date:	Immediately
Affected Parts and/or Replacements:	All Panasonic Thermal Cutoffs - EYP Series
Datasheet(s):	See attached.
Notes:	

Panasonic NRFND.PG47.10.17.2017 EYP Series Thermal Cutoffs

Affected Part Numbers

EYP-05BE101
EYP-05BE101L
EYP-05BE115
EYP-05BE134
EYP-05BE138
EYP-05BE145
EYP-1BF101
EYP-1BF115
EYP-1BF134
EYP-1BF138
EYP-1BF145
EYP-2BH101
EYP-2BH115
EYP-2BH134
EYP-2BH138
EYP-2BH145
EYP-2BN082
EYP-2BN098V
EYP-2BN099
EYP-2BN099L
EYP-2BN109
EYP-2BN110
EYP-2BN127
EYP-2BN134
EYP-2BN143
EYP-2ML098U
EYP-2ML102U
EYP-2MP092AFT
EYP-2MP098AFT
EYP-2MT92
EYP-2MT92A
EYP-2MT92B
EYP-2MT98
EYP-2MT98A
EYP-2MT98B
EYP-4MU092GFD