

TAIYO YUDEN

TAIYO YUEN (USA) INC.
2107 North First Street
Suite 450
San Jose, CA 95131
Tel: (800) 368-2496
Fax: 408-213-011

DISCONTINUATION NOTICE

DATE: February 25, 2015

RE: LEADED COMMON MODE CHOKE COILS FOR AC LINES

Part Number: TLF24HB □□□K1
TLF24HBH□□□K1

REF NO.: UTY-DN15-02D

TAIYO YUDEN (U.S.A.), INC hereby gives notice that the following part number will be discontinued effective immediately. There is no sales history on these parts and therefore no last orders will be accepted.

Part No. TLF24HB Type	Note	Part No. TLF24HBH	Note
TLF24HB1223R0K1	No replacement	TLF24HBH1223R0K1	No replacement
TLF24HB2222R2K1	No replacement	TLF24HBH2222R2K1	No replacement
TLF24HB2722R0K1	No replacement	TLF24HBH2722R0K1	No replacement
TLF24HB3321R8K1	No replacement	TLF24HBH3321R8K1	No replacement
TLF24HB3921R5K1	No replacement	TLF24HBH3921R5K1	No replacement
TLF24HB5621R4K1	No replacement	TLF24HBH5621R4K1	No replacement
TLF24HB6821R2K1	No replacement	TLF24HBH6821R2K1	No replacement
TLF24HB8221R0K1	No replacement	TLF24HBH8221R0K1	No replacement
TLF24HB1031R0K1	No replacement	TLF24HBH1031R0K1	No replacement
TLF24HB1230R9K1	No replacement	TLF24HBH1230R9K1	No replacement
TLF24HB1830R8K1	No replacement	TLF24HBH1830R8K1	No replacement
TLF24HB2730R6K1	No replacement	TLF24HBH2730R6K1	No replacement
TLF24HB3330R5K1	No replacement	TLF24HBH3330R5K1	No replacement

NOTE: The information in this notice is applicable only to Taiyo Yuden customers in North and South America. Discontinuation schedules and availability may vary in other regions. To best serve you, all inquires and requests should be directed through the normal sales channels or you can contact the nearest Taiyo Yuden Sales Office.

Issued by TAIYO YUDEN (U.S.A.) INC.
Sales Planning Department