



**To : Dear Valued Customers**

**Product Discontinuance Notice**

Subject : CDBD Series Products discontinue.									
Parts Affected :									
<table border="1"><thead><tr><th>Part No.</th><th>Package</th></tr></thead><tbody><tr><td>CDBD1040-HF Thru CDBD10200-HF</td><td>TO-263/D2PAK</td></tr><tr><td>CDBD2040-HF Thru. CDBD20200-HF</td><td>TO-263/D2PAK</td></tr><tr><td>CDBD3060-G</td><td>TO-263/D2PAK</td></tr></tbody></table>		Part No.	Package	CDBD1040-HF Thru CDBD10200-HF	TO-263/D2PAK	CDBD2040-HF Thru. CDBD20200-HF	TO-263/D2PAK	CDBD3060-G	TO-263/D2PAK
Part No.	Package								
CDBD1040-HF Thru CDBD10200-HF	TO-263/D2PAK								
CDBD2040-HF Thru. CDBD20200-HF	TO-263/D2PAK								
CDBD3060-G	TO-263/D2PAK								
Reason for Discontinuance :									
Due to low demand, the part listed below will be discontinued.									
Alternative Products :									
Please contact sales person or manufacturer's representative.									
Effective Date : Feb 10, 2022									
R&D Dept. Signature :	QA Dept. Signature :								
									

**PDN210803**

CDBD1040-HF

CDBD1060-HF

CDBD10100-HF

CDBD10150-HF

CDBD10200-HF

CDBD2040-HF

CDBD2045-HF

CDBD2060-HF

CDBD20100-HF

CDBD20150-HF

CDBD20200-HF

CDBD3060-G