



TDK-Lambda Americas Inc.
401 Mile of Cars Way, Suite 325
National City, CA 91950 USA
<https://us.tdk-lambda.com/lp>

January 6, 2020

Re: Obsolescence of JWT75 and JWT100 /B and /C option codes

Dear Valued Distributor,

TDK-Lambda has received an EOL notice for the Molex connector used on the JWT75 and JWT100 /B and /C option code models. Without a suitable alternative component, we are offering a last time buy for these products. The alternative will be the standard terminal block version which will require a wiring harness change. Please see page 2 for the affected models and suggested alternatives.

TDK-Lambda recognizes that as a Distributor, you have past or current customers of these products, and may require additional units until substitution testing is complete or for service spares. We are offering a last time buy opportunity until May 1st, 2020, with a last time ship date of April 30th 2021. Please understand that these orders would be non-cancelable and non-returnable and cannot be counted towards future stock rotations.

Please contact our technical support for additional information. 1-800-526-2324 or email lambda.techsupport@us.tdk-lambda.com

A handwritten signature in black ink, appearing to read "Tom Tillman", enclosed within a hand-drawn oval.

Tom Tillman
Director of Marketing



TDK-Lambda Americas Inc.
401 Mile of Cars Way, Suite 325
National City, CA 91950 USA
<https://us.tdk-lambda.com/lp>

Model	Replacement	Notes
JWT755FF/B	JWT755FF	Cable harness change required
JWT755FF/RB	JWT755FF/R	Cable harness change required
JWT755FF/C	JWT755FF	Cable harness change required
JWT755FF/RC	JWT755FF/R	Cable harness change required
JWT75525/B	JWT75525	Cable harness change required
JWT75525/RB	JWT75525/R	Cable harness change required
JWT75525/C	JWT75525	Cable harness change required
JWT75525/RC	JWT75525/R	Cable harness change required
JWT75522/B	JWT75522	Cable harness change required
JWT75522/RB	JWT75522/R	Cable harness change required
JWT75522/C	JWT75522	Cable harness change required
JWT75522/RC	JWT75522/R	Cable harness change required
JWT1005FF/B	JWT1005FF	Cable harness change required
JWT1005FF/RB	JWT1005FF/R	Cable harness change required
JWT1005FF/C	JWT1005FF	Cable harness change required
JWT1005FF/RC	JWT1005FF/R	Cable harness change required
JWT100525/B	JWT100525	Cable harness change required
JWT100525/RB	JWT100525/R	Cable harness change required
JWT100525/C	JWT100525	Cable harness change required
JWT100525/RC	JWT100525/R	Cable harness change required
JWT100522/B	JWT100522	Cable harness change required
JWT100522/RB	JWT100522/R	Cable harness change required
JWT100522/C	JWT100522	Cable harness change required
JWT100522/RC	JWT100522/R	Cable harness change required