

Skywire[®] LTE

NL-SW-LTE-S7588-V-B

Product Change Notification

NimbeLink Corp

Updated: April 2018



© NimbeLink Corp. 2018. All rights reserved.

NimbeLink Corp. provides this documentation in support of its products for the internal use of its current and prospective customers. The publication of this document does not create any other right or license in any party to use any content contained in or referred to in this document and any modification or redistribution of this document is not permitted.

While efforts are made to ensure accuracy, typographical and other errors may exist in this document. NimbeLink reserves the right to modify or discontinue its products and to modify this and any other product documentation at any time.

All NimbeLink products are sold subject to its published Terms and Conditions, subject to any separate terms agreed with its customers. No warranty of any type is extended by publication of this documentation, including, but not limited to, implied warranties of merchantability, fitness for a particular purpose and non-infringement.

NimbeLink and Skywire are registered trademarks of NimbeLink Corp. All trademarks, service marks and similar designations referenced in this document are the property of their respective owners.

Table of Contents

Table of Contents	2
Introduction	3
Migration Overview	3
Contact	4

1. Introduction

Over their lifetime, Skywire® modems may incur several firmware updates provided from the module manufacturers. These updates will improve communication, fix bugs, and add features to the module and resulting modem functionality. NimbeLink will stay current with the latest firmware releases. It is recommended that customers also test and apply these new firmware versions when they become available.

The NL-SW-LTE-S7588-V Skywire modem originally shipped with firmware version "RHL75xx.V.3.6.151600.201606082134.x7160_1".

Cellular network updates to support new features in 3GPP TS 36.331, Version 14.4.0 and above may prevent the NL-SW-LTE-S7588-V from reliably connecting to the network. Customers should immediately update the firmware on their devices to firmware "RHL75xx.V.3.15.151600.201802071640.x7160_1" to ensure the devices continue to operate on the network.

Due to this new firmware update being required in order to maintain network connectivity, NimbeLink can no longer offer any downgrade path to older firmwares, nor new orders of older firmware versions at this time.

The NL-SW-LTE-S7588-V will no longer be manufactured by NimbeLink and all future orders should move to the NL-SW-LTE-S7588-V-B Skywire modem which ships with firmware version "RHL75xx.V.3.15.151600.201802071640.x7160_1".

All new and existing customers should move to the NL-SW-LTE-S7588-V-B for currently-deployed units and future purchase.

2. Migration Overview

All new orders should use part number NL-SW-LTE-S7588-V-B which is specific to the newest version of firmware "RHL75xx.V.3.15.151600.201802071640.x7160_1".

Summary of changes include:

- Numerous AT command fixes
- Numerous fixes to NCM mode
- Numerous AirPrime fixes
- Random Shutdown - (B66SIB5 message decoding)

For a complete list of changes, please see the following release notes (registration with Sierra Wireless Source required):

Firmware V.3.13 Customer Release Note -

https://source.sierrawireless.com/resources/airprime/software/release_notes/airprime_hl7588_firmware_v_3_13_customer_release_note/

Firmware V.3.15 Customer Release Note -

https://source.sierrawireless.com/resources/airprime/software/release_notes/airprime_hl7588_firmware_v_3_15_customer_release_note/

Updated documentation for firmware version "RHL75xx.V.3.15.151600.201802071640.x7160_1" can be found on the product page here: <https://www.nimbelink.com/4g-lte/#docs>

Customers with existing NL-SW-LTE-S7588-V parts can upgrade to the NL-SW-LTE-S7588-V-B firmware. Options for updating the firmware are outlined in Application Note 30270: Skywire LTE CAT4 Firmware Update Procedure:

https://nimbelink.com/Documentation/Skywire/4G_LTE_Cat_4/30270_NL-SW-LTE-S7588_Firmware-Update-AppNote.pdf

3. Contact

For further information please contact NimbeLink at:

Sales@NimbeLink.com