



MOQ CHANGE NOTICE

18 March 2021


Dear Customer,

We are sorry to inform you that our suppliers have increased the Minimum Order Quantity (MOQ) for certain raw materials that are required to manufacture the part(s) listed below. As a result, effective immediately, we are forced to increase our MOQ. Any OPEN PO's will not be able to be filled unless revised for the new MOQ below.

| Part # | Old MOQ | New MOQ | Replacement Available |
|---------------|---------|---------|------------------------------|
| Z4KH2B0470652 | 1K | 50K | Yes, Z4KH2B0470653N , MOQ 2K |
| JQ24-35F580C | 500 | 5K | No |
| JQ24-35K270B | 500 | 5K | No |
| JP08-74D160A | 500 | 5K | No |
| JP10-35C270 | 500 | 5K | No |
| JP16-70E310 | 500 | 5K | No |

Regards,

For and on behalf of
JINLONG MACHINERY (HK) LIMITED


.....
Authorized Signature(s)

Charles Tepper
VP Sales Engineering