







PCN Number:	20230324000.0			PCN Date:	March 28, 2023				
Title:	Device Topside Marking Change for select devices								
Customer Contact:	PCN Manager	Dept:	Quality Services						
Change Type:									
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design	<input type="checkbox"/>	Wafer Bump Site				
<input type="checkbox"/>	Assembly Process	<input type="checkbox"/>	Data Sheet	<input type="checkbox"/>	Wafer Bump Material				
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change	<input type="checkbox"/>	Wafer Bump Process				
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site	<input type="checkbox"/>	Wafer Fab Site				
<input checked="" type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process	<input type="checkbox"/>	Wafer Fab Materials				
				<input type="checkbox"/>	Wafer Fab Process				
PCN Details									
Description of Change:									
Texas Instruments Incorporated is announcing an information only notification for a device topside marking change for select devices.									
Reason for Change:									
Continuity of Supply									
Anticipated impact on Form, Fit, Function, Quality or Reliability (positive / negative):									
None									
Changes to product identification resulting from this PCN:									
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr style="background-color: #00A0C0; color: white;"> <th style="width: 50%; padding: 5px;">Current</th> <th style="width: 50%; padding: 5px;">Proposed</th> </tr> </thead> <tbody> <tr> <td style="text-align: center; padding: 10px;">  <p style="font-size: small; margin-top: 5px;"> TI = TI LETTERS YM = YEAR MONTH DATE CODE LLLL = ASSEMBLY LOT CODE S = ASSEMBLY SITE CODE # = DIE REVISION O = PIN1 ID </p> </td> <td style="text-align: center; padding: 10px;">  <p style="font-size: small; margin-top: 5px;"> TI = TI LETTERS YM = YEAR MONTH DATE CODE LLLL = ASSEMBLY LOT CODE S = ASSEMBLY SITE CODE O = PIN1 ID </p> </td> </tr> </tbody> </table>						Current	Proposed	 <p style="font-size: small; margin-top: 5px;"> TI = TI LETTERS YM = YEAR MONTH DATE CODE LLLL = ASSEMBLY LOT CODE S = ASSEMBLY SITE CODE # = DIE REVISION O = PIN1 ID </p>	 <p style="font-size: small; margin-top: 5px;"> TI = TI LETTERS YM = YEAR MONTH DATE CODE LLLL = ASSEMBLY LOT CODE S = ASSEMBLY SITE CODE O = PIN1 ID </p>
Current	Proposed								
 <p style="font-size: small; margin-top: 5px;"> TI = TI LETTERS YM = YEAR MONTH DATE CODE LLLL = ASSEMBLY LOT CODE S = ASSEMBLY SITE CODE # = DIE REVISION O = PIN1 ID </p>	 <p style="font-size: small; margin-top: 5px;"> TI = TI LETTERS YM = YEAR MONTH DATE CODE LLLL = ASSEMBLY LOT CODE S = ASSEMBLY SITE CODE O = PIN1 ID </p>								
Product Affected:									
DRV8311HRRWR	DRV8311PRRWR	DRV8311SRRWR	PDRV8311SRRWR						

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com