


Product Obsolescence Memo

INDUCTIVE COMPONENTS



January, 2015

Bourns® Model 9310 Series Molded Axial Inductor to be Discontinued

Bourns will be discontinuing the Bourns® [Model 9310 Series](#) Molded Axial Inductor due to a lack of sales volume and diminishing demand. Regrettably, no replacement part numbers are available at this time.

Obsolete Part Numbers			
9310-00-RC	9310-12-RC	9310-26-RC	9310-40-RC
9310-00-TR-RC	9310-12-TR-RC	9310-26-TR-RC	9310-40-TR-RC
9310-02-RC	9310-14-RC	9310-28-RC	9310-42-RC
9310-02-TR-RC	9310-14-TR-RC	9310-28-TR-RC	9310-42-TR-RC
9310-04-RC	9310-16-RC	9310-30-RC	9310-44-RC
9310-04-TR-RC	9310-16-TR-RC	9310-30-TR-RC	9310-44-TR-RC
9310-06-RC	9310-18-RC	9310-32-RC	9310-46-RC
9310-06-TR-RC	9310-18-TR-RC	9310-32-TR-RC	9310-46-TR-RC
9310-07-RC	9310-20-RC	9310-34-RC	9310-48-RC
9310-07-TR-RC	9310-20-TR-RC	9310-34-TR-RC	9310-48-TR-RC
9310-08-RC	9310-22-RC	9310-36-RC	9310-50-RC
9310-08-TR-RC	9310-22-TR-RC	9310-36-TR-RC	9310-50-TR-RC
9310-10-RC	9310-24-RC	9310-38-RC	9310-52-RC
9310-10-TR-RC	9310-24-TR-RC	9310-38-TR-RC	9310-52-TR-RC

Please plan for the following deadlines:

Last time buy date: July 20, 2015

Last time ship date: January 16, 2016

Should you have any questions or need additional information, please feel free to contact [Customer Service/Inside Sales](#).