

PRODUCT DISCONTINUATION

PD_043_07 !! UPDATE !!

Reason: low demand

Original: Product Discontinuation PD_043_07 dated 08. May 2007

Update: [New replacement product for discontinued BB 640 E7786 \(see page 2\)](#)

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Function	Package	Device	Ordering Code	Function	Package
BA 592 E6543	SP000010145	RF Diode	SOD323	BA 592 E6327	SP000010141	RF Diode	SOD323
BA 595 B6327	SP000095921	RF Diode	SOD323	BA 595 E6327	SP000010146	RF Diode	SOD323
BA 595 E6393	SP000010147	RF Diode	SOD323	BA 595 E6327	SP000010146	RF Diode	SOD323
BAR 63-03W E6433	SP000010173	RF Diode	SOD323	BAR 63-03W E6327	SP000010172	RF Diode	SOD323
BAT 60A E6393	SP000010295	Schottky Diode	SOD323	BAT 60A E6327	SP000010294	Schottky Diode	SOD323
BAT 60B E6433	SP000010297	Schottky Diode	SOD323	BAT 60B E6327	SP000010296	Schottky Diode	SOD323
BB 439 E7263	SP000010373	RF Varactor Diode	SOD323	BB 439 E6327	SP000010372	RF Varactor Diode	SOD323
BB 535 E6540	SP000010379	RF Varactor Diode	SOD323	BB 535 E7904	SP000010375	RF Varactor Diode	SOD323
BB 535 E6700	SP000062291	RF Varactor Diode	SOD323	BB 535 E7904	SP000010375	RF Varactor Diode	SOD323
BB 535 E7989	SP000010378	RF Varactor Diode	SOD323	BB 535 E7904	SP000010375	RF Varactor Diode	SOD323

Last order:	15. November 2007
Last delivery:	15. May 2008

PRODUCT DISCONTINUATION



PD_043_07 !! UPDATE !!

Reason: low demand

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Function	Package	Device	Ordering Code	Function	Package
BB 545 E7906	SP000010386	RF Varactor Diode	SOD323	BB 545 E7904	SP000010383	RF Varactor Diode	SOD323
BB 545 E7908	SP000010384	RF Varactor Diode	SOD323	BB 545 E7904	SP000010383	RF Varactor Diode	SOD323
BB 545 E7909	SP000010385	RF Varactor Diode	SOD323	BB 545 E7907	SP000010387	RF Varactor Diode	SOD323
BB 639 E7906	SP000010403	RF Varactor Diode	SOD323	BB639 E7904	SP000010401	RF Varactor Diode	SOD323
BB 639 E7908	SP000010402	RF Varactor Diode	SOD323	BB 639 E7904	SP000010401	RF Varactor Diode	SOD323
BB 639C E6541	SP000010395	RF Varactor Diode	SOD323	BB 639C E7904	SP000010396	RF Varactor Diode	SOD323
BB 639C E7906	SP000010397	RF Varactor Diode	SOD323	BB 639C E7904	SP000010396	RF Varactor Diode	SOD323
BB 640 E7786	SP000055846	RF Varactor Diode	SOD323	BB 644 E7904 BB 640 E6327	SP000010411 SP000010406	RF Varactor Diode	SOD323
BB 644 E7840	SP000010410	RF Varactor Diode	SOD323	BB 644 E7904	SP000010411	RF Varactor Diode	SOD323
BB 669 E6770	SP000010421	RF Varactor Diode	SOD323	BB 669 E7904	SP000010419	RF Varactor Diode	SOD323

Last order:	15. November 2007
Last delivery:	15. May 2008

PRODUCT DISCONTINUATION



PD_043_07 !! UPDATE !!

Reason: low demand

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Function	Package	Device	Ordering Code	Function	Package
BB 831 E6327	SP000012249	RF Varactor Diode	SOD323	BB 831 E7904	SP000012250	RF Varactor Diode	SOD323
BB 831 E7906	SP000012251	RF Varactor Diode	SOD323	BB 831 E7904	SP000012250	RF Varactor Diode	SOD323
BB 833 E6433	SP000010438	RF Varactor Diode	SOD323	BB 833 E6327	SP000010437	RF Varactor Diode	SOD323
BB 833 E7263	SP000016788	RF Varactor Diode	SOD323	BB 833 E6327	SP000010437	RF Varactor Diode	SOD323
SD 197 B6552	SP000095910	RF Varactor Diode	SOD323	SD 197 E6552	SP000010382	RF Varactor Diode	SOD323
SD 198 B6553	SP000095911	RF Varactor Diode	SOD323	SD 198 E6553	SP000010404	RF Varactor Diode	SOD323
SD 199 B6327	SP000095912	RF Varactor Diode	SOD323	SD 199 E6327	SP000010409	RF Varactor Diode	SOD323

Last order:	15. November 2007
Last delivery:	15. May 2008