

Light is OSRAM


Product Or Individual Q-Code Discontinuation (acc. JEDEC J-STD-048)  
OS-PDN-2022-026

01 March 2022

---

Last order: 01 September 2022  
Last delivery: 01 March 2023

---



Please direct your feedback to your local Sales office.

| DISCONTINUED                      |               |                |  | NEW (REPLACEMENT)                 |                         |                |
|-----------------------------------|---------------|----------------|--|-----------------------------------|-------------------------|----------------|
| Device                            | Ordering Code | Brand          | Reason for discontinuation                     | Device                            | Datasheet Ordering Code | Brand          |
| GB DASPA2.13-EPER-24-LM-100-R18   | Q65112A5513   | OSCONIQ P 2226 | No fallout on EP bin.                          | GB DASPA2.13-EQFQ-24-LM-100-R18   | Q65112A7920             | OSCONIQ P 2226 |
| GB DASPA2.13-EPES-24-LM-100-R18   | Q65112A7465   | OSCONIQ P 2226 | No fallout on EP bin.                          | GB DASPA2.13-EQFQ-24-LM-100-R18   | Q65112A7920             | OSCONIQ P 2226 |
| GD DASPA2.14-RMRO-25-1-100-R18    | Q65112A3338   | OSCONIQ P 2226 | No fallout on RM bin.                          | GD DASPA2.14-ROSK-24-LM-100-R18   | Q65112A3441             | OSCONIQ P 2226 |
| GR DASPA2.23-GRGT-24-FH-100-R18   | Q65112A3465   | OSCONIQ P 2226 | Able to be cater by replacement Ordering Code. | GR DASPA2.23-GPGU-24-FH-100-R18   | Q65112A7464             | OSCONIQ P 2226 |
| GW DASPA2.UC-HSHU-5C8G-KM-100-R18 | Q65112A3335   | OSCONIQ P 2226 | No fallout on HS bin.                          | GW DASPA2.UC-HTJR-5C8G-KM-100-R18 | Q65112A8367             | OSCONIQ P 2226 |
| GW DASPA2.UC-HSHU-GPHR-KM-100-R18 | Q65112A3337   | OSCONIQ P 2226 | No fallout on HS Bin & no demand or orders.    | GW DASPA2.UC-HTJR-GPHR-KM-100-R18 | Q65112A8374             | OSCONIQ P 2226 |