

END OF LIFE (EOL) NOTIFICATION

EOL Number:	WE163703
Notification Subject:	End of Life (EOL) of MSL385, MSL1060, MSL1061, MSL1064, MSL2010, MSL2021, MSL2023, MSL2166, MSL2024, MSL2041, MSL2100, MSL2160, MSL2164, MSL3080, MSL4164, MSL3082, MSL3085, MSL3086, MSL3088, MSL3162, MSL3163 and MSL3164 device families
Issue Date:	September 29, 2016
PCN Status:	End of Life (EOL) notification
Microchip/Atmel Parts Affected:	Please open the attachments found in the attachments field below labeled as PCN_#_Affected_CPN. NOTE: For your convenience Microchip includes identical files in two formats (.pdf and .xls).
EOL Description:	The MSL385, MSL1060, MSL1061, MSL1064, MSL2010, MSL2021, MSL2023, MSL2166, MSL2024, MSL2041, MSL2100, MSL2160, MSL2164, MSL3080, MSL4164, MSL3082, MSL3085, MSL3086, MSL3088, MSL3162, MSL3163 and MSL3164 device families will be moving to End of Life (EOL) status effective today. These device families will no longer be offered after the LTB and LTS dates listed below. Please review the attached parts affected list for details about replacement parts if applicable.
Reason for EOL:	No longer have manufacturing support for the CPN(s) listed in the attachment.
Last Time Buy Date (LTB):	March 29, 2017
Last Time Ship Date (LTS):	September 29, 2017
Revision History:	September 29, 2016: Issued the EOL Notification



Please contact your local [Microchip](#) or [Atmel](#) Sales Office or Distributor with questions or concerns regarding this notification.

Attention Distributors: The products listed in this notification have been, or soon will be, declared obsolete. Distributors are required to provide Atmel with the distributor's current inventory of the obsolete product within 30 days of the earlier of the date of this notice or the date that the products were added to the obsolete tab in the distributor price schedule. Distributors may be entitled to return some or all of the obsolete products in accordance with the requirements of the applicable distribution agreement.

WE163703 - EOL of MSL385,MSL1060,MSL1061,MSL1064,MSL2010,MSL2021,MSL2023,MSL2166,MSL2024,MSL2041,MSL2100,MSL2160,MSL2164,MSL3080,MSL4164,MSL3082,MSL3085,MSL3086,MSL3088,MSL3162,MSL3163,MSL3164 device families

Affected Catalog Part Numbers (CPN)

PCN_WE163703	
Current Part Number	Recommended Replacement
MSL3085BT	Contact Your Local Sales Office
MSL1060AW	Contact Your Local Sales Office
MSL1060AW-R	Contact Your Local Sales Office
MSL1061AV	Contact Your Local Sales Office
MSL1061AV-R	Contact Your Local Sales Office
MSL1064AW	Contact Your Local Sales Office
MSL1064-TC	Contact Your Local Sales Office
MSL1064AW-R	Contact Your Local Sales Office
MSL2010-IN	Contact Your Local Sales Office
MSL2010-INR	Contact Your Local Sales Office
MSL2021-IN	Contact Your Local Sales Office
MSL2021-INR	Contact Your Local Sales Office
MSL2023-IN	Contact Your Local Sales Office
MSL2166-DU	Contact Your Local Sales Office
MSL2166-DUR	Contact Your Local Sales Office
MSL2023-INR	Contact Your Local Sales Office
MSL2024-IN	Contact Your Local Sales Office
MSL2024-INR	Contact Your Local Sales Office
MSL2041GU	Contact Your Local Sales Office
MSL2041GU-R	Contact Your Local Sales Office
MSL2100BR	Contact Your Local Sales Office
MSL2041GU-R	Contact Your Local Sales Office
MSL2100BR	Contact Your Local Sales Office
MSL2100BR-R	Contact Your Local Sales Office
MSL2160DQ	Contact Your Local Sales Office
MSL2160DQ-R	Contact Your Local Sales Office
MSL2164-DU	Contact Your Local Sales Office
MSL2164-DUR	Contact Your Local Sales Office
MSL3080-IU	Contact Your Local Sales Office
MSL3080-IUR	Contact Your Local Sales Office
MSL4164BT	Contact Your Local Sales Office
MSL4164BT-R	Contact Your Local Sales Office
MSL3082CS	Contact Your Local Sales Office
MSL3082CS-R	Contact Your Local Sales Office
MSL3085BT-R	Contact Your Local Sales Office
MSL3086-IU	Contact Your Local Sales Office
MSL3086-IUR	Contact Your Local Sales Office
MSL3088-IU	Contact Your Local Sales Office
MSL3088-IUR	Contact Your Local Sales Office
MSL3162BT	Contact Your Local Sales Office
MSL3162BT-R	Contact Your Local Sales Office
MSL3163BT	Contact Your Local Sales Office
MSL3163BT-R	Contact Your Local Sales Office

WE163703 - EOL of MSL385,MSL1060,MSL1061,MSL1064,MSL2010,MSL2021,MSL2023,MSL2166,MSL2024,MSL2041,MSL2100,MSL2160,MSL2164,MSL3080,MSL4164,MSL3082,MSL3085,MSL3086,MSL3088,MSL3162,MSL3163,MSL3164 device families

Affected Catalog Part Numbers (CPN)

PCN_WE163703	
Current Part Number	Recommended Replacement
MSL3164BT	Contact Your Local Sales Office
MSL3164BT-R	Contact Your Local Sales Office