

Product Advisor (PA)

Subject: Datasheet specification correction for listed Intersil ISL98608IIH* products

Publication Date: 10/2/2017

Effective Date: 10/2/2017

Revision Description:

Initial Release

Description of Change:

Datasheet has been corrected to reflect default value of Register in Electrical Specifications.

Parameter	Description	Test Condition	
		From	To
V _{VBSTA}	VBST Output Voltage Accuracy	Register 0x06 = 0x0 5	Register 0x06 = 0x0 0
I _{VBSTO}	VBST Output Current	Register 0x06 = 0x0 5	Register 0x06 = 0x0 0
V _{ACC_VN}	VN Output Voltage Accuracy	Register 0x06 = 0x0 5	Register 0x06 = 0x0 0
t _{SS_VN}	VN Soft-Start Time	Register 0x05 b ₇ = 1	Register 0x05 b ₇ = 0
V _{ACC_VP}	VP Output Voltage Accuracy	Register 0x06 = 0x0 5	Register 0x06 = 0x0 0
t _{SS_VP}	VP Soft-Start Time	Register 0x05 b ₇ = 1	Register 0x05 b ₇ = 0

Affected Product List

ISL98608IIHZ-T

Reason for Change:

This is a correction to the datasheet only. The default value of Register shown in the electrical specification were in error and has been updated to reflect the actual default value. For an updated datasheet, please contact your local sales representative or the Intersil Corporate Line, 1-888-468-3774, for our Central Applications Department.

Impact on fit, form, function, quality & reliability:

The change will have no impact on the form, fit, function, quality, reliability and environmental compliance of the devices.

Product Identification:

Product affected by this change is identifiable via Intersil's internal traceability system.

Qualification status: Not Applicable

Sample availability: 10/2/2017

Device material declaration: Available upon request

Questions or requests pertaining to this change notice, including additional data or samples, must be sent to Intersil within 30 days of the publication date.

For additional information regarding this notice, please contact your regional change coordinator (below)			
Americas: PCN-US@INTERSIL.COM	Europe: PCN-EU@INTERSIL.COM	Japan: PCN-JP@INTERSIL.COM	Asia Pac: PCN-APAC@INTERSIL.COM