



Product Discontinuation Notice: HN Series Relay Terminal Sockets

PDN.PG0003.06.11.2019

06.11.2019

Effective Date: Immediate

Last Time Buy Date: September 30, 2019

Last Eligible Ship Date: December 31, 2019

Discontinuation Details:

Before				
Item	Specifications			
Type	AHNA11	AHNA11P	AHNA21	AHNA21P
Contact arrangement	1 Form C		2 Form C	
Dielectric strength (Initial)	Between contact and coil		5,000Vrms for 1min. (Detection current: 10mA)	
Max. continuous current	16A	10A	5A	

After			
Item	Specifications		
Type	AHNA11K		AHNA21K
Contact arrangement	1 Form C		2 Form C
Dielectric strength (Initial)	Between contact and coil		4,000Vrms for 1min. (Detection current: 10mA)
Max. continuous current	10A		5A

Suggested Replacement:

Discontinued items	
No. of pole	Part number
1 pole	AHNA11
	AHNA11P
2 pole	AHNA21
	AHNA21P

Replacement items	
No. of pole	Part number
1 pole	AHNA11K
2 pole	AHNA21K

Affected Part Numbers: See Attached.

Datasheets: See Attached.

Notes: Panasonic announces the discontinuation and recommended replacement of certain HN Series Relay Terminal Socket part numbers. This will allow for more efficient product lineup integration.

Panasonic PDN.PG0003.06.11.2019 Affected Parts

Discontinued Part List

AHNA11
AHNA11P
AHNA21
AHNA21P

Recommended Replacement

AHNA11K
AHNA11K
AHNA21K
AHNA21K