



Product Change Notification

TE Connectivity

Product Change Notification: P-20-018876

PCN Date: 03-APR-20

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Notification of packaging changes for -STK tubing products

Description of Changes

This is a notification informing TE Connectivity customers that the packaging boxes used for the tubing -STK products will be changing.

Other attachments:

- [New Stick Boxes](#)
- [PCN - Changes to Stick boxes](#)
- [Stick parts for box changes](#)

Reason for Changes:

Product improvement. We are moving to a more robust design that will give better protection to the tubing products during transportation. The boxes are moving from a square profile to a rectangular one with different cardboard and latching method. We will be transitioning boxes as existing packaging is consumed so not all product will change at the same time.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	06-APR-2020
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	31-OCT-2020

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
035377P004	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			
063725P022	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
085193P003	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			
121397P024	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
130599P006	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
193197P004	NO			"4-1191401-7", "ES1000-NO.1-C1-X-STK"			
206247P038	NO			"2-1191495-7", "SCT-NO.4-E2-0-STK"			
2951512003	NO			"DWP-125-1/4-0-STK", "1448670-1", "16-0151"			
363884-000	NO			"1-1199654-7", "FL2500-NO.3-J1-0-STK"			
4429522003	NO			"6-1193329-8", "DWP-125-1/8-0-STK"			
5052842057	NO			"3-1193821-9", "RNF-100-3/64-BK-STK"			
5052892107	NO			"5-1193823-3", "RNF-100-1/16-BK-STK", "16-0112"			
5052942218	NO			"1-1193827-7", "RNF-100-3/32-BK-STK"			
5052992172	NO			"1-1193833-7", "RNF-100-1/8-BK-STK"			
5053042176	NO			"8-1193838-6", "RNF-100-3/16-BK-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5053092267	NO			"2-1193845-2", "RNF-100-1/4-BK-STK"			
5053142385	NO			"2-1193853-6", "RNF-100-3/8-BK-STK"			
5053192266	NO			"1-1193862-2", "RNF-100-1/2-BK-STK"			
5053242179	NO			"1-1193869-9", "RNF-100-3/4-BK-STK"			
5053292160	NO			"3-1193876-7", "RNF-100-1-BK-STK"			
5053342101	NO			"2-1193882-6", "RNF-100-1-1/2-BK-STK"			
5053392064	NO			"7-1193885-6", "RNF-100-2-BK-STK"			
5053442033	NO			"5-1193887-7", "RNF-100-3-BK-STK"			
5067592001	NO			"5-1193934-3", "TAT-125-3/4-2-STK"			
5070022040	NO			"2-1193959-4", "RNF-100-1/16-CL-STK"			
5070082131	NO			"2-1193965-3", "RNF-100-1/2-CL-STK"			
5070122027	NO			"5-1193969-9", "RNF-100-2-CL-STK"			
5076682002	NO			"DWP-125-3/4-0-STK", "1448810-3"			
5233452001	NO			"6-1194111-2", "DWP-125-3/8-2-STK"			
537637P041	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			
543633P064	NO			"5-1194264-0", "SCT-NO.1-E6-0-STK"			
5500042003	NO			"5-1194328-8", "SCL-3/8-2-STK"			
5500102028	NO			"2-1194329-8", "SCL-1/8-0-STK", "SCL-1/8-0-STK"			
5500192011	NO			"5-1194330-0", "SCL-3/8-0-STK", "SCL-3/8-0-STK"			
5500282020	NO			"6-1194331-8", "SCL-3/16-0-STK", "SCL-3/16-0-STK"			
5500312016	NO			"8-1194332-3", "SCL-1/2-0-STK", "SCL-1/2-0-STK"			
5500692005	NO			"TAT-125-1/4-0-STK", "1324239-2"			
5500702004	NO			"7-1194335-4", "TAT-125-3/8-0-STK"			
5500712011	NO			"1194336-2", "TAT-125-1/2-0-STK"			
5500722008	NO			"4-1194336-1", "TAT-125-3/4-0-STK", "1406806"			
5500732014	NO			"7-1194336-1", "TAT-125-1-0-STK"			
5500742015	NO			"1194337-3", "TAT-125-1-1/2-0-STK"			
5500752003	NO			"2-1194337-2", "TAT-125-2-0-STK"			
5500762006	NO			"4-1194337-1", "TAT-125-3-0-STK"			
5500962003	NO			"3-1194338-0", "TAT-125-1/8-0-STK"			
5500982001	NO			"3-1194338-9", "TAT-125-3/16-0-STK"			
5501052008	NO			"1-1194339-0", "SCL-3/4-0-STK", "SCL-3/4-0-STK"			
5501062005	NO			"7-1194339-5", "SCL-1-0-STK", "SCL-1-0-STK"			
5501092019	NO			"3-1194340-1", "SCL-1/4-0-STK", "SCL-1/4-0-STK"			
576105P004	NO			"7-1194570-9", "ES1000-NO.2-B9-X-STK"			
581913P020	NO			"1-1194610-0", "QS1500-NO.2-F6-0-STK"			
5978892002	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"4-1194727-5", "DWP-125-1-1/2-0-STK"			
6009112002	NO			"7-1194754-0", "DWP-125-3/16-0-STK"			
607381P046	NO			"5-1194804-3", "SCT-NO.2-E5-0-STK"			
636901P014	NO			"8-1195035-6", "QS1500-NO.3-F7-0-STK"			
6465212003	NO			"114517-01", "1448193-1", "DWP-125-1/2-0-STK", "16-0149"			
7580142002	NO			"DWP-125-3/8-0-STK", "1448852-3", "16-0150"			
774185P009	NO			"8-1196028-7", "QS1500-NO.1-F5-0-STK"			
829131P021	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
895231P008	NO			"5-1196961-1", "SCT-NO.0-E8-0-STK"			
9170152001	NO			"1-1197118-5", "DWP-125-2-0-STK"			
9346692002	NO			"2-1197242-1", "DWP-125-1-0-STK"			
958133P007	NO			"1197417-6", "QS1500-NO.4-F8-0-STK"			
CB0929-000	NO			"FL2500-NO.0-I7-0-STK"			
CV37322001	NO			"RW-175-E-1-X-STK", "3-1899810-8"			
CZ0181-000	NO			"SCT-NO.5-Z4-0-STK"			
D20444-000	NO			"1-1199653-5", "FL2500-NO.1-I8-0-STK"			
E43149-000	NO			"3-1199653-6", "FL2500-NO.2-I9-0-STK"			
E95757-000	NO			"4-1199653-3", "FL2500-NO.4-J2-0-STK"			
EH2288-000	NO			"DWFR-3/1-0-STK"			
EH2289-000	NO			"DWFR-6/2-0-STK"			
EH2290-000	NO			"DWFR-9/3-0-STK"			
EH2291-000	NO			"DWFR-12/4-0-STK"			
EH2292-000	NO			"DWFR-19/6-0-STK"			
EH2293-000	NO			"DWFR-24/8-0-STK"			
EH2294-000	NO			"DWFR-40/13-0-STK"			
EH2295-000	NO			"DWFR-4/1-0-STK"			
EH2296-000	NO			"DWFR-8/2-0-STK"			
EH2297-000	NO			"DWFR-12/3-0-STK"			
EH2298-000	NO			"DWFR-16/4-0-STK"			
EH2299-000	NO			"DWFR-24/6-0-STK"			
EH2300-000	NO			"DWFR-32/8-0-STK"			
EH2301-000	NO			"DWFR-52/13-0-STK"			
EM63332001	NO			"BATTU-12.7/6.1-A1-3-STK"			
EM63392001	NO			"BATTU-20.1/8.9-A1-3-STK"			
EM63602001	NO			"BATTU-25.4/12.7-A1-3-STK"			
EM63952001	NO			"BATTU-12.7/6.1-A1-4-STK"			
EM64322001	NO			"BATTU-20.1/8.9-A1-4-STK"			
EM64392001	NO			"BATTU-25.4/12.7-A1-4-STK"			
NB07072001	NO			"BATTU-12.7/6.1-A1-0-STK", "8-1899840-5"			
NB07092001	NO			"BATTU-12.7/6.1-A1-2-STK", "8-1899840-3"			
NB07112001	NO			"BATTU-20.1/8.9-A1-0-STK", "8-1899840-1"			
NB07132001	NO			"BATTU-20.1/8.9-A1-2-STK", "7-1899840-9"			
NB07152001	NO			"BATTU-25.4/12.7-A1-0-STK", "7-1899840-7"			
NB07172001	NO			"BATTU-25.4/12.7-A1-2-STK", "7-1899840-6"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
035377P004	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			
063725P022	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
085193P003	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			
121397P024	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
130599P006	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
193197P004	NO			"4-1191401-7", "ES1000-NO.1-C1-X-STK"			
206247P038	NO			"2-1191495-7", "SCT-NO.4-E2-0-STK"			
2951512003	NO			"DWP-125-1/4-0-STK", "1448670-1", "16-0151"			
363884-000	NO			"1-1199654-7", "FL2500-NO.3-J1-0-STK"			
4429522003	NO			"6-1193329-8", "DWP-125-1/8-0-STK"			
5052842057	NO			"3-1193821-9", "RNF-100-3/64-BK-STK"			
5052892107	NO			"5-1193823-3", "RNF-100-1/16-BK-STK", "16-0112"			
5052942218	NO			"1-1193827-7", "RNF-100-3/32-BK-STK"			
5052992172	NO			"1-1193833-7", "RNF-100-1/8-BK-STK"			
5053042176	NO			"8-1193838-6", "RNF-100-3/16-BK-STK"			
5053092267	NO			"2-1193845-2", "RNF-100-1/4-BK-STK"			
5053142385	NO			"2-1193853-6", "RNF-100-3/8-BK-STK"			
5053192266	NO			"1-1193862-2", "RNF-100-1/2-BK-STK"			
5053242179	NO			"1-1193869-9", "RNF-100-3/4-BK-STK"			
5053292160	NO			"3-1193876-7", "RNF-100-1-BK-STK"			
5053392064	NO			"7-1193885-6", "RNF-100-2-BK-STK"			
5053442033	NO			"5-1193887-7", "RNF-100-3-BK-STK"			
5070022040	NO			"2-1193959-4", "RNF-100-1/16-CL-STK"			
5070082131	NO			"2-1193965-3", "RNF-100-1/2-CL-STK"			
5070122027	NO			"5-1193969-9", "RNF-100-2-CL-STK"			
5076682002	NO			"DWP-125-3/4-0-STK", "1448810-3"			
537637P041	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			
543633P064	NO			"5-1194264-0", "SCT-NO.1-E6-0-STK"			
5500102028	NO			"2-1194329-8", "SCL-1/8-0-STK", "SCL-1/8-0-STK"			
5500312016	NO			"8-1194332-3", "SCL-1/2-0-STK", "SCL-1/2-0-STK"			
5500692005	NO			"TAT-125-1/4-0-STK", "1324239-2"			
5500702004	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"7-1194335-4", "TAT-125-3/8-0-STK"			
5500712011	NO			"1194336-2", "TAT-125-1/2-0-STK"			
5500722008	NO			"4-1194336-1", "TAT-125-3/4-0-STK", "1406806"			
5500732014	NO			"7-1194336-1", "TAT-125-1-0-STK"			
5500742015	NO			"1194337-3", "TAT-125-1-1/2-0-STK"			
5500962003	NO			"3-1194338-0", "TAT-125-1/8-0-STK"			
5500982001	NO			"3-1194338-9", "TAT-125-3/16-0-STK"			
5501062005	NO			"7-1194339-5", "SCL-1-0-STK", "SCL-1-0-STK"			
576105P004	NO			"7-1194570-9", "ES1000-NO.2-B9-X-STK"			
6009112002	NO			"7-1194754-0", "DWP-125-3/16-0-STK"			
607381P046	NO			"5-1194804-3", "SCT-NO.2-E5-0-STK"			
6465212003	NO			"114517-01", "1448193-1", "DWP-125-1/2-0-STK", "16-0149"			
7580142002	NO			"DWP-125-3/8-0-STK", "1448852-3", "16-0150"			
829131P021	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
9346692002	NO			"2-1197242-1", "DWP-125-1-0-STK"			
E95757-000	NO			"4-1199653-3", "FL2500-NO.4-J2-0-STK"			
EH2289-000	NO			"DWFR-6/2-0-STK"			
EH2292-000	NO			"DWFR-19/6-0-STK"			
EH2296-000	NO			"DWFR-8/2-0-STK"			
EH2297-000	NO			"DWFR-12/3-0-STK"			
EH2298-000	NO			"DWFR-16/4-0-STK"			
EH2299-000	NO			"DWFR-24/6-0-STK"			
EM63332001	NO			"BATTU-12.7/6.1-A1-3-STK"			
EM63392001	NO			"BATTU-20.1/8.9-A1-3-STK"			
EM63602001	NO			"BATTU-25.4/12.7-A1-3-STK"			
EM63952001	NO			"BATTU-12.7/6.1-A1-4-STK"			
EM64322001	NO			"BATTU-20.1/8.9-A1-4-STK"			
EM64392001	NO			"BATTU-25.4/12.7-A1-4-STK"			
NB07072001	NO			"BATTU-12.7/6.1-A1-0-STK", "8-1899840-5"			
NB07092001	NO			"BATTU-12.7/6.1-A1-2-STK", "8-1899840-3"			
NB07112001	NO			"BATTU-20.1/8.9-A1-0-STK", "8-1899840-1"			
NB07132001	NO			"BATTU-20.1/8.9-A1-2-STK", "7-1899840-9"			
NB07152001	NO			"BATTU-25.4/12.7-A1-0-STK", "7-1899840-7"			
NB07172001	NO			"BATTU-25.4/12.7-A1-2-STK", "7-1899840-6"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
035377P004	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			
063725P022	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
121397P024	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
130599P006	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
2951512003	NO			"DWP-125-1/4-0-STK", "1448670-1", "16-0151"			
363884-000	NO			"1-1199654-7", "FL2500-NO.3-J1-0-STK"			
4429522003	NO			"6-1193329-8", "DWP-125-1/8-0-STK"			
5052842057	NO			"3-1193821-9", "RNF-100-3/64-BK-STK"			
5052892107	NO			"5-1193823-3", "RNF-100-1/16-BK-STK", "16-0112"			
5052942218	NO			"1-1193827-7", "RNF-100-3/32-BK-STK"			
5052992172	NO			"1-1193833-7", "RNF-100-1/8-BK-STK"			
5053042176	NO			"8-1193838-6", "RNF-100-3/16-BK-STK"			
5053092267	NO			"2-1193845-2", "RNF-100-1/4-BK-STK"			
5053142385	NO			"2-1193853-6", "RNF-100-3/8-BK-STK"			
5053192266	NO			"1-1193862-2", "RNF-100-1/2-BK-STK"			
5053242179	NO			"1-1193869-9", "RNF-100-3/4-BK-STK"			
5053292160	NO			"3-1193876-7", "RNF-100-1-BK-STK"			
5053392064	NO			"7-1193885-6", "RNF-100-2-BK-STK"			
5053442033	NO			"5-1193887-7", "RNF-100-3-BK-STK"			
5070122027	NO			"5-1193969-9", "RNF-100-2-CL-STK"			
5076682002	NO			"DWP-125-3/4-0-STK", "1448810-3"			
543633P064	NO			"5-1194264-0", "SCT-NO.1-E6-0-STK"			
5500102028	NO			"2-1194329-8", "SCL-1/8-0-STK", "SCL-1/8-0-STK"			
5500312016	NO			"8-1194332-3", "SCL-1/2-0-STK", "SCL-1/2-0-STK"			
5500692005	NO			"TAT-125-1/4-0-STK", "1324239-2"			
5500702004	NO			"7-1194335-4", "TAT-125-3/8-0-STK"			
5500712011	NO			"1194336-2", "TAT-125-1/2-0-STK"			
5500722008	NO			"4-1194336-1", "TAT-125-3/4-0-STK", "1406806"			
5500732014	NO			"7-1194336-1", "TAT-125-1-0-STK"			
5500742015	NO			"1194337-3", "TAT-125-1-1/2-0-STK"			
5500962003	NO			"3-1194338-0", "TAT-125-1/8-0-STK"			
5500982001	NO			"3-1194338-9", "TAT-125-3/16-0-STK"			
576105P004	NO			"7-1194570-9", "ES1000-NO.2-B9-X-STK"			
6009112002	NO			"7-1194754-0", "DWP-125-3/16-0-STK"			
607381P046	NO			"5-1194804-3", "SCT-NO.2-E5-0-STK"			
6465212003	NO			"114517-01", "1448193-1", "DWP-125-1/2-0-STK", "16-0149"			
7580142002	NO			"DWP-125-3/8-0-STK", "1448852-3", "16-0150"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
829131P021	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
9170152001	NO			"1-1197118-5", "DWP-125-2-0-STK"			
9346692002	NO			"2-1197242-1", "DWP-125-1-0-STK"			
E95757-000	NO			"4-1199653-3", "FL2500-NO.4-J2-0-STK"			
EH2289-000	NO			"DWFR-6/2-0-STK"			
EH2296-000	NO			"DWFR-8/2-0-STK"			
EH2297-000	NO			"DWFR-12/3-0-STK"			
EH2298-000	NO			"DWFR-16/4-0-STK"			
EH2299-000	NO			"DWFR-24/6-0-STK"			
EM63332001	NO			"BATTU-12.7/6.1-A1-3-STK"			
EM63392001	NO			"BATTU-20.1/8.9-A1-3-STK"			
EM63602001	NO			"BATTU-25.4/12.7-A1-3-STK"			
EM63952001	NO			"BATTU-12.7/6.1-A1-4-STK"			
EM64322001	NO			"BATTU-20.1/8.9-A1-4-STK"			
EM64392001	NO			"BATTU-25.4/12.7-A1-4-STK"			
NB07072001	NO			"BATTU-12.7/6.1-A1-0-STK", "8-1899840-5"			
NB07092001	NO			"BATTU-12.7/6.1-A1-2-STK", "8-1899840-3"			
NB07112001	NO			"BATTU-20.1/8.9-A1-0-STK", "8-1899840-1"			
NB07132001	NO			"BATTU-20.1/8.9-A1-2-STK", "7-1899840-9"			
NB07152001	NO			"BATTU-25.4/12.7-A1-0-STK", "7-1899840-7"			
NB07172001	NO			"BATTU-25.4/12.7-A1-2-STK", "7-1899840-6"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
035377P004	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			
085193P003	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			
193197P004	NO			"4-1191401-7", "ES1000-NO.1-C1-X-STK"			
5067592001	NO			"5-1193934-3", "TAT-125-3/4-2-STK"			
5233452001	NO			"6-1194111-2", "DWP-125-3/8-2-STK"			
537637P041	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			
5500042003	NO			"5-1194328-8", "SCL-3/8-2-STK"			
5500102028	NO			"2-1194329-8", "SCL-1/8-0-STK", "SCL-1/8-0-STK"			
5500192011	NO			"5-1194330-0", "SCL-3/8-0-STK", "SCL-3/8-0-STK"			
5500282020	NO			"6-1194331-8", "SCL-3/16-0-STK", "SCL-3/16-0-STK"			
5500312016	NO			"8-1194332-3", "SCL-1/2-0-STK", "SCL-1/2-0-STK"			
5500752003	NO			"2-1194337-2", "TAT-125-2-0-STK"			
5500762006	NO			"4-1194337-1", "TAT-125-3-0-STK"			
5501052008	NO			"1-1194339-0", "SCL-3/4-0-STK", "SCL-3/4-0-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5501092019	NO			"3-1194340-1", "SCL-1/4-0-STK", "SCL-1/4-0-STK"			
576105P004	NO			"7-1194570-9", "ES1000-NO.2-B9-X-STK"			
581913P020	NO			"1-1194610-0", "QS1500-NO 2-F6-0-STK"			
5978892002	NO			"4-1194727-5", "DWP-125-1-1/2-0-STK"			
636901P014	NO			"8-1195035-6", "QS1500-NO 3-F7-0-STK"			
774185P009	NO			"8-1196028-7", "QS1500-NO.1-F5-0-STK"			
9170152001	NO			"1-1197118-5", "DWP-125-2-0-STK"			
958133P007	NO			"1197417-6", "QS1500-NO.4-F8-0-STK"			
CB0929-000	NO			"FL2500-NO.0-I7-0-STK"			
CV37322001	NO			"RW-175-E-1-X-STK", "3-1899810-8"			
CZ0181-000	NO			"SCT-NO.5-Z4-0-STK"			
D20444-000	NO			"1-1199653-5", "FL2500-NO.1-I8-0-STK"			
E43149-000	NO			"3-1199653-6", "FL2500-NO 2-I9-0-STK"			
EH2288-000	NO			"DWFR-3/1-0-STK"			
EH2289-000	NO			"DWFR-6/2-0-STK"			
EH2290-000	NO			"DWFR-9/3-0-STK"			
EH2291-000	NO			"DWFR-12/4-0-STK"			
EH2292-000	NO			"DWFR-19/6-0-STK"			
EH2293-000	NO			"DWFR-24/8-0-STK"			
EH2294-000	NO			"DWFR-40/13-0-STK"			
EH2295-000	NO			"DWFR-4/1-0-STK"			
EH2296-000	NO			"DWFR-8/2-0-STK"			
EH2297-000	NO			"DWFR-12/3-0-STK"			
EH2298-000	NO			"DWFR-16/4-0-STK"			
EH2299-000	NO			"DWFR-24/6-0-STK"			
EH2300-000	NO			"DWFR-32/8-0-STK"			
EH2301-000	NO			"DWFR-52/13-0-STK"			
NB07092001	NO			"BATTU-12.7/6.1-A1-2-STK", "8-1899840-3"			
NB07112001	NO			"BATTU-20.1/8.9-A1-0-STK", "8-1899840-1"			
NB07132001	NO			"BATTU-20.1/8.9-A1-2-STK", "7-1899840-9"			
NB07152001	NO			"BATTU-25.4/12.7-A1-0-STK", "7-1899840-7"			
NB07172001	NO			"BATTU-25.4/12.7-A1-2-STK", "7-1899840-6"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5053342101	NO			"2-1193882-6", "RNF-100-1-1/2-BK-STK"			
829131P021	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
035377P004	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			
085193P003	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			
193197P004	NO			"4-1191401-7", "ES1000-NO.1-C1-X-STK"			
5067592001	NO			"5-1193934-3", "TAT-125-3/4-2-STK"			
5233452001	NO			"6-1194111-2", "DWP-125-3/8-2-STK"			
537637P041	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			
5500042003	NO			"5-1194328-8", "SCL-3/8-2-STK"			
5500102028	NO			"2-1194329-8", "SCL-1/8-0-STK", "SCL-1/8-0-STK"			
5500192011	NO			"5-1194330-0", "SCL-3/8-0-STK", "SCL-3/8-0-STK"			
5500282020	NO			"6-1194331-8", "SCL-3/16-0-STK", "SCL-3/16-0-STK"			
5500312016	NO			"8-1194332-3", "SCL-1/2-0-STK", "SCL-1/2-0-STK"			
5500752003	NO			"2-1194337-2", "TAT-125-2-0-STK"			
5500762006	NO			"4-1194337-1", "TAT-125-3-0-STK"			
5501052008	NO			"1-1194339-0", "SCL-3/4-0-STK", "SCL-3/4-0-STK"			
5501092019	NO			"3-1194340-1", "SCL-1/4-0-STK", "SCL-1/4-0-STK"			
576105P004	NO			"7-1194570-9", "ES1000-NO.2-B9-X-STK"			
581913P020	NO			"1-1194610-0", "QS1500-NO 2-F6-0-STK"			
5978892002	NO			"4-1194727-5", "DWP-125-1-1/2-0-STK"			
636901P014	NO			"8-1195035-6", "QS1500-NO 3-F7-0-STK"			
774185P009	NO			"8-1196028-7", "QS1500-NO.1-F5-0-STK"			
895231P008	NO			"5-1196961-1", "SCT-NO.0-E8-0-STK"			
9170152001	NO			"1-1197118-5", "DWP-125-2-0-STK"			
958133P007	NO			"1197417-6", "QS1500-NO.4-F8-0-STK"			
CB0929-000	NO			"FL2500-NO.0-I7-0-STK"			
CV37322001	NO			"RW-175-E-1-X-STK", "3-1899810-8"			
CZ0181-000	NO			"SCT-NO.5-Z4-0-STK"			
D20444-000	NO			"1-1199653-5", "FL2500-NO.1-I8-0-STK"			
E43149-000	NO			"3-1199653-6", "FL2500-NO 2-I9-0-STK"			
EH2288-000	NO			"DWFR-3/1-0-STK"			
EH2289-000	NO			"DWFR-6/2-0-STK"			
EH2290-000	NO			"DWFR-9/3-0-STK"			
EH2291-000	NO			"DWFR-12/4-0-STK"			
EH2292-000	NO			"DWFR-19/6-0-STK"			
EH2293-000	NO			"DWFR-24/8-0-STK"			
EH2294-000	NO			"DWFR-40/13-0-STK"			
EH2295-000	NO			"DWFR-4/1-0-STK"			
EH2296-000	NO			"DWFR-8/2-0-STK"			
EH2297-000	NO			"DWFR-12/3-0-STK"			
EH2298-000	NO			"DWFR-16/4-0-STK"			
EH2299-000	NO			"DWFR-24/6-0-STK"			
EH2300-000	NO			"DWFR-32/8-0-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
EH2301-000	NO			"DWFR-52/13-0-STK"			
NB07092001	NO			"BATTU-12.7/6.1-A1-2-STK", "8-1899840-3"			
NB07112001	NO			"BATTU-20.1/8.9-A1-0-STK", "8-1899840-1"			
NB07132001	NO			"BATTU-20.1/8.9-A1-2-STK", "7-1899840-9"			
NB07152001	NO			"BATTU-25.4/12.7-A1-0-STK", "7-1899840-7"			
NB07172001	NO			"BATTU-25.4/12.7-A1-2-STK", "7-1899840-6"			