


# Product Change Notification (PCN)

PCN Number	502335	Date Issued	March 23, 2017
Reason for Change	Obsolete		
Change Type Description	This is to inform you that the part(s) referenced in this notice will be made obsolete due to low demand. Please contact your Molex Sales Engineer for additional questions concerning possible replacement part(s).		
Planned Implementation Date	March 01, 2018		
Recommended Replacement Parts	Please see the attached replacement parts list .xls file.		
Last Time Buy Date for Obsolete Parts	December 01, 2017		
Last Time Ship Date for Obsolete Parts	January 03, 2018		

## Before Change

- Modifications to small grip conductor crimp (shown in gold) from existing small grip design (shown in gray)



Molex Confidential Information  
© 2016 Molex - All Rights Reserved. Unauthorized Reproduction/Distribution is Prohibited.



## After Change

### Overview

- 560023-0422, 560023-0424 will be made obsolete and replaced by 560023-0444, 560023-0445
- Product Impact
  - 560023-0444, 560023-0445 have been created to meet USCAR-21 REV 3 for 0.13mm<sup>2</sup> wire
  - Newly designed conductor crimp area
  - New crimping dimensions and crimp tooling
- Part Number Impact
  - OLD P/N's (560023-0422, 560023-0424) will be offered through December 2017
  - All orders must be moved to NEW P/N's 560023-0444, 560023-0445 by December 2017
- PPAP and samples available upon request after November 1, 2017

Molex Confidential Information  
© 2016 Molex - All Rights Reserved. Unauthorized Reproduction/Distribution is Prohibited.



## Product Change Notification (PCN)

---

You may address any technical inquiries regarding this PCN by sending E-mail to [pcn\\_coordinator@molex.com](mailto:pcn_coordinator@molex.com) or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:502335**" in the e-mail Subject line for faster response.

RELEASED

**Molex, LLC**  
2222 Wellington Court  
Lisle, IL 60532  
TEL: 630-969-4747  
[www.molex.com](http://www.molex.com)

Molex Part Number	Replacement part number:
5600230422	5600230444
5600230424	5600230445