

PRODUCT CHANGE NOTIFICATION

Product Category COPPER CONNECTORS 20220525-1

Product Group ENTERPRISE CONNECTIVITY

ISSUE DATE: 25-May-22

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Panduit is discontinuing Keystone UTP Jack Modules (KJ688TP** and KJ5E88T**). Please reference Part Numbers tab for affected part numbers and replacement parts.

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2022	5	25
Old product discontinuation date*	2022	8	23

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Compatibility Type	Replacement Part 1
KJ5E88TBL	No Replacement	NO-REPLACEMENT
KJ5E88TBU	No Replacement	NO-REPLACEMENT
KJ5E88TIW	No Replacement	NO-REPLACEMENT
KJ5E88TWH	No Replacement	NO-REPLACEMENT
KJ688TPBL	Direct	NK6TMBL
KJ688TPIW	Direct	NK6TMIW
KJ688TPAW	No Replacement	NO-REPLACEMENT
KJ688TPBU	Direct	NK6TMBU
KJ688TPEI	Direct	NK6TMEI
KJ688TPGR	Direct	NK6TMGR
KJ688TPIG	Direct	NK6TMIG
KJ688TPOR	Direct	NK6TMOR
KJ688TPRD	Direct	NK6TMRD
KJ688TPVL	No Replacement	NO-REPLACEMENT
KJ688TPWH	Direct	NK6TMWH
KJ688TPYL	Direct	NK6TMYL