

1 Products affected

Product hierarchy no.				Part no.	SBU	Product Type	Customer part no.
SBU	PG	PUG	Type				
01	002	042	0000000585	See list below	Circuit Protection	CSO Clip	



List of part numbers affected				
0751.0500	0751.0501	0751.0502	0751.0503	0751.0507
0751.0508	3-111-506	3-111-507	3-124-244	3-124-245

2 Type of change

- Change of material

3 Detailed description of change

The material of the CSO series fuse clip changes back to the original copper alloy. Fuse clips manufactured with the original material can be identified by a mark "1" or "2", instead of "B1" and "B2" for the alternative. This change has no effect on the rating and the approval of the fuse clip.

Current material	New / original material
Copper alloy	Different copper alloy, which may reduce the clip temperature by 15K
Current label	New label
	

4 Reason of change

The original copper alloy is available again. Please refer to the PCN D10-061-218

5 Release date

The change takes effect in week 51/2022 (Date code 2251 or higher on label).
Parts on stock will be used upon depletion.

6 Impact of change and recommended action

- | | |
|--|--------------------|
| <input checked="" type="checkbox"/> Form | No action required |
| <input type="checkbox"/> Fit | |
| <input checked="" type="checkbox"/> Function | No action required |
| <input type="checkbox"/> Manufacturing | |
| <input type="checkbox"/> Label | |
| <input type="checkbox"/> Packaging | |

7 Reference Documents

Kind of document	Document Title
Data Sheet	CSO

Product Change Notification					PCN CSO Change of material		
owner	creation date	release date	released by	change order	rev	page	D10-068-759
zeierjo	19.10.2022	19.10.2022	schulejo	2022915	A	1 of 1	