

PRODUCT CHANGE NOTIFICATION

Product Category COPPER PATCHCORDS 20221109-1

Product Group ENTERPRISE CONNECTIVITY

ISSUE DATE: 9-Nov-22

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

A subset of 24 AWG Cat6A LSZH patch cords are being discontinued.
 Parts remaining in this product family will be the following: 1, 3, 5, 7, 10 M in Blue and Off-White (BU and IW).

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2022	11	14
Old product discontinuation date*	2023	2	7

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Compatibility Type	Replacement Part 1	Discontinuation
			Date
UTP6AL1.5M	Compatible	UTP6AL2M	7-Feb-23
UTP6AL1.5MBU	Compatible	UTP6AL2MBU	7-Feb-23
UTP6AL4M	Compatible	UTP6AL5M	7-Feb-23
UTP6AL8M	Compatible	UTP6AL10M	7-Feb-23
UTP6AL8MBU	Compatible	UTP6AL10MBU	7-Feb-23
UTP6AL15M	No Replacement	NO-REPLACEMENT	7-Feb-23
UTP6AL20M	No Replacement	NO-REPLACEMENT	7-Feb-23
UTP6AL20MBU	No Replacement	NO-REPLACEMENT	7-Feb-23
UTP6AL30M	No Replacement	NO-REPLACEMENT	7-Feb-23