



Product Change Notification

Date Issued :	April 18, 2022	PCN Number :	511896
Reason for Change :	Obsolete		
Description of Change :	Due to critical shortage of beryllium copper, we have serious Decommits of spring fingers from our vendors / raw material shortage		
Reason for Short Notice :	Force Majeure		
Planned Implementation Date :	July 30, 2022		
Recommended replacement parts :	Please see the attached replacement parts list .xls file.		
Last Time Buy Date for Obsolete Parts :	April 30, 2022		
Last Time Ship Date for Obsolete Parts :	July 30, 2022		

After Picture

Overview

- Due to critical shortage of beryllium copper , we have serious Decommits of spring fingers from our vendors / raw material shortage
- Product Impact
 - Obsolescence with Replacement
 - See attached for Replacement Part List
 - Please refer to above for LTB and LTS Date
- Part Number Impact
 - See attached impacted part list

"After the last time ship date, Molex will no longer manufacture the products included within this notification and all related tooling will be decommissioned."

Do you feel we should clearly specify for customer owned assets?

"For assets that are customer owned, the owner has 90 days after the last time ship date to claim the tooling."

You may address inquires regarding this PCN by clicking on the below link

mailto:pcn_coordinator@molex.com?subject=PCN_Notification:511896

or contact your Local Sales Engineer.

Note: While responding, please retain " PCN Notification : **PCN Notification: 511896** " in the e-mail Subject line for faster response.

Molex, LLC

2222 Wellington Court

Lisle, IL 60532

TEL (800) 786-6539

www.molex.com

PCN No Part List

511896 [0747500044](#)
511896 [1000141250](#)
511896 [1000141340](#)
511896 [1000141341](#)
511896 [1000141346](#)
511896 [1000171343](#)
511896 [1000171344](#)
511896 [2220402574](#)
511896 [2220402588](#)
511896 [2220402598](#)
511896 [2221100607](#)
511896 [2221100609](#)
511896 [2221100743](#)
511896 [2221101241](#)
511896 [2221101242](#)
511896 [2221101243](#)
511896 [2221101244](#)
511896 [2221101247](#)
511896 [2221102392](#)
511896 [2221102595](#)
511896 [2221102659](#)
511896 [2221102707](#)
511896 [2221102709](#)
511896 [2221102710](#)
511896 [2221102747](#)
511896 [2221102750](#)
511896 [2221102791](#)
511896 [2221102848](#)
511896 [2221102889](#)
511896 [2221102891](#)
511896 [2221102923](#)
511896 [2221102957](#)
511896 [2221102963](#)
511896 [2221102965](#)
511896 [2221102988](#)
511896 [2221102994](#)
511896 [2221102998](#)
511896 [2221103041](#)
511896 [2221103047](#)
511896 [2221103049](#)
511896 [2221103053](#)
511896 [2221103057](#)
511896 [2221103059](#)
511896 [2221103061](#)
511896 [2221103063](#)

511896 [2221103073](#)
511896 [2221103079](#)
511896 [2221103083](#)
511896 [2221103095](#)
511896 [2221103141](#)
511896 [2221103145](#)
511896 [2221103147](#)
511896 [2221103153](#)
511896 [2221103221](#)
511896 [2221103330](#)
511896 [2221103331](#)
511896 [2221103332](#)
511896 [2221103340](#)
511896 [2221103466](#)
511896 [2221103467](#)
511896 [2221103490](#)
511896 [2221103491](#)
511896 [2221103492](#)
511896 [2221103493](#)
511896 [2221103497](#)

Molex Part Number	Replacement part number:
1000141250	1000143250
1000141340	1000143340
1000141341	1000143341
1000141346	1000143346
1000171343	1000173343
1000171344	1000173344
1000141348	1000143348
747500044	747503044