

IIoT Product Change Notice


The change will be applied on the ULI-344TC (BB-USOPTL4-4P). If you need more information or special support, please contact the corresponding PMs/AEs listed in the table below.


Note: The ordering process has not been changed. Customers should continue to order model number BB-USOPTL4-4P.

- Reason for the Change:** Branding and UL File Number change.
- Affected Products:** ULI-344TC (BB-USOPTL4-4P)
- Impact on Application:** No change to form, fit, or function.


Item	Impact
Impact on Mechanical Design	No
Impact on Software Compatibility	No
Impact on Environment Characteristics	No
Impact on System Certifications	Yes – UL File Number is changing from E222870 to E3278845
Physical Outlook Change	Yes
Ordering P/N Change	No
Cut-in Implement	Component Running Change

4. Description of the Change(s):

Affected Models	Current Component	New Component	Category	Outlook Difference	Reason
ULI-344TC BB-USOPTL4-4P	20BB250-10906-00	1990039375T000	Label	<p>Old name plate</p> 	Branding and UL File Number

				 <p>USB</p> <p>+</p> <p>UL LISTED</p> <p>Int. Cert. Eq. US 44W2 EZZZPTO</p> <p>See Instruction Manual for Additional Information</p> <p>Power In: 10-30VDC @ 5W Max CLASS 2 INPUT ONLY</p> <p>Power</p> <p>+</p>	
New name plate					

--	--	--	--	--	--



5. Implementation & Schedule of the Change(s):

Affected Models	ECOM Number	Estimated Effective Date	Cut-in Implement	Change Description
ULI-344TC (BB-USOPTL4-4P)	ECOM-196592	11/15/2022	Running Change	Update name plate and UL File Number

*Note: Cut-in progress depends on factory production schedule.

** Note: The ordering process has not been changed. Customers should continue to order model number BB-

Contact Windows

PM	Brian Foster / brian.foster@advantech.com
AE	N/A