

# PRODUCT DISCONTINUATION **!! CORRECTION LOD LDD in RED TYPE !!**



referring to PCN N° 2009-122-C

Transfer of assembly and final test to Infineon Technologies (Wuxi), implementation of Cu wire bonding and change to halogen-free mold compound for products assembled in lead-free package PG-SOT3x3

<b>Last order date:</b>	<del>31.07.2010</del>	<del>31.03.2011</del>	<b>31.03.2012</b>
<b>Last delivery date</b>	<del>31.01.2011</del>	<del>30.09.2011</del>	<b>30.09.2012</b>

DISCONTINUED					NEW (REPLACEMENT)			
Sales Name	Current SP number	Package	Last order date	Last delivery date	Sales Name (E substituted by H)	New SP number	Package	Comment
BAR 63-04W E6327	SP000010174	PG-SOT323-3	31.03.2012	30.09.2012	BAR 63-04W H6327	SP000742896	PG-SOT323-3	
BAR 63-05W E6327	SP000010175	PG-SOT323-3	31.03.2012	30.09.2012	BAR 63-05W H6327	SP000766086	PG-SOT323-3	
BAR 63-06W E6327	SP000010176	PG-SOT323-3	31.03.2012	30.09.2012	BAR 63-06W H6327	SP000743402	PG-SOT323-3	
BAR 64-04W E6327	SP000010180	PG-SOT323-3	31.03.2012	30.09.2012	BAR 64-04W H6327	SP000743414	PG-SOT323-3	
BAR 64-05W E6327	SP000010181	PG-SOT323-3	31.03.2012	30.09.2012	BAR 64-05W H6327	SP000734362	PG-SOT323-3	
BAR 64-05W E6433	SP000010183	PG-SOT323-3	31.03.2012	30.09.2012	BAR 64-05W H6433	SP000743442	PG-SOT323-3	
BAR 64-06W E6327	SP000010182	PG-SOT323-3	31.03.2012	30.09.2012	BAR 64-06W H6327	SP000743444	PG-SOT323-3	
BAS 125-04W E6327	SP000012255	PG-SOT323-3	31.03.2012	30.09.2012	BAS 125-04W H6327	SP000749598	PG-SOT323-3	
BAS 125-05W E6327	SP000012256	PG-SOT323-3	31.03.2012	30.09.2012	BAS 125-05W H6327	SP000749600	PG-SOT323-3	
BAS 16W E6327	SP000010214	PG-SOT323-3	31.03.2012	30.09.2012	BAS 16W H6327	SP000753166	PG-SOT323-3	
BAS 16W E6433	SP000010215	PG-SOT323-3	31.03.2012	30.09.2012	BAS 16W H6433	SP000753168	PG-SOT323-3	
BAS 40-05W E6327	SP000014595	PG-SOT323-3	31.03.2012	30.09.2012	BAS 40-05W H6327	SP000749762	PG-SOT323-3	
BAS 40-06W E6327	SP000014597	PG-SOT323-3	31.03.2012	30.09.2012	BAS 40-06W H6327	SP000749764	PG-SOT323-3	
BAS 70-04W E6327	SP000010249	PG-SOT323-3	31.03.2012	30.09.2012	BAS 70-04W H6327	SP000749820	PG-SOT323-3	
BAS 70-05W E6327	SP000010250	PG-SOT323-3	31.03.2012	30.09.2012	BAS 70-05W H6327	SP000749822	PG-SOT323-3	
BAS 70-06W E6327	SP000010251	PG-SOT323-3	31.03.2012	30.09.2012	BAS 70-06W H6327	SP000749824	PG-SOT323-3	
BAT 15-04W E6327	SP000012598	PG-SOT323-3	31.03.2012	30.09.2012	BAT 15-04W H6327	SP000743458	PG-SOT323-3	
BAT 15-05W E6327	SP000012597	PG-SOT323-3	31.03.2012	30.09.2012	BAT 15-05W H6327	SP000743460	PG-SOT323-3	
BAT 17-04W E6327	SP000012242	PG-SOT323-3	31.03.2012	30.09.2012	BAT 17-04W H6327	SP000743462	PG-SOT323-3	
BAT 17-05W E6327	SP000012243	PG-SOT323-3	31.03.2012	30.09.2012	BAT 17-05W H6327	SP000743464	PG-SOT323-3	
BAT 17-06W E6327	SP000012244	PG-SOT323-3	31.03.2012	30.09.2012	BAT 17-06W H6327	SP000743466	PG-SOT323-3	
BAT 54-04W E6327	SP000233428	PG-SOT323-3	31.03.2012	30.09.2012	BAT 54-04W H6327	SP000749830	PG-SOT323-3	
BAT 54-05W E6327	SP000233429	PG-SOT323-3	31.03.2012	30.09.2012	BAT 54-05W H6327	SP000749832	PG-SOT323-3	
BAT 54-06W E6327	SP000233430	PG-SOT323-3	31.03.2012	30.09.2012	BAT 54-06W H6327	SP000749834	PG-SOT323-3	
BAT 54W E6327	SP000233431	PG-SOT323-3	31.03.2012	30.09.2012	BAT 54W H6327	SP000786162	PG-SOT323-3	
BAT 64-04W E6327	SP000014600	PG-SOT323-3	31.03.2012	30.09.2012	BAT 64-04W H6327	SP000749838	PG-SOT323-3	
BAT 64-05W E6327	SP000014601	PG-SOT323-3	31.03.2012	30.09.2012	BAT 64-05W H6327	SP000749840	PG-SOT323-3	
BAT 64-06W E6327	SP000014602	PG-SOT323-3	31.03.2012	30.09.2012	BAT 64-06W H6327	SP000749842	PG-SOT323-3	
BAT 68-04W E6327	SP000012246	PG-SOT323-3	31.03.2012	30.09.2012	BAT 68-04W H6327	SP000743536	PG-SOT323-3	
BAT 68-06W E6327	SP000012245	PG-SOT323-3	31.03.2012	30.09.2012	BAT 68-06W H6327	SP000743538	PG-SOT323-3	

# PRODUCT DISCONTINUATION **!! CORRECTION LOD LDD in RED TYPE !!**



referring to PCN N° 2009-122-C

Transfer of assembly and final test to Infineon Technologies (Wuxi), implementation of Cu wire bonding and change to halogen-free mold compound for products assembled in lead-free package PG-SOT3x3

<b>Last order date:</b>	<del>31.07.2010</del>	<b>31.03.2011</b>	<b>31.03.2012</b>
<b>Last delivery date</b>	<del>31.01.2011</del>	<b>30.09.2011</b>	<b>30.09.2012</b>

DISCONTINUED					NEW (REPLACEMENT)			
Sales Name	Current SP number	Package	Last order date	Last delivery date	Sales Name (E substituted by H)	New SP number	Package	Comment
BAV 70W E6327	SP000014989	PG-SOT323-3	31.03.2012	30.09.2012	BAV 70W H6327	SP000754042	PG-SOT323-3	
BAV 70W E6433	SP000014990	PG-SOT323-3	31.03.2012	30.09.2012	BAV 70W H6433	SP000754044	PG-SOT323-3	
BAV 99W E6327	SP000010340	PG-SOT323-3	31.03.2011	30.09.2011	BAV 99W H6327	SP000754054	PG-SOT323-3	product won't be transferred, no replacement planed Please refer to PD N° PD_059_10
BAV 99W E6433	SP000010341	PG-SOT323-3	31.03.2011	30.09.2011	BAV 99W H6433	SP000754058	PG-SOT323-3	product won't be transferred, no replacement planed Please refer to PD N° PD_059_10
BAW 56W E6327	SP000014991	PG-SOT323-3	31.03.2011	30.09.2011	BAW 56W H6327	SP000754066	PG-SOT323-3	product won't be transferred, no replacement planed Please refer to PD N° PD_059_10
BBY 53-05W E6327	SP000012248	PG-SOT323-3	31.03.2012	30.09.2012	BBY 53-05W H6327	SP000743554	PG-SOT323-3	
BBY 57-05W E6327	SP000012457	PG-SOT323-3	31.03.2012	30.09.2012	BBY 57-05W H6327	SP000743564	PG-SOT323-3	
BBY 58-05W E6327	SP000014603	PG-SOT323-3	31.03.2012	30.09.2012	BBY 58-05W H6327	SP000743572	PG-SOT323-3	
BBY 58-06W E6327	SP000014605	PG-SOT323-3	31.03.2012	30.09.2012	BBY 58-06W H6327	SP000743574	PG-SOT323-3	
BBY 66-05W E6327	SP000012827	PG-SOT323-3	31.03.2012	30.09.2012	BBY 66-05W H6327	SP000743582	PG-SOT323-3	
BC 807-16W E6327	SP000014778	PG-SOT323-3	31.03.2011	30.09.2011	BC 807-16W H6327	SP000745926	PG-SOT323-3	product won't be transferred, no replacement planed Please refer to PD N° PD_059_10
BC 807-25W E6327	SP000014779	PG-SOT323-3	31.03.2011	30.09.2011	BC 807-25W H6327	SP000745928	PG-SOT323-3	product won't be transferred, no replacement planed Please refer to PD N° PD_059_10

# PRODUCT DISCONTINUATION **!! CORRECTION LOD LDD in RED TYPE !!**



referring to PCN N° 2009-122-C

Transfer of assembly and final test to Infineon Technologies (Wuxi), implementation of Cu wire bonding and change to halogen-free mold compound for products assembled in lead-free package PG-SOT3x3

<b>Last order date:</b>	<del>31.07.2010</del>	<b>31.03.2011</b>	<b>31.03.2012</b>
<b>Last delivery date</b>	<del>31.01.2011</del>	<b>30.09.2011</b>	<b>30.09.2012</b>

DISCONTINUED					NEW (REPLACEMENT)			
Sales Name	Current SP number	Package	Last order date	Last delivery date	Sales Name <i>(E substituted by H)</i>	New SP number	Package	Comment
BC 807-40W E6327	SP000014688	PG-SOT323-3	<b>31.03.2011</b>	<b>30.09.2011</b>	BC 807-40W H6327	SP000745930	PG-SOT323-3	product won't be transferred, no replacement planed Please refer to PD N° PD_059_10
BC 807-40W E6433	SP000014689	PG-SOT323-3	<b>31.03.2011</b>	<b>30.09.2011</b>	BC 807-40W H6433	SP000746842	PG-SOT323-3	product won't be transferred, no replacement planed Please refer to PD N° PD_059_10
BC 808-25W E6327	SP000014777	PG-SOT323-3	<b>31.03.2011</b>	<b>30.09.2011</b>	BC 808-25W H6327	SP000746844	PG-SOT323-3	product won't be transferred, no replacement planed Please refer to PD N° PD_059_10
BC 808-40W E6327	SP000010462	PG-SOT323-3	<b>31.03.2011</b>	<b>30.09.2011</b>	BC 808-40W H6327	SP000746846	PG-SOT323-3	product won't be transferred, no replacement planed Please refer to PD N° PD_059_10
BC 817K-16W E6327	SP000307664	PG-SOT323-3	31.03.2012	30.09.2012	BC 817K-16W H6327	SP000786164	PG-SOT323-3	
BC 817K-25W E6327	SP000271929	PG-SOT323-3	31.03.2012	30.09.2012	BC 817K-25W H6327	SP000746848	PG-SOT323-3	
BC 817K-25W E6433	SP000271930	PG-SOT323-3	31.03.2012	30.09.2012	BC 817K-25W H6433	SP000786166	PG-SOT323-3	
BC 817K-40W E6327	SP000271931	PG-SOT323-3	31.03.2012	30.09.2012	BC 817K-40W H6327	SP000746850	PG-SOT323-3	
BC 818K-16W E6327	SP000271932	PG-SOT323-3	31.03.2012	30.09.2012	BC 818K-1HW E6327	SP000746852	PG-SOT323-3	
BC 846BW E6327	SP000010523	PG-SOT323-3	<b>31.03.2011</b>	<b>30.09.2011</b>	BC 846BW H6327	SP000746854	PG-SOT323-3	product won't be transferred, no replacement planed Please refer to PD N° PD_059_10
BC 847BW E6327	SP000010606	PG-SOT323-3	31.03.2012	30.09.2012	BC 847BW H6327	SP000746930	PG-SOT323-3	
BC 847BW E6433	SP000010617	PG-SOT323-3	31.03.2012	30.09.2012	BC 847BW H6433	SP000746932	PG-SOT323-3	
BC 847CW B6778	SP000057017	PG-SOT323-3	31.03.2012	30.09.2012	BC 847CW H6778	SP000747286	PG-SOT323-3	
BC 847CW E6327	SP000010607	PG-SOT323-3	31.03.2012	30.09.2012	BC 847CW H6327	SP000746934	PG-SOT323-3	
BC 847CW E6433	SP000010616	PG-SOT323-3	31.03.2012	30.09.2012	BC 847CW H6433	SP000747284	PG-SOT323-3	

# PRODUCT DISCONTINUATION **!! CORRECTION LOD LDD in RED TYPE !!**



referring to PCN N° 2009-122-C

Transfer of assembly and final test to Infineon Technologies (Wuxi), implementation of Cu wire bonding and change to halogen-free mold compound for products assembled in lead-free package PG-SOT3x3

<b>Last order date:</b>	<del>31.07.2010</del>	<del>31.03.2011</del>	<b>31.03.2012</b>
<b>Last delivery date:</b>	<del>31.01.2011</del>	<del>30.09.2011</del>	<b>30.09.2012</b>

DISCONTINUED					NEW (REPLACEMENT)			
Sales Name	Current SP number	Package	Last order date	Last delivery date	Sales Name (E substituted by H)	New SP number	Package	Comment
BC 847CW E6778	SP000054062	PG-SOT323-3	31.03.2012	30.09.2012	BC 847CW H6778	SP000747286	PG-SOT323-3	
BC 848BW E6327	SP000010610	PG-SOT323-3	31.03.2012	30.09.2012	BC 848BW H6327	SP000747410	PG-SOT323-3	
BC 848CW E6327	SP000010611	PG-SOT323-3	31.03.2012	30.09.2012	BC 848CW H6327	SP000747412	PG-SOT323-3	
BC 849CW E6327	SP000010613	PG-SOT323-3	31.03.2012	30.09.2012	BC 849CW H6327	SP000747414	PG-SOT323-3	
BC 850BW E6327	SP000010614	PG-SOT323-3	31.03.2012	30.09.2012	BC 850BW H6327	SP000747416	PG-SOT323-3	
BC 850CW E6327	SP000010615	PG-SOT323-3	31.03.2012	30.09.2012	BC 850CW H6327	SP000747418	PG-SOT323-3	
BC 856BW E6327	SP000012943	PG-SOT323-3	31.03.2011	30.09.2011	BC 856BW H6327	SP000747442	PG-SOT323-3	product won't be transferred, no replacement planed Please refer to PD N° PD_059_10
BC 856BW E6433	SP000012945	PG-SOT323-3	31.03.2011	30.09.2011	BC 856BW H6433	SP000747444	PG-SOT323-3	product won't be transferred, no replacement planed Please refer to PD N° PD_059_10
BC 857BW E6327	SP000010672	PG-SOT323-3	31.03.2012	30.09.2012	BC 857BW H6327	SP000747448	PG-SOT323-3	
BC 857BW E6778	SP000455112	PG-SOT323-3	31.03.2012	30.09.2012	BC 857BW H6778	SP000747450	PG-SOT323-3	
BC 857CW E6327	SP000010673	PG-SOT323-3	31.03.2012	30.09.2012	BC 857CW H6327	SP000747452	PG-SOT323-3	
BC 857CW E6433	SP000010682	PG-SOT323-3	31.03.2012	30.09.2012	BC 857CW H6433	SP000747454	PG-SOT323-3	
BC 858BW E6327	SP000010675	PG-SOT323-3	31.03.2012	30.09.2012	BC 858BW H6327	SP000747582	PG-SOT323-3	
BC 858CW E6327	SP000010676	PG-SOT323-3	31.03.2012	30.09.2012	BC 858CW H6327	SP000747584	PG-SOT323-3	
BC 860BW E6327	SP000010680	PG-SOT323-3	31.03.2012	30.09.2012	BC 860BW H6327	SP000747586	PG-SOT323-3	
BC 860CW E6327	SP000010681	PG-SOT323-3	31.03.2012	30.09.2012	BC 860CW H6327	SP000747588	PG-SOT323-3	
BCR 108W E6327	SP000010746	PG-SOT323-3	31.03.2012	30.09.2012	BCR 108W H6327	SP000750780	PG-SOT323-3	
BCR 108W E6359	SP000010745	PG-SOT323-3	31.03.2012	30.09.2012	BCR 108W H6433	SP000757882	PG-SOT323-3	
BCR 112W E6327	SP000010748	PG-SOT323-3	31.03.2012	30.09.2012	BCR 112W H6327	SP000750790	PG-SOT323-3	
BCR 116W E6327	SP000012264	PG-SOT323-3	31.03.2012	30.09.2012	BCR 116W H6327	SP000754072	PG-SOT323-3	
BCR 119W E6327	SP000012267	PG-SOT323-3	31.03.2012	30.09.2012	BCR 119W H6327	SP000755044	PG-SOT323-3	
BCR 129W E6327	SP000014963	PG-SOT323-3	31.03.2012	30.09.2012	BCR 129W H6327	SP000755048	PG-SOT323-3	
BCR 133W E6327	SP000010764	PG-SOT323-3	31.03.2012	30.09.2012	BCR 133W H6327	SP000756246	PG-SOT323-3	
BCR 135W E6327	SP000010768	PG-SOT323-3	31.03.2012	30.09.2012	BCR 135W H6327	SP000756252	PG-SOT323-3	

# PRODUCT DISCONTINUATION !! CORRECTION LOD LDD in RED TYPE !!



referring to PCN N° 2009-122-C

Transfer of assembly and final test to Infineon Technologies (Wuxi), implementation of Cu wire bonding and change to halogen-free mold compound for products assembled in lead-free package PG-SOT3x3

<b>Last order date:</b>	<del>31.07.2010</del>	<del>31.03.2011</del>	<b>31.03.2012</b>
<b>Last delivery date</b>	<del>31.01.2011</del>	<del>30.09.2011</del>	<b>30.09.2012</b>

DISCONTINUED					NEW (REPLACEMENT)			
Sales Name	Current SP number	Package	Last order date	Last delivery date	Sales Name (E substituted by H)	New SP number	Package	Comment
BCR 141W E6327	SP000010773	PG-SOT323-3	31.03.2012	30.09.2012	BCR 141W H6327	SP000756258	PG-SOT323-3	
BCR 142W E6327	SP000012269	PG-SOT323-3	31.03.2012	30.09.2012	BCR 142W H6327	SP000756260	PG-SOT323-3	
BCR 148W E6327	SP000010783	PG-SOT323-3	31.03.2012	30.09.2012	BCR 148W H6327	SP000756268	PG-SOT323-3	
BCR 148W E6359	SP000010782	PG-SOT323-3	31.03.2012	30.09.2012	BCR 148W H6433	SP000756242	PG-SOT323-3	
BCR 158W E6327	SP000012761	PG-SOT323-3	31.03.2012	30.09.2012	BCR 158W H6327	SP000750762	PG-SOT323-3	
BCR 166W E6327	SP000012875	PG-SOT323-3	31.03.2012	30.09.2012	BCR 166W H6327	SP000750764	PG-SOT323-3	
BCR 169W E6327	SP000012271	PG-SOT323-3	31.03.2012	30.09.2012	BCR 169W H6327	SP000756844	PG-SOT323-3	
BCR 183W E6327	SP000010805	PG-SOT323-3	31.03.2012	30.09.2012	BCR 183W H6327	SP000757002	PG-SOT323-3	
BCR 185W E6327	SP000010808	PG-SOT323-3	31.03.2012	30.09.2012	BCR 185W H6327	SP000757894	PG-SOT323-3	
BCR 191W E6327	SP000012275	PG-SOT323-3	31.03.2012	30.09.2012	BCR 191W H6327	SP000757896	PG-SOT323-3	
BCR 192W E6327	SP000010816	PG-SOT323-3	31.03.2012	30.09.2012	BCR 192W H6327	SP000757898	PG-SOT323-3	
BCR 196W E6327	SP000018040	PG-SOT323-3	31.03.2012	30.09.2012	BCR 196W H6327	SP000757902	PG-SOT323-3	
BCR 198W E6327	SP000010824	PG-SOT323-3	31.03.2012	30.09.2012	BCR 198W H6327	SP000757912	PG-SOT323-3	
BF 799W E6327	SP000010975	PG-SOT323-3	31.03.2012	30.09.2012	BF 799W H6327	SP000734406	PG-SOT323-3	
BFS 17W E6327	SP000011082	PG-SOT323-3	31.03.2012	30.09.2012	BFS 17W H6327	SP000750450	PG-SOT323-3	
BFS 17W E6393	SP000067487	PG-SOT323-3	31.03.2012	30.09.2012	BFS 17W H6393	SP000750456	PG-SOT323-3	
ESD1P0RFW E6327	SP000260031	PG-SOT323-3	31.03.2012	30.09.2012	ESD1P0RFW H6327	SP000753520	PG-SOT323-3	
BC 847CW B6327	SP000056355	PG-SOT323-4	31.03.2012	30.09.2012	BC 847CW H6327	SP000746934	PG-SOT323-4	
<del>BAR 81W E6327</del>	<del>SP000040192</del>	<del>PG-SOT343-4</del>	31.03.2012	30.09.2012	<del>BAR 81W H6327</del>	<del>SP000743450</del>	<del>PG-SOT343-4</del>	referring to PCN 2009-188-A1
BAS 125-07W E6327	SP000010198	PG-SOT343-4	31.03.2012	30.09.2012	BAS 125-07W H6327	SP000749602	PG-SOT343-4	
BAS 28W E6327	SP000010230	PG-SOT343-4	31.03.2012	30.09.2012	BAS 28W H6327	SP000753170	PG-SOT343-4	
BAS 40-07W E6327	SP000010246	PG-SOT343-4	31.03.2012	30.09.2012	BAS 40-07W H6327	SP000749806	PG-SOT343-4	
BAS 70-07W E6327	SP000010270	PG-SOT343-4	31.03.2012	30.09.2012	BAS 70-07W H6327	SP000749826	PG-SOT343-4	
BAT 62-07W E6327	SP000010304	PG-SOT343-4	31.03.2012	30.09.2012	BAT 62-07W H6327	SP000743524	PG-SOT343-4	
BAT 63-07W E6327	SP000010306	PG-SOT343-4	31.03.2012	30.09.2012	BAT 63-07W H6327	SP000743534	PG-SOT343-4	
BCR 400W E6327	SP000010834	PG-SOT343-4	31.03.2012	30.09.2012	BCR 400W H6327	SP000745168	PG-SOT343-4	
BCR 401W E6327	SP000274678	PG-SOT343-4	31.03.2012	30.09.2012	BCR 401W H6327	SP000745174	PG-SOT343-4	
BCR 402W E6327	SP000274679	PG-SOT343-4	31.03.2012	30.09.2012	BCR 402W H6327	SP000745922	PG-SOT343-4	
BCR 410W E6327	SP000012946	PG-SOT343-4	31.03.2012	30.09.2012	BCR 410W H6327	SP000745924	PG-SOT343-4	
BF 2030W E6814	SP000012223	PG-SOT343-4	31.03.2012	30.09.2012	BF 2030W H6814	SP000752012	PG-SOT343-4	

# PRODUCT DISCONTINUATION **!! CORRECTION LOD LDD in RED TYPE !!**



referring to PCN N° 2009-122-C

Transfer of assembly and final test to Infineon Technologies (Wuxi), implementation of Cu wire bonding and change to halogen-free mold compound for products assembled in lead-free package PG-SOT3x3

<b>Last order date:</b>	<del>31.07.2010</del>	<del>31.03.2011</del>	<b>31.03.2012</b>
<b>Last delivery date</b>	<del>31.01.2011</del>	<del>30.09.2011</del>	<b>30.09.2012</b>

DISCONTINUED					NEW (REPLACEMENT)			
Sales Name	Current SP number	Package	Last order date	Last delivery date	Sales Name (E substituted by H)	New SP number	Package	Comment
BF 2040W E6814	SP000012226	PG-SOT343-4	31.03.2012	30.09.2012	BF 2040W H6814	SP000753484	PG-SOT343-4	
BF 5020W E6327	SP000306870	PG-SOT343-4	31.03.2012	30.09.2012	BF 5020W H6327	SP000753486	PG-SOT343-4	
BF 5030W E6327	SP000101236	PG-SOT343-4	31.03.2012	30.09.2012	BF 5030W H6327	SP000753488	PG-SOT343-4	
BAS 16S E6727	SP000253066	PG-SOT363-6	31.03.2012	30.09.2012	BAS 16S H6727	SP000753164	PG-SOT363-6	
BAS 16S E6327	SP000010200	PG-SOT363-6	31.03.2012	30.09.2012	BAS 16S H6327	SP000753162	PG-SOT363-6	
BAS 3020B E6327	SP000356309	PG-SOT363-6	31.03.2012	30.09.2012	BAS 3020B H6327	SP000749686	PG-SOT363-6	
BAS 70-04S E6327	SP000014598	PG-SOT363-6	31.03.2012	30.09.2012	BAS 70-04S H6327	SP000749814	PG-SOT363-6	
BAS 70-04S E6727	SP000387880	PG-SOT363-6	31.03.2012	30.09.2012	BAS 70-04S H6727	SP000749816	PG-SOT363-6	
BAS 70-04S E6827	SP000014599	PG-SOT363-6	31.03.2012	30.09.2012	BAS 70-04S H6827	SP000749818	PG-SOT363-6	
BAV 70S E6327	SP000010338	PG-SOT363-6	31.03.2012	30.09.2012	BAV 70S H6327	SP000753172	PG-SOT363-6	
BAV 70S E6727	SP000256268	PG-SOT363-6	31.03.2012	30.09.2012	BAV 70S H6727	SP000753176	PG-SOT363-6	
BAV 70S E6827	SP000010339	PG-SOT363-6	31.03.2012	30.09.2012	BAV 70S H6827	SP000753178	PG-SOT363-6	
BAV 99S E6327	SP000010356	PG-SOT363-6	31.03.2012	30.09.2012	BAV 99S H6327	SP000754046	PG-SOT363-6	
BAV 99S E6433	SP000010357	PG-SOT363-6	31.03.2012	30.09.2012	BAV 99S H6433	SP000754048	PG-SOT363-6	
BAV 99S E6827	SP000010358	PG-SOT363-6	31.03.2012	30.09.2012	BAV 99S H6827	SP000754052	PG-SOT363-6	
BAW 56S E6327	SP000014908	PG-SOT363-6	31.03.2012	30.09.2012	BAW 56S H6327	SP000754060	PG-SOT363-6	
BAW 56S E6727	SP000358813	PG-SOT363-6	31.03.2012	30.09.2012	BAW 56S H6727	SP000754064	PG-SOT363-6	
BC 846PN E6327	SP000010518	PG-SOT363-6	31.03.2012	30.09.2012	BC 846PN H6327	SP000746856	PG-SOT363-6	
BC 846PN E6727	SP000396286	PG-SOT363-6	31.03.2012	30.09.2012	BC 846PN H6327	SP000746856	PG-SOT363-6	
BC 846S E6327	SP000010521	PG-SOT363-6	31.03.2012	30.09.2012	BC 846S H6327	SP000746922	PG-SOT363-6	
BC 846S E6393	SP000010519	PG-SOT363-6	31.03.2012	30.09.2012	BC 846S H6393	SP000746924	PG-SOT363-6	
BC 846S E6433	SP000010522	PG-SOT363-6	31.03.2012	30.09.2012	BC 846S H6433	SP000746926	PG-SOT363-6	
BC 846S E6727	SP000010520	PG-SOT363-6	31.03.2012	30.09.2012	BC 846S H6727	SP000746928	PG-SOT363-6	
BC 847PN E6327	SP000010593	PG-SOT363-6	31.03.2012	30.09.2012	BC 847PN H6327	SP000747288	PG-SOT363-6	
BC 847PN E6433	SP000010594	PG-SOT363-6	31.03.2012	30.09.2012	BC 847PN H6433	SP000747292	PG-SOT363-6	
BC 847PN E6727	SP000010595	PG-SOT363-6	31.03.2012	30.09.2012	BC 847PN H6727	SP000747296	PG-SOT363-6	
BC 847S E6327	SP000010598	PG-SOT363-6	31.03.2012	30.09.2012	BC 847S H6327	SP000747298	PG-SOT363-6	
BC 847S E6359	SP000010600	PG-SOT363-6	31.03.2012	30.09.2012	BC 847S H6359	SP000747402	PG-SOT363-6	
BC 847S E6433	SP000010599	PG-SOT363-6	31.03.2012	30.09.2012	BC 847S H6433	SP000747404	PG-SOT363-6	
BC 847S E6727	SP000010596	PG-SOT363-6	31.03.2012	30.09.2012	BC 847S H6727	SP000747406	PG-SOT363-6	

# PRODUCT DISCONTINUATION !! CORRECTION LOD LDD in RED TYPE !!



referring to PCN N° 2009-122-C

Transfer of assembly and final test to Infineon Technologies (Wuxi), implementation of Cu wire bonding and change to halogen-free mold compound for products assembled in lead-free package PG-SOT3x3

<b>Last order date:</b>	<del>31.07.2010</del>	<del>31.03.2011</del>	<b>31.03.2012</b>
<b>Last delivery date</b>	<del>31.01.2011</del>	<del>30.09.2011</del>	<b>30.09.2012</b>

DISCONTINUED					NEW (REPLACEMENT)			
Sales Name	Current SP number	Package	Last order date	Last delivery date	Sales Name (E substituted by H)	New SP number	Package	Comment
BC 847S E6794	SP000010602	PG-SOT363-6	31.03.2012	30.09.2012	BC 847S H6794	SP000857072	PG-SOT363-6	
BC 847S E6827	SP000010597	PG-SOT363-6	31.03.2012	30.09.2012	BC 847S H6827	SP000747408	PG-SOT363-6	
BC 856S E6327	SP000012942	PG-SOT363-6	31.03.2012	30.09.2012	BC 856S H6327	SP000747446	PG-SOT363-6	
BC 857S E6327	SP000010666	PG-SOT363-6	31.03.2012	30.09.2012	BC 857S H6327	SP000747456	PG-SOT363-6	
BC 857S E6433	SP000010667	PG-SOT363-6	31.03.2012	30.09.2012	BC 857S H6433	SP000747576	PG-SOT363-6	
BC 857S E6794	SP000010669	PG-SOT363-6	31.03.2012	30.09.2012	BC 857S H6794	SP000747578	PG-SOT363-6	
BC 857S E6827	SP000010665	PG-SOT363-6	31.03.2012	30.09.2012	BC 857S H6827	SP000747580	PG-SOT363-6	
BCM 846S E6327	SP000013958	PG-SOT363-6	31.03.2012	30.09.2012	BCM 846S H6327	SP000747590	PG-SOT363-6	
BCM 856S E6327	SP000014127	PG-SOT363-6	31.03.2012	30.09.2012	BCM 856S H6327	SP000747592	PG-SOT363-6	
BCM 856S E6359	SP000014128	PG-SOT363-6	31.03.2012	30.09.2012	BCM 856S H6433	SP000747594	PG-SOT363-6	
BCM 856S E6778	SP000017446	PG-SOT363-6	31.03.2012	30.09.2012	BCM 856S H6778	SP000747596	PG-SOT363-6	
BCR 08PN E6327	SP000010727	PG-SOT363-6	31.03.2012	30.09.2012	BCR 08PN H6327	SP000750766	PG-SOT363-6	
BCR 08PN E6393	SP000010725	PG-SOT363-6	31.03.2012	30.09.2012	BCR 08PN H6393	SP000750768	PG-SOT363-6	
BCR 08PN E6433	SP000083564	PG-SOT363-6	31.03.2012	30.09.2012	BCR 08PN H6433	SP000750770	PG-SOT363-6	
BCR 08PN E6727	SP000010728	PG-SOT363-6	31.03.2012	30.09.2012	BCR 08PN H6727	SP000750772	PG-SOT363-6	
BCR 108S E6327	SP000010743	PG-SOT363-6	31.03.2012	30.09.2012	BCR 108S H6327	SP000750774	PG-SOT363-6	
BCR 108S E6393	SP000010744	PG-SOT363-6	31.03.2012	30.09.2012	BCR 108S H6393	SP000750776	PG-SOT363-6	
BCR 108S E6433	SP000010740	PG-SOT363-6	31.03.2012	30.09.2012	BCR 108S H6433	SP000750778	PG-SOT363-6	
BCR 10PN E6327	SP000010732	PG-SOT363-6	31.03.2012	30.09.2012	BCR 10PN H6327	SP000750782	PG-SOT363-6	
BCR 10PN E6393	SP000010733	PG-SOT363-6	31.03.2012	30.09.2012	BCR 10PN H6393	SP000750784	PG-SOT363-6	
BCR 10PN E6727	SP000010734	PG-SOT363-6	31.03.2012	30.09.2012	BCR 10PN H6727	SP000750786	PG-SOT363-6	
BCR 10PN E6730	SP000010730	PG-SOT363-6	31.03.2012	30.09.2012	BCR 10PN H6730	SP000750788	PG-SOT363-6	
BCR 116 S E6727	SP000679396	PG-SOT363-6	31.03.2012	30.09.2012	BCR 116 S H6727	SP000752048	PG-SOT363-6	
BCR 116S E6327	SP000012266	PG-SOT363-6	31.03.2012	30.09.2012	BCR 116S H6327	SP000752050	PG-SOT363-6	
BCR 116S E6393	SP000012265	PG-SOT363-6	31.03.2012	30.09.2012	BCR 116S H6393	SP000752052	PG-SOT363-6	
BCR 119S E6327	SP000012331	PG-SOT363-6	31.03.2012	30.09.2012	BCR 119S H6327	SP000754074	PG-SOT363-6	
BCR 119S E6393	SP000012330	PG-SOT363-6	31.03.2012	30.09.2012	BCR 119S H6393	SP000754076	PG-SOT363-6	
BCR 119S E6433	SP000012332	PG-SOT363-6	31.03.2012	30.09.2012	BCR 119S H6433	SP000755042	PG-SOT363-6	
BCR 129S E6327	SP000010755	PG-SOT363-6	31.03.2012	30.09.2012	BCR 129S H6327	SP000755046	PG-SOT363-6	
BCR 133S E6327	SP000010761	PG-SOT363-6	31.03.2012	30.09.2012	BCR 133S H6327	SP000755050	PG-SOT363-6	

# PRODUCT DISCONTINUATION !! CORRECTION LOD LDD in RED TYPE !!



referring to PCN N° 2009-122-C

Transfer of assembly and final test to Infineon Technologies (Wuxi), implementation of Cu wire bonding and change to halogen-free mold compound for products assembled in lead-free package PG-SOT3x3

<b>Last order date:</b>	<del>31.07.2010</del>	<del>31.03.2011</del>	<b>31.03.2012</b>
<b>Last delivery date:</b>	<del>31.01.2011</del>	<del>30.09.2011</del>	<b>30.09.2012</b>

DISCONTINUED					NEW (REPLACEMENT)			
Sales Name	Current SP number	Package	Last order date	Last delivery date	Sales Name (E substituted by H)	New SP number	Package	Comment
BCR 133S E6393	SP000010762	PG-SOT363-6	31.03.2012	30.09.2012	BCR 133S H6393	SP000755052	PG-SOT363-6	
BCR 133S E6433	SP000010763	PG-SOT363-6	31.03.2012	30.09.2012	BCR 133S H6433	SP000755082	PG-SOT363-6	
BCR 133S E6444	SP000054162	PG-SOT363-6	31.03.2012	30.09.2012	BCR 133S H6444	SP000756244	PG-SOT363-6	
BCR 135S E6327	SP000012335	PG-SOT363-6	31.03.2012	30.09.2012	BCR 135S H6327	SP000756248	PG-SOT363-6	
BCR 135S E6827	SP000012334	PG-SOT363-6	31.03.2012	30.09.2012	BCR 135S H6827	SP000756250	PG-SOT363-6	
BCR 141 S E6727	SP000679398	PG-SOT363-6	31.03.2012	30.09.2012	BCR 141 S H6727	SP000756254	PG-SOT363-6	
BCR 141S E6327	SP000012336	PG-SOT363-6	31.03.2012	30.09.2012	BCR 141S H6327	SP000756256	PG-SOT363-6	
BCR 148S E6327	SP000012338	PG-SOT363-6	31.03.2012	30.09.2012	BCR 148S H6327	SP000756262	PG-SOT363-6	
BCR 148S E6433	SP000012339	PG-SOT363-6	31.03.2012	30.09.2012	BCR 148S H6433	SP000756264	PG-SOT363-6	
BCR 148S E6827	SP000012337	PG-SOT363-6	31.03.2012	30.09.2012	BCR 148S H6827	SP000756266	PG-SOT363-6	
BCR 169S E6327	SP000012272	PG-SOT363-6	31.03.2012	30.09.2012	BCR 169S H6327	SP000756842	PG-SOT363-6	
BCR 183S E6327	SP000010802	PG-SOT363-6	31.03.2012	30.09.2012	BCR 183S H6327	SP000756882	PG-SOT363-6	
BCR 183S E6393	SP000010803	PG-SOT363-6	31.03.2012	30.09.2012	BCR 183S H6393	SP000756884	PG-SOT363-6	
BCR 183S E6433	SP000010804	PG-SOT363-6	31.03.2012	30.09.2012	BCR 183S H6433	SP000756886	PG-SOT363-6	
BCR 185S E6327	SP000012273	PG-SOT363-6	31.03.2012	30.09.2012	BCR 185S H6327	SP000757888	PG-SOT363-6	
BCR 185S E6393	SP000064687	PG-SOT363-6	31.03.2012	30.09.2012	BCR 185S H6393	SP000757890	PG-SOT363-6	
BCR 198S E6327	SP000010822	PG-SOT363-6	31.03.2012	30.09.2012	BCR 198S H6327	SP000757904	PG-SOT363-6	
BCR 198S E6827	SP000010821	PG-SOT363-6	31.03.2012	30.09.2012	BCR 198S H6827	SP000757908	PG-SOT363-6	
BCR 22PN E6327	SP000010826	PG-SOT363-6	31.03.2012	30.09.2012	BCR 22PN H6327	SP000757916	PG-SOT363-6	
BCR 22PN E6433	SP000010827	PG-SOT363-6	31.03.2012	30.09.2012	BCR 22PN H6433	SP000757920	PG-SOT363-6	
BCR 22PN E6727	SP000010828	PG-SOT363-6	31.03.2012	30.09.2012	BCR 22PN H6727	SP000766122	PG-SOT363-6	
BCR 35PN E6327	SP000010831	PG-SOT363-6	31.03.2012	30.09.2012	BCR 35PN H6327	SP000757922	PG-SOT363-6	
BCR 35PN E6393	SP000010829	PG-SOT363-6	31.03.2012	30.09.2012	BCR 35PN H6327	SP000757922	PG-SOT363-6	
BCR 35PN E6433	SP000010832	PG-SOT363-6	31.03.2012	30.09.2012	BCR 35PN H6433	SP000757928	PG-SOT363-6	
BCR 48PN E6327	SP000010836	PG-SOT363-6	31.03.2012	30.09.2012	BCR 48PN H6327	SP000757930	PG-SOT363-6	
BCR 48PN E6433	SP000010837	PG-SOT363-6	31.03.2012	30.09.2012	BCR 48PN H6433	SP000757932	PG-SOT363-6	
BCR 48PN E6727	SP000010838	PG-SOT363-6	31.03.2012	30.09.2012	BCR 48PN H6327	SP000757930	PG-SOT363-6	
BFS 17S E6327	SP000011081	PG-SOT363-6	31.03.2012	30.09.2012	BFS 17S H6327	SP000750448	PG-SOT363-6	
BG 3123 E6327	SP000014846	PG-SOT363-6	31.03.2012	30.09.2012	BG 3123 H6327	SP000753490	PG-SOT363-6	
BG 3123R E6327	SP000015126	PG-SOT363-6	31.03.2012	30.09.2012	BG 3123R H6327	SP000753492	PG-SOT363-6	



# PRODUCT DISCONTINUATION **!! CORRECTION LOD LDD in RED TYPE !!**



referring to PCN N° 2009-122-C

Transfer of assembly and final test to Infineon Technologies (Wuxi), implementation of Cu wire bonding and change to halogen-free mold compound for products assembled in lead-free package PG-SOT3x3

<b>Last order date:</b>	<del>31.07.2010</del>	<b>31.03.2012</b>	<del>31.03.2011</del>
<b>Last delivery date</b>	<del>31.01.2011</del>	<b>30.09.2012</b>	<del>30.09.2011</del>

DISCONTINUED					NEW (REPLACEMENT)			
Sales Name	Current SP number	Package	Last order date	Last delivery date	Sales Name (E substituted by H)	New SP number	Package	Comment
BG 3130 E6327	SP000013182	PG-SOT363-6	31.03.2012	30.09.2012	BG 3130 H6327	SP000753494	PG-SOT363-6	
BG 3130R E6327	SP000014450	PG-SOT363-6	31.03.2012	30.09.2012	BG 3130R H6327	SP000753496	PG-SOT363-6	
BG 3430R E6327	SP000240529	PG-SOT363-6	31.03.2012	30.09.2012	BG 3430R H6327	SP000753498	PG-SOT363-6	
BG 5120K E6327	SP000292148	PG-SOT363-6	31.03.2012	30.09.2012	BG 5120K H6327	SP000753500	PG-SOT363-6	
BG 5412K E6327	SP000468150	PG-SOT363-6	31.03.2012	30.09.2012	BG 5412K H6327	SP000753502	PG-SOT363-6	
ESD1P0RFS E6327	SP000260032	PG-SOT363-6	31.03.2012	30.09.2012	ESD1P0RFS H6327	SP000753518	PG-SOT363-6	
ESD5V0S4US E6327	SP000260036	PG-SOT363-6	31.03.2012	30.09.2012	ESD5V0S4US H6327	SP000753522	PG-SOT363-6	
ESD5V0S5US E6327	SP000205611	PG-SOT363-6	31.03.2012	30.09.2012	ESD5V0S5US H6327	SP000753524	PG-SOT363-6	
ESD5V3U4RRS E6327	SP000429650	PG-SOT363-6	31.03.2012	30.09.2012	ESD5V3U4RRS H6327	SP000753528	PG-SOT363-6	
SMBT 3904PN E6327	SP000014740	PG-SOT363-6	31.03.2012	30.09.2012	SMBT 3904PN H6327	SP000749584	PG-SOT363-6	
SMBT 3904S E6327	SP000014737	PG-SOT363-6	31.03.2012	30.09.2012	SMBT 3904S H6327	SP000749590	PG-SOT363-6	
SMBT 3906S E6327	SP000016694	PG-SOT363-6	31.03.2012	30.09.2012	SMBT 3906S H6327	SP000749596	PG-SOT363-6	
VS911SL-TR-H	SP000746804	PG-SOT363-6	31.03.2012	30.09.2012	VS911SL-TR-H	SP000784042	PG-SOT363-6	